FORM 'H': FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[See sub-rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/EH/2021/ SZ/ 06

Dated: 4/0/ /2021

FIRE SAFETY CERTIFICATE

Certified that the M/s Mic Drop (A Unit of Chop House Hospitality Pvt. Ltd.) located at M4, 2nd Floor, South Extension Part-2, New Delhi in a building comprised of Basement, Stilt, Ground Floor & 2 Upper Floors. The Restaurant is running at 2nd floor only owned / occupied by F Lounge (A Unit of Kea Retail P Ltd.), has already been issued Fire Safety Certificate vide Letter No. F6/DFS/MS/EH/SZ/2016/1497 dated 10/10/2016 for assembly occupancy. The premises / Building was re-inspected by the officer concerned of Fire Service on 24.12.2020 in the presence of Mr. Rakesh Mehra (Manager) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition and found that building / premises have deem complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building / premises is fit for occupancy class "Assembly" (Group – D) (Eating House) with effect from 4-/ | /2021 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued on 04/1/2021 at New Delhi.

(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER

Copy to:-

- 1. Authorized Signatory, M/s Mic Drop (A Unit of Chop House Hospitality Pvt. Ltd.) at M4, 2nd Floor, South Extension Part-2, New Delhi.
- 2. Dy. Health Officer, Central Zone, SDMC, Jal Vihar, Lajpat Nagar, New Delhi.

Conditions for the validity of Fire Safety Certificate:

- 1. Fire Safety Certificate is valid from 2nd Floor only.
- 2. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- 3. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 6. Basements shall be used strictly as per Building-By-Laws.
- 7. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on WWW.dfs.Delhigovt.nic.in.

INSPECTION REPORT

- 1. Name & address of the building: M/s Mic Drop (A Unit of Chop House Hospitality Pvt. Ltd.) at M4, 2nd Floor, South Extension Part-2, New Delhi.
- Type of Occupancy : Assembly Building, Group-D (Restaurant) 3. Type of Case
- : Renewal (Building is Basement, Stilt, Ground & 2 Upper Floors) (Restaurant at 2nd floor only)
- 4. Details of previous NOC : F6/DFS/MS/EH/SZ/2016/1497 dated 10/10/2016
- 5. Fire Safety directives Letter No.: Nil
- 6. Date of inspection : 24/12/2020 7. Name of the Inspecting Officer: A.D.O. (S.J.)
- 8. Name and designation of Officer

from the building side : Mr. Rakesh Mehra (Manager)

9. Year of Construction : 2012

S	Applicant's letter received through Minimum standards on fire	NBC / BBL	Provided					
No	prevention and fire safety U/R 33	Requirement	1	MR/NMI				
1.	Access of building			101101011				
	Gate width	N/A						
	Width of internal road		N/A	N/A				
2.			N/A	N/A				
	Number, width, Type & Arrangements of exits a. Number of staircases							
	Upper floors	2 2		MD				
	Basements	N/A		MR				
	b. Width of staircases	N/A N/A		N/A				
	Upper floors	1.50 m (each)	1 50m / 2 2 2) AAD				
	Basements	N/A	1.50m (each					
	c. Protection of exits	14/74	N/A					
	Fire check door	N/A	N/A	NI/A				
	Pressurization	N/A	N/A	N/A				
	d. No of continuous	1	2	N/A				
	staircase to terrace		2	MR				
	e. Width Of Corridor	N/A	N/A	N/A				
	f. Door Size	2m & 1.5m	2m & 1.5m	MR				
3.	Compartmentation							
	 Fire check door 	N/A	N/A	N/A				
	 Sealing of electrical shafts 	N/A	N/A	N/A				
	 Fire Rating of shaft door 	N/A	N/A	N/A				
	 Water Curtain 	N/A	N/A	N/A				
	 Fire Dampers 	N/A	N/A	N/A				
ł.	Smoke managements System							
	• Basements	N/A	N/A	N/A				
	 Upper floors 	12ACPH	Exhaust Fan	MR				
	Fire Extinguishers							
	 Total numbers 	6	6	M/R				
	• Types	ABC/CO ₂	ABC-4 & CO ₂ -2	M/R				
	ISI marking	Required	Provided	M/R				
	. Ed		, n					

		The Hose Reels		176				
		• Total numbers of each floor	n	One		One		MR
		 Length of hose re hose 	eel	30 Mtr.		30 Mtr.	M	MR
		 Nozzle diameter 		5mm		- Francis		
7	7.	Automatic fire detection	larming sys	tem	5mm		MR	
	Type of detector CO			N/A	tem	N/A		
		 Location of Main 		N/A		N/A	,	N/A
	Panel					17/4		N/A
		 Location of Repeat Panel 		N/A		N/A		N/A
	77	 Alternate source o power 	f	N/A		N/A		N/A
		 Hooters' Location 		N/A		N/A		N1/0
8.	1	MOEFA		Required				N/A
9.	F	Public Address System		N/A		Provided		MR
10	A	Automatic Sprinkler Syste	m	4.7		N,/A		N/A
		• Basements		N/A		NI/A		
		 Upper Floor 		NI/A		N/A N/A		N/A
		 Sprinkler above fals 	se	N/A		N/A		N/A
11.	T	ceiling				N/P.		N/A
11.	In	ternal Hydrants						
		 Size of riser/down- comer 	1	L00mm		100mm		MR
	 Number of hydrants 		1	1		1		
		per floor				1		MR
12.	17	Hose Box	1			1	-	MR
12.	Ya	rd Hydrants	v					VIK
		 Total number of hydrants 	N,	/A		N/A	1	V/A
		Hose Box	- DI	/ 6				,,,,
13.	Pur	nping Arrangements	N,	/A		N/A	N	I/A
•		round Level						
•		ischarge of main pump	N/	^				
> F		ead of main pump	N/			I/A	N	/A
Number of main pumps		_	DI/A				/A	
>	Jo	ckey pump out put	N/A			/A	_	/A
Jockey pump head				N1/0		1.		/A
Standby Pump out put			D1/4		11/4		'A	
Standby Pump Head			N/A N/A			14/7		
Auto Staring/Manual		N/A	11//		/ .			
stopping				11/	7	N/	A	
Pump House AccessTerrace level		N/A	/A N/A		'A	N//	A	
Discharge of			-				1	
Head of the					& 180 LPM	MR		
**		wer supply	40m		40m		MR	
A		to starting of pump		uired	Provi	- 10.000	MR	
14 =			Requ		Provid	led	MR	
14. C	apti	ve water Storage for fire f	ightir	ng		-		
_ TT 1			N/A		N/A	1	N/A	
	7	Draw of connection	N/A		NI/A			
4.5	A	Fire service inlet	N1/A		N/A		N/A	

15	Exit Signage	Required	Provided	MR			
16.	Provision of Lifts						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of lift lobby	N/A	N/A	N/A			
	Communication in lift Car	t N/A	N/A	N/A			
	Fireman's Grounding Switch	, N/A	N/A	N/A			
	➤ Lift Signage	N/A	N/A	N/A			
17.	Standby power supply	Required	Provided	MR			
18.	Refuge Area	N/A	N/A				
	> Total area	N/A	N/A	N/A			
	> Location	N/A	N/A	N/A			
19.	Fire control room						
	Detector system pane	l N/A	N/A	N/A			
	> Flow Switch Panel	N/A	N/A	N/A			
	> PA System Panel	N/A.	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20.	Special Fire Protection	N/A	N/A	N/A			
	Systems for Protection of						
	special Risks, if any;						

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. F6/DFS/MS/EH/SZ/2016/1497 dated 10/10/2016 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer

Name

: Ashok Kumar Jaiswal

Designation: A.D.O. (S.J.)

ADO(QJ)
F.T. is adoled for sign bl.