

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No.F.6/DFS/MS/School/SZ/2021/30

Dated: 13/01/2021

**FIRE SAFETY CERTIFICATE**

Certified that the Govt. Boys / Girls Sr. Sec. School, Block-ABC(SPS) Building located at Village Samalkha New Delhi-110037, comprised of Ground & Three Upper Floors only, owned / occupied by Director of Education, Govt. of NCT of Delhi, was granted Fire Safety Certificate by this department Vide letter No. F6/DFS/MS/School/2017/SZ/1155 Dated 02.08.17 The premises was re-inspected by the officer concerned of this department on 07-01-2021 in the presence of Mrs. Jayati Kapoor (HOS) and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for Occupancy "Educational" (Group-B) with effect from 13/01/2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service.

**Issued on** 13/01/2021 **at New Delhi by.**



(SUNIL CHAWDHARY)  
DY. CHIEF FIRE OFFICER (S.Z.).

Copy to :-

1. The Principal, Govt. Girls Sr. Sec. School, Samalka, New Delhi-110097.
2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Civil Lines, New Delhi-52.

**Conditions for the validity of Fire Safety Certificate:**

1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [WWW.dfs.Delhigovt.nic.in](http://WWW.dfs.Delhigovt.nic.in)
8. There shall not be more than 45 students in class rooms in any case.

## INSPECTION REPORT

1. Name & address of the building: **Govt. Boys / Girls Senior Secondary School, Block-ABC(SPS) Building located at Village Samalkha, New Delhi-110037.**
2. Type of Occupancy : **Educational Building (2 New Blocks. Ground & three upper floors. But this case is for only one block named as ABC Block.)**  
Type of Case : **Renewal**
3. Details of previous NOC : No. : **F6/DFS/MS/School/2017/SZ/1155 Dated 02.08.17**
4. Fire Safety directives Letter No. : **NBC (Part-IV)**
5. Date of inspection : **07.01.2021**
6. Name of the Inspecting Officer : **A.D.O (S.J.)**  
Name and designation of Officer from the building side : **Mrs. Jayati Kapoor (HOS)**
7. Year of Construction : **2015-2016**
8. Applicant's letter No. : **GGSSS/Sam/1821280/2020/492 dated 31.12.2020**

S No	Minimum standards on fire prevention and fire safety U/R 33	Requirements as per NBC-2005	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	9 m	15 m	MR
	• Gate width	4.5m	5m	MR
	• Width of internal road	N/A	N/A	N/A
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	4	4	MR
	• Basements	N/A	N/A	N/A
	b. Width of staircases			
	• Upper floors	1.5 m (each)	1.9m (each)	MR
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No of continuous staircase to terrace	01	Provided	M/R
	e. Width Of Corridor	1.50m	Provided	MR
	f. Door Size	1 m	Provided	MR
3.	Compartmentation			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke managements System			
	• Basements	30 a/c per hour	N/A	N/A
	• Upper floors	12 a/c per hour	Natural ventilation	MR
5.	Fire Extinguishers			
	• Total numbers	30 nos.	34 nos.	MR
	• Types	ABC/CO <sub>2</sub>	ABC & water Co2	M/R
	• IS marking	ISI marked	ISI marked	M/R

	• Total numbers on each floor	3	Provided	MR
	• Length of hose reel hose	30m	Provided	MR
	• Nozzle diameter	5mm	Provided	MR
7.	Automatic fire detection and alarming system			
	• Type of detector	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System			
	• Basements	N/A	N/A	N/A
	• Upper Floor	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	• Size of riser/down-comer	N/A	N/A	N/A
	• Number of hydrants per floor	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	• Ground Level	N/A		
	• Discharge of main pump	N/A	N/A	N/A
	➤ Head of main pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey pump out put	N/A	N/A	N/A
	➤ Jockey pump head	N/A	N/A	N/A
	➤ Standby Pump out put	N/A	N/A	N/A
	➤ Standby Pump Head	N/A	N/A	N/A
	➤ Auto Starting/Manual stopping	N/A	N/A	N/A
	➤ Pump House Access	N/A	N/A	N/A
	• Terrace level			
	➤ Discharge of pump	450LPM	450LPM x 2	MR
	➤ Head of the pump	40m	40m (each)	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw of connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	N/A	N/A	N/A

N/-29

15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	N/A	N/A	N/A
	➤ Pressurization of lift lobby	N/A	N/A	N/A
	➤ Communication in lift Car	N/A	N/A	N/A
	➤ Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area			
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire control room			
	➤ Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Battery backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A


The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. **F6/DFS/MS/School/2017/SZ/1155 Dated 02.08.17** renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

*Note : Girls school is running in morning shift and Boys school is running in evening shift for same Bldg.*

*DO(SD) on leave  
By CFO(SZ)*

*F.T. plan*

  
 Signature of the Inspecting Officer  
 Name : A.K. Jaiswal  
 Designation : A.D.O. (S.J.)

*A.D.O. (S.J.)*

*Sir, F.T. is put up for sign. pl.*

*By CFO(SZ)*

  
 11/1/2021