

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/School/2020/ NDZ/ 56 4

Dated: 17/12/2020

## FIRE SAFETY CERTIFICATE

Certified that the Nav Jiwan Adarsh Public School at C-9, Yamuna Vihar, Delhi-110053, comprised of ground floor only owned/occupied by Nav Jiwan Adarsh Public School was issued NOC vide letter No. F6/DFS/MS/2008/778 dated 17/03/08. The school building was re-inspected by the officer concerned of this department in the presence of Mr. Vijay Gaur and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with rules 33 of the Delhi Fire Service Rules, 2010 and observed that the school building is fit for occupancy class "B" 'Educational Building' with effect from 13/12/2020... for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

Issued on 17/12/2020 at New Delhi by

(Dr. S. K. Tomar)

Dy. Chief Fire Officer

To,

The Head Mistress Nav Jeevan Adarsh Public School C-9, Yamuna Vihar Delhi-110053

Copy:-

The Dy. Director of Education, B–Block, Yamuna Vihar, Delhi-110053

## **CONDITIONS**

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form `J` [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

1. Name & address of the building

: Nav Jiwan Adarsh Public School,

C-9, Yamuna Vihar, Delhi-110053

2. Building is comprised of

: Ground floor only

3. Type of Occupancy

: Educational

4. Type of Case

: Renewal

5. Details of Previous NOC letter

: F6/DFS/MS/2008/778 dated 17/03/08

6. Fire Safety directive letter No

: Circular No.-262-362 dated 17/01/2005

7. Date of Inspection

: 24/11/2020

8. Name of the Inspecting officers

: ADO Mehmood

9. Name and designation of Officer

: Mr. Vijay Gaur.

from the building side 10. Year of Construction

: 1989

11. Applicant's letter No

: Nil Dated- 19/11/2020

Sr.	Minimum Standards on fire prevention and fire safety U/R33	Circula: Requirement	Provided at Site	Remarks MR/NMR			
No.	Access to building.						
	ما المارية الم	06 mtr.	06 mtr.	MR			
	Road width	N/A	N/A	N/A			
	Gate width	N/A	N/A	N/A			
02	Width of internal road     N/A     N/A						
	a. Number of Staircases						
		N/A	N/A.	N/A			
	Upper Floor	N/A	N/A.	N/A			
	<ul><li>Basement</li><li>B. Width of Staircases</li></ul>	1473	V.				
		N/A	N/A.	N/A			
	Upper Floor     Decement	N/A	N/A	N/A			
	Basement     C. Protection of exits	1071					
	Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircases to terrace e. Width of Corridor f. Door Size	N/A	N/A.	N/A			
		N/A	N/A.	N/A			
		01 mtr.	01 mtr.	MR			
03	Compartmentation.						
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Fire rating of shaft door	N/A	N/A	N/A			
	<ul> <li>Water curtain</li> </ul>	N/A	N/A	N/A			
04	Fire Dampers     Smoke Management System.						
04		N/A	N/A	N/A			
05.	Basement	N/A	N/A	N/A			
	Upper floor     Fire Extinguishers.						
00.		02 nos.	04 nos.	MR			
	Total numbers	ABC /CO <sub>2</sub>	ABC /CO <sub>2</sub>	MR			
	• types	ISI marked	ISI marked	MR			
	IS marking	10111101110					

5	1. 11	N/A	N/A	N/A		
	Total numbers on each floor	N/A	N/A	N/A		
	Length of hose reel hose	N/A	N/A	N/A		
	Nozzle diameter		1477	,		
7	Automatic fire detection and alarming system		NI/A	N/A		
+	Type of detectors	N/A	N/A	N/A		
	Location of main panel	N/A	N/A	N/A		
	Location of repeater panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A			
	Hooter's location	N/A	N/A	N/A		
0	MOEFA	N/A	N/A	N/A		
9	Public address System.	N/A	N/A	N/A		
0	Automatic Sprinkler System.					
0		N/A	N/A	N/A		
	Basement		N/A	N/A		
	upper floor	N/A		N/A		
	sprinkler above false ceiling	N/A	N/A	14//		
1	Internal Hydrants					
07.0	i si/down comor	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	i D floor	N/A	N/A	N/A		
10	· ·					
12	Yard Hydrants.	NI/A	N/A	N/A		
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	IN/A	147.		
13	Pumping Arrangements.					
	Ground Level	N/A	N/A	N/A		
	f in Duner	N/A	N/A	N/A		
	Discharge of main Pump     Head of Main Pump	N/A	N/A	N/A		
	> Number of main pumps	N/A	N/A	N/A		
	Jockey pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	> Standby pump out put	N/A	N/A	N/A		
	> Standby pump Head	N/A	N/A	N/A		
	> Auto Starting /Manual stopping	N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace Level			2.1/4		
	Discharge of pump	N/A	N/A	N/A		
	Head of the Pump	N/A	N/A	N/A		
	> Power supply	N/A	N/A	N/A		
	> Auto Starting of pump	N/A	N/A	N/A		
14	for Fire Fighting		D. / / A	N1/A		
14	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	> Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	N/A	N/A			
15		N/A	N/A	N/A		
16						
	Pressurization of Lift Shaft	N/A	N/A	N//		
		N/A	N/A	N/A		
	Pressurization of Lift lobby     Communication in lift car	N/A	N/A	N/A		
	Communication in lift car	14//		N1/		
	Firemen's grounding switch	N/A	N/A	N/A		

218

		N/A	N/A	N/A			
17	Standby power supply	INIT					
18	Refuge Area.						
		N/A	N/A	N/A			
	Total area	N/A	N/A	N/A			
	<ul> <li>Location</li> </ul>	IN/A	14// 1				
19	Fire Control Room						
	D. L. L. system papal	N/A	N/A	N/A			
	Detector system panel	N/A	N/A	N/A			
	Flow switch panel		N/A	N/A			
	<ul> <li>PA system panel</li> </ul>	N/A	*				
	D-Hami bookup	N/A	N/A	N/A			
	Battery backup  Building Floor Plans	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection systems for protection of special Risks, if	IN/A	14//				
	any:						

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the circular No. 262-362 dated 17/01/2005 issued by Director of Education, it is recommended to renew Fire Safety Certificate.

Signature of the Inspecting Officer

Name

: Mehmood

Designation : ADO (TP)

A O. + Sum pour of for Signar Sham

James

Tom (+ 1 Man)

De (20 (A102))

De (20 (A102))

De (20 (A102))

M.S. Cell