

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. *f6/Dfs/ms/school/2021/32*

Dated: *18/01/2021*

To,

Smt. Amita Gupta (Principal),  
The Air Force School, Subroto Park,  
Delhi Cantt (Near Dhoula Kuan), New Delhi-110010.

Subject: Inspection Report in r/o The Air Force School, Subroto Park, Delhi Cantt (Near Dhoula Kuan), New Delhi-110010, from Fire Safety and means of escape point of view.

Sir,

Please refer to your letter No.-Nil outdoor diary No.9816 dated 14/12/2020 on the subject noted above, in this connection, it is to inform you that the said premises was inspected by the officer concerned of this department on 07.01.2021 in the presence of Mrs. Amita Gupta (Principal) & Sh. A.K. Singh (Section Officer) and observed that the building comprised of Ground & Two Upper Floors only. [There are Two Blocks= 1<sup>st</sup> Blk is G+1 (Admn. Block) & 2<sup>nd</sup> Blk. Is G+2 (School Block) and interconnected to each other].

Following shortcomings were observed during the time of inspection:-

1. Hose Reel not provided.
2. Down Comer not provided.
3. A Fire pump of 450 LPM not provided.
4. Over head tank of 10,000 ltr not provide.

You are requested to rectify above mentioned shortcoming under intimation to this department for further necessary action please.

Yours faithfully,

*(Signature)*  
**(ATUL GARG)**  
**DIRECTOR.**

*o/c*

Copy to:-

1. Director of Education, Old Secretariat, Civil Lines, New Delhi-110054.