

FIRE SAFETY CERTIFICATE

Certified that **Hotel Le Heritage located at 8A/3, WEA, Karol Bagh, New Delhi- 110005**, comprised of Basement (Reception & Office), Upper ground floor (Shops & 5 guest rooms), first floor (10 guest rooms), second floor (10 guest rooms) and third floor (09 guest rooms) (total 34 guest rooms) and two staff room on terrace floor, was granted FSC by this department vide letter No. F6/DFS/MS/GH/2017/SZ/1747 dated 06.12.2017. The premises was re-inspected by the officer concerned of this department on 12.01.2021 in presence of Sh. Rakesh Mittal, Owner/Occupier of the guest house and found that the owner/occupier have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential (Guest House) with effect from 20/01/2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued 20/01/2021 at New Delhi by.



(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
o/c Delhi Fire Service

Copy to:-

1. The Manager, M/s. Hotel Le Heritage, 8A/3, WEA. Karol Bagh, New Delhi- 110005.
2. The Joint C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.
3. The Municipal Health officer, NDMC, Civic centre, New Delhi- 110002.

Conditions for the Validity of Fire Safety Certificate

1. **The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.**
2. All the means of escape shall be kept free of all type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
6. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
7. All comments / directions of licensing department shall always be permitted and followed.
8. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
9. The owner / occupier shall apply for renewal of this **Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37)** along with copy of the certificate, six months prior to its expiry.
10. Basement shall be used as per BBL.
11. No temporary shed is allowed on terrace.
12. The Fire Safety Certificate is only for Guest Rooms.

1. Name & address of the building : M/s. Hotel Le Heritage, 8A/3, WEA, Karol Bagh, New Delhi- 110005.
2. Type of Occupancy : Lodging House
3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/GH/2017/SZ/1747 dated 06.12.2017
5. Fire Safety directives letter No : Nil
6. Date of inspection : 12.01.2021
7. Name of the Inspecting Officers : P.V Rathee, Asstt. Div. Officer (SRD)
8. Name and designation of officers from the building side : Mr. Rakesh Mittal, Owner
9. Year of Construction : 1999-2000
10. Applicant's letter No. : Email ID leheritagehotel@gmail.com dated 07.01.2021

The said guest house is comprised of Basement, ground plus three upper floors

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	fire safety requirements as per BBL	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	Accessible	09 mtrs	MR
	• Gate width	Required	Directly accessible	MR
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	-	-	-
	• Upper Floors	01	01	MR
	• Basements	02	02	MR
	b. Width of staircases	-	-	-
	• Upper Floors	125 cms	103 cms	MR being old case
	• Basements	200 & 125 cms	200 & 125 cms	MR
	c. Protection of exits	-	-	-
	• Fire check door	Required	Not Provided	date of compliance has been extended up to 31.03.2021
	• Pressurization	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	01	01	MR
	g. Width of Corridor	125 cms	150 cms	MR
	h. Door Size	100 cms	86 cms	MR being old case
3	Compartmentation.			
	• Fire check door	Required	Not Provided	date of compliance has been extended up to 31.03.2021
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.			
	• Basements	30 a/c per hour	Exhaust fan provided	MR
	• Upper floors	Required	Natural Ventilation	MR
5	Fire Extinguishers			
	• Total numbers	02 no's at each floors	Provided	MR
	• Types	CO ₂ , ABC, WCO ₂	Provided	MR
	• IS marking	ISI marked	Provided	MR

	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	01 30 m 5 mm	Provided Provided Provided	MR MR MR
7	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	Required Required N/A N/A N/A	Not Provided Not Provided N/A N/A N/A	date of compliance has been extended up to 31.03.2021 date of compliance has been extended up to 31.03.2021 N/A N/A N/A
8	MOEFA	Required	Provided	MR
9	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none"> Basement Upper Floor Sprinkler above false ceiling 	Required N/A N/A	Provided N/A N/A	MR N/A N/A
11	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A
12	Yard Hydrants.			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	N/A N/A	N/A N/A	N/A N/A
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	--- N/A N/A N/A N/A N/A N/A N/A N/A N/A ----- 450 LPM 30 mts Required N/A	--- N/A N/A N/A N/A N/A N/A N/A N/A N/A ----- Provided (450 LPM) Provided Provided N/A	--- N/A N/A N/A N/A N/A N/A N/A N/A N/A ----- MR MR MR N/A
14	Captive Water Storage for fire fighting.			
	<ul style="list-style-type: none"> Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 	N/A N/A N/A N/A 5,000 lts	N/A N/A N/A N/A Provided	N/A N/A N/A N/A MR being old case

15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication In lift Car	Required	Provided	MR
	• Fireman's Grounding Switch	Required	Provided	MR
	• Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection. The management of the guest house has given an undertaking not to use any occupancy above third floor. (Placed at C-67)

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety required as per Delhi Fire Service Act- 2007 under Delhi Fire Service Rules- 2010,, the NOC issued vide letter No. F6/DFS/MS/GH/2017/SZ/1747 dated 06.12.2017, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

[Handwritten Signature] 13/1/2021

P.V Rathee
Asstt. Div. Officer (SRD)

D.O (SWS)

[Handwritten Signature]
19/01/2021

Dy. CEO (S2)

F. f. please

[Handwritten Signature]