## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 29

## FIRE SAFETY CERTIFICATE

Dated: 20/01/2021

Certified that M/S Hotel A.V International located at 3636, Gali Ram Nath Patwa, Tel Mandi, Paharganj, New Delhi building is comprised of Ground + 04 Upper floors (fourth floor not in use for any purpose) was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2017/NDZ/1067 dated 19/07/17. Now, the owner has applied for Ground floor (02 guest room+ reception), 1st floor to 3rd floor (04 guest room at each floor), 4th floor not in use as per affidavit and total 14 guest rooms. The premises was reinspected by the officer concerned of this department on 12/01/21 in the presence of Mr. Lamba and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 as above 14 guest rooms only and up to three upper floor only with effect from 20 purposed and the premise in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 20/01/2021 at New Delhi by.

(Dr. S. K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

12 July 1

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi .ID No 2020122309153 dated 29.12.2020.
- 2. The Manager,

Hotel A.V International located at 3636, Gali Ram Nath Patwa, Tel Mandi, Paharganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other condition mentioned in the gazette notification dated 27.05.2019 & clarification issued dated on 25.09.2019 & 17.12.2020 latest by 31.03.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

**INSPECTION REPORT** 1. Name & address of the building Hotel A.V International located at 3636, Gali Ram Nath Patwa, Tel mandi Paharganj, New Delhi Comprises of Gr+ 4 upper floor (4th floor not in use for any purpose). 2. Type of occupancy: -Residential, Sub Division-A-1 Gr. + 03 Upper floors (total 14 Guest rooms) Ground floor (02 guest room + reception 1), 1<sup>st</sup> floor to 3<sup>rd</sup> floor (04 guest room at each floor), 4<sup>th</sup> floor ( not in use as per building plans & affidavit. 3. Type of case:-Renewal 4. Details of previous FSC:-No. F6/DFS/MS/GH/2017/NDZ/1067 dated 19/07/17. 5. Fire safety directives No.-N/A 6. Date of inspection:-12/01/21 7. Name of the inspecting officer:-Sh. Ravinder Singh (ADO/CC) Sh. Rajinder Atwal (DO (CD) 8. Name & designation of officer From the building side:-Mr. Lamba 9. Year of construction:-Old 10. Applicant's letter No:-2020122309153 dated 29.12.2020.

				Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			S a
	1) Road width	N/A	03 mtr.	MR(old case)
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arr	angement of E	xits	
	A. Number of staircases			-
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase		-	8
	1. Upper floors	1.50 mtr.	1.50 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits		2	
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	01	01	MR
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	1 mtr.	1 mtr.	MR
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A



4	C I M		6	
4.	Smoke Management System	20 A CDII	NI/A	NI/A
	1) Basements	30 ACPH	N/A	N/A
	2) Upper floors	12 a/c per hour	Natural	MR -
5.	Fire Extinguishers			
	1) Total numbers	10 Nos.	10 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr	30 mtr	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection & A			
_	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	N/A	Provided	N/A
9.	<b>Public Address System</b>	N/A	Provided	N/A
10.	<b>Automatic Sprinkler System</b>			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			51
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor			
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants		45	3 0
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level			
	a) Discharge of pump	450LPM	450 LPM	MR



12	b) Head of pump	30mtr	30mtr	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for I			
	Under ground tank     capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	Required	Provided	MR
	d) Over head tank capacity	5,000	5,000	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syst Risk, if any:	em for Protec	tion of special	MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Further, the compliance of gazette notification dated 27.05.2019 is not checked as it exempted up to 31.03.2021 as per letter of clarification dated 17.12.2020.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2017/NDZ/1067 dated 19/07/17 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval.

Signature of the inspecting officer

Signature of the Inspecting Officer

Name: - Rajinder Atwal Designation: - DO (CD)

Name: Ravinder Singh Designation: ADO (CC)

Pl. Apeak about point no. 8 19

illed ofter making correction