GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2021/ND2 31

Dated: 20 /-01 /2021

FIRE SAFETY CERTIFICATE

Certified that the **Welcome Inn Guest House located** at 4647, Shora Kothi, Pahar Ganj, New Delhi comprised of **Ground + 03 Upper floor**, **Ground floor** (**Reception + 02 guest rooms**), 1st floor (04 guest rooms), 2nd floor (04 guest rooms) and 3rd floor (02 guest room), total 12 guest rooms owned/occupied by Welcome Inn Guest House was granted FSC by this department vide letter No. **F6/DFS/MS/GH/2018/191 dated 30/01/2018**. The premises was re-inspected by the officer concerned of this department on 11/01/2021 in the presence of Sh. Varun Puri and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class **Residential**, **Sub Division-A-1 as above 12 guest rooms only** with effect from -20 (2012) for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 20/01/2021 at New Delhi by.

(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. online ID no.: 2020030803572 dated 24.12.2020 with a request to verify 02 guest rooms at third floor which were earlier proposed as personnel rooms, before issuance of the license.
- 2. The Manager, Welcome Inn Guest House at 4647, Sora Kothi, New Delhi.

Condition for the validity of fire safety certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. Any flammable material for interior decoration is strictly prohibited.

INSPECTION REPORT

1. Name & address of the building :- Welcome Inn Guest House at 4647, Sora

Kothi, New Delhi. Type of Occupancy:-

Residential, Sub Division-A-1

Ground + 03 Upper floor (12 guest rooms) Ground floor (Reception + 02 guest rooms), 1st floor (04 guest rooms), 2nd floor (04 guest rooms) and 3rd floor (02 guest room),

3. Type of case:-

2.

4. Details of previous FSC:-

No. F6/DFS/MS/GH/2018/191 dated

30/01/18.

Renewal

5. Fire safety directives No.-

6. Date of inspection:-

N/A 11/01/21

7. Name of the inspecting officer:-

Sh. Ravinder singh (ADO/CC)

8. Name & designation of officer From the building side:-

9. Year of construction:-

Sh. Varun Puri

2004

10. Applicant's letter No:-

2020030803572 dated 24/12/2020

Old Case S.No. Minimum Standards on fire Requirement Provided at Remarks Prevention and fire safety / Existing fire site MR/NMR U/R 33 safety arrangement S 1 Access to Building 1) Road width N/A 5 mtr. N/A 2) Gate width N/A N/A N/A 3)Width of internal road N/A N/A N/A Number, Width Type & Arrangement of Exits 2 A. Number of staircases 1. Upper floors 01 Nos. 01 Nos. MR 2. Basements N/A N/A N/A B. Width of staircase 1. Upper floors MR (old case) .80 mtr. 1.25 Mtr. 2. Basements N/A N/A N/A C. Protection of exits 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous 01 01 MR staircase to terrace E. Width of corridor N/A N/A N/A F. Door size 1 mtr. 1 mtr. MR 3. Compartmentation N/A 1) Fire check door N/A N/A N/A 2) Sealing of electrical shafts N/A N/A N/A N/A N/A 3) Fire rating of shaft door 4) Water curtain N/A N/A N/A 5) Fire Dampers N/A N/A N/A 4. **Smoke Management System** 30 ACPH N/A N/A 1) Basements MR Natural 2) Upper floors 12 a/c per hour



			1	
5.	Fire Extinguishers			
	1) Total numbers	08	10	MR
	2) Types	ABC & CO		
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel	rtoquilou	TTOVIACA	IVIIX
	Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection 8	IVIIX		
	1) Type of detectors(CO	Required	Provided	MR
	type) as per notification	. toquirou	Trovided	IVIIX
	27.05.2019			
	2) Location of main panel	Gr. floor	Provided	MR
	3) Location of repeater pane		N/A	N/A
	4) Alternate source of power		Provided	MR
	5) Hooter's Location	at each floo		MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System		1 Tovided	IVIIX
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling	IN/A	INA	IN/A
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor	1071	14// (
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	1.07	14//	2 2 3
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement		1 177 3	1477
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main		N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head		N/A	N/A
	f) Stand by pump output		N/A	N/A
	g) Stand by pump head		N/A	N/A
(9)	h) Auto starting/Manual		N/A	N/A
	stopping			
	2) Terrace level			
	a) Discharge of pump	450 LPM	450 LPM	MR
	b) Head of pump	-	40 mtr.	MR
	c) Power supply		Provided	MR
	d) Auto starting of pump		Provided	MR
14.	Captive Water Storage for Fire			
		3		N/A



	Tarana Maria		H125	
	a) Draw-off connection	N/A	N/A	N/A
45	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	25,00 ltr.	25,00 ltr.	MR Old case
	,	Required	Provided	MR
15.	Exit Signage. Provision of Lifts.	T to quite a		
16.		N/A	N/A	N/A
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby		N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	Provided	MR
17.	Stand by Power Supply	Required		N/A
18.	Refuge Area	N/A	N/A	1 0000000000000000000000000000000000000
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	Required	Provided	MR
	e) Building floor plan	Required	Provided	MR
20.	Special Fire Protection System for Protection of special Risk, if any:			NA .

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no. No. F6/DFS/MS/GH/2018/191 dated 30/01/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval.

Signature of the Inspecting Officer

Name: Ravinder Singh Designation: ADO (CC)

Doces 141

Il vocak apart chast de sooms box flour

1411121

7----

5