GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2021/SZ/

Dated: 21/01/2021

FIRE SAFETY CERTIFICATE

Certified that the New Deep Public School, B-Block, Sita Puri, Part-II, Dabri Dwarka Road New Delhi-110045, comprised of ground floor plus two upper floors, owned/occupied by New Deep Public School was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/2010/3281 dated 01.12.10. The School building was re-inspected by the officer concerned of this department on 13/01/2021 in the presence of Sh. Balwan Singh (Manager) and found that School building have deemed complied the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (Except three new rooms on Second floor) is fit for occupancy class "Educational" for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on $\frac{21}{01}\frac{1}{202}$ at New Delhi.

(Sunil Chawdhary) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

1

- The Chairman, New Deep Public School, B-Block, Sita Puri, Part-II, Dabri Dwarka Road New Delhi-110045
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
- 9. In case of usage of three new rooms on second floor for schooling purpose then this FSC will be null and void.

INSPECTION REPORT 1. Name & address of the building: New Deep Public School, B-Block, Sita Puri, Part-II, Dabri Dwarka Road New Delhi-110045 2. Building is comprised of ground plus two upper floors Type of Occupancy 3. Educational 4. Type of Case Renewal 5. Details of Previous NOC F.6/DFS/MS/2010/3281 dated 01.12.10 6. Fire Safety directives letter No N/A 7. Date of inspection 13/01/2021 Name of Inspecting Officer A.D.O. R.K. Yadav 9. Name and designation of officers From the building side Sh. Balwan Singh (Manager) 10. Year of Construction Before 2006 11. Applicant's letter No. Nil dated 02/12/2020 S. No. Minimum Standards on fire prevention and NBC/BBL Provided at Remarks fire safety U/R 33 Requirements site MR/NMR Access to building 1. Road width Accessible (06 M/R, being old case 4.5 mtrs. mtrs.) Directly accessible M/R Gate width 4.5 mtrs from road N/A Width of internal road N/A N/A Number, Width, Type & Arrangement of Exits 2. a. Number of staircases Upper Floors 02 No.'s 02 No.'s M/R Basements N/A N/A N/A b. Width of staircases 1.0 m (Old case) 1.0 to 1.18 & M/R Upper Floor 1.0 m N/A N/A N/A Basements c. Protection of exits Fire check door N/A N/A N/A Pressurization N/A N/A N/A d. No. of continuous staircases to Provided M/R Required terrace 2.70 m 1.5 m M/R Width of Corridor 1.0 to 1.07 m 1.0 m M/R Class Room Door Size Compartmentation 3. N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System 4. N/A N/A N/A Basements Natural ventilation M/R Required Upper floors provided Fire Extinguishers 5. 07 no's Provided MR Total numbers ABC/CO₂ type MR Types Provided IS marking Provided MR ISI marked

5.	First-Aid Hose Reels			
	Total numbers on each floor	One	Provided	MR
	 Length of hose reel hose 	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
•	Automatic fire detection and alarming system			
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A N/A	N/A N/A
	 Hooters' Location 	N/A	N/A	N/A
	MOEFA	N/A	N/A	N/A
	Public Address System	N/A	N/A	N/A
0.	Automatic Sprinkler System	14/11		1471
	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
1.	Internal Hydrants			V = a
	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
2.	Yard Hydrants			
D tel	Total number of hydrants	N/A	N/A	N/A
ė.	Hose Box	N/A	N/A	N/A
3.	Pumping Arrangements			
	Ground Level			
,	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out putJockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head			N/A
	> Auto Starting/Manual Stopping	N/A	N/A	
		N/A	N/A	N/A
A)		N/A	N/A	· N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	450 LPM	Provided	MR
	> Head of the pump	30 m	Provided	MR
	> Power Supply	Required	Provided	MR
ų.	➤ Auto Starting of pump	Required	Provided	MR
1.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	 Overhead Tank capacity 	10000 ltrs	Provided	MR

- (No Lift		
6.	Provision of Lifts.	N/A	N/A	N/A
	Pressurization of Lift Shaft Pressurization of Lift lobby	N/A	N/A	N/A
		N/A	N/A	N/A
*	Communication In lift Car Crounding Switch	N/A	N/A	N/A
	 Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A
	• Lift Signage		N/A	N/A
17.	Standby power supply	N/A		
18.	Refuge Area.	DI/A	N/A	N/A
	> Total Area	N/A	N/A	N/A
	> Location	N/A	IVA	2
19.	Fire Control Room			27/4
19.		N/A	N/A	N/A
i i	 Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		177-		N/A
	Special Fire Protection System for Protection of	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcoming communicated by this department vide letter no. F.6/DFS/MS/School/2019/SZ/4646 dated 31.07/19 have been complied. Earlier Fire safety certificate was issued by this department vide letter no. F.6/DFS/MS/2010/3281 dated 01.12.10 for 07 rooms on Ground floor, 07 rooms on First floor and 02 rooms on Second floor. Now three new rooms have been constructed on second floor which are sealed by brickwall as per the undertaking submitted by the Manager (placed at C-46).

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F.6/DFS/MS/2010/3281_dated_01.12.10_renewal under rule 37 of Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name: - R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)