## FORM 'H' FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE

NEW DELHI - 110001

No. F6/DFS/MS/2021/BNQT/WZ 58

Dated: 21 101 12021

## FIRE SAFETY CERTIFICATE

Certified that the Golden Royale Hospital Pvt. Ltd. (Banquet Hall) located at Plot No-27-C-2/3, Najafgarh Road, Industrial Area New Delhi-110015, is running on upper ground & first floor in a building comprised of basement, stilt, upper ground and two upper floors, was granted Fire Safety Certificate vide letter No. F.6/DFS/MS/BNQT/2017/WZ/900 dated 22.06.2017, owned/ occupied by Golden Royale Hospital PVT. LTD. The premises was re-inspected by the officer concerned of this department on 06.01.2021 in the presence of Mr. Parveen Kumar Rathore (Owner) and found that the management have added 2<sup>nd</sup> floor & complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and found that the said building / premises is fit for occupancy class "Assembly" Group D (for upper ground, first & second floor only) with effect from 2 1 2 2 2 1 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on 2101 2021 at New Delhi by.

Director
Delhi Fire Service

Copy to:-

1. The Manager, Golden Royale Hospital Pvt. Ltd., Plot No-27-C-2/3, Najafgarh Road, Industrial Area New Delhi-110015.

## Conditions for the Validity of Fire Safety Certificate

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 9. Kitchen demolished on terrace floor and submitted undertaking by the owner/occupier not to use. If the terrace floor is used for Kitchen or other purpose without approval / sanction, FSC shall be null & void.

THOI ECTION REPURI 1. Name & address of the building : M/s. Golden Royale Hospitality Pvt. Ltd., Plot No. 27-C-2/3, Najafgarh Road, Industrial Area, New Delhi- 110015. 2. Type of Occupancy : Assembly 3. Type of Case : Renewal / Addition of 2<sup>nd</sup> Floor 4. Details of previous NOC : F.6/DFS/MS/Bmqt/2017/WZ/900 dated 22.06.2017 (for upper ground and first floor only) 5. Fire Safety directives letter No : N/A 6. Date of inspection : 06.01.2021 7. Name of the Inspecting Officers: Sarabjeet Singh, ADO (Moti Nagar) 8. Name and designation of officers from the building side : Mr. Parveen Kumar Rathore, Owner 9. Year of Construction : 2015-16 10. Applicant's letter No. : E-mail dated 05.01.2021 The said banquet hall is running on upper ground, first and second floor only in a building comprised of basement, stilt, upper ground plus two upper floors. Minimum Standards on fire BBL /NBC Provided at site Remarks No. prevention and fire safety U/R 33 Requirement MR/NMR Access to building Road width 12 mts Provided MR Gate width 4.5 mts Directly accessible from the road MR Width of internal road N/A N/A N/A Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 02 02 MR Basements 02 02 b. Width of staircases MR Upper Floors 2.0 mts each Provided Basements MR 1.50 mts each Provided MR c. Protection of exits Fire check door Required Provided in basement Pressurization MR being old case N/A e. No. of continuous staircases to terrace N/A N/A 01 01 g. Width of Corridor MR N/A h. Door Size N/A N/A 02 x 2.0 mts Provided MR Compartmentation. Fire check door Required Provided in basement MR being old case Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System. Basements 30 a/c per hour Exhaust fan provided MR Upper floors 12 a/c per hour Natural ventilation MR Fire Extinguishers Total numbers 15 Provided MR Types CO<sub>2</sub>, ABC type

ISI marked

Provided

Dravidad

MR

1 (1)

S.

2

3

4

5

IS marking

6	First-Aid Hose Reels.			No.			
	Total numbers on each floor	02	Provided	MR			
	• Length of hose reel hose	30 m	Provided	MR			
	Nozzle diameter	5 mm	Provided	MR			
	Automatic fire detection and alarming system.						
	Type of detectors	Smoke & Heat	Provided	MR			
	Location of Main Panel	Required	Provided	MR			
	Location of Repeater Panel	Required	Provided	MR			
	Alternate source of power	Required	Provided	MR			
	Hooters' Location	Required	Provided	MR			
	MOEFA	Required	Provided	MR			
	Public Address System.	Required	Provided	MR			
0	Automatic Sprinkler System.						
	Basement	Required	Provided	MR			
	Upper Floor		Provided				
	Sprinkler above false ceiling		Provided				
1	Internal Hydrants						
	Size of riser/down-comer	100 mm	Provided	MR			
	Number of hydrants per floor	02 Nos.	Provided	MR			
	Hose Box	02 Nos.	Provided	MR			
2	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
3	Pumping Arrangements.		¥				
	Ground Level						
	Discharge of main Pump	2280 LPM	Provided	MR			
	➤ Head of Main pump	70 mts	Provided	MR			
	Number of main pumps	1	Provided	MR			
	Jockey Pump out put	180 LPM	Provided	MR			
	Jockey pump head	60 mts	Provided	MR			
	> Standby Pump out put	2280 LPM	Provided	MR			
	> Standby Pump Head	60 mts	Provided	MR			
	> Auto Starting/ Manual stopping	Required	Provided	MR			
	Pump House Access	Required	Provided	MR			
	Terrace level						
	Discharge of pump	2 x 450 LPM	Provided	MR			
	➤ Head of the pump	40 mts each	Provided	MR			
	> Power Supply	Required	Provided	MR			
	> Auto Starting of pump	Required	Provided	MR			
4	Captive Water Storage for fire fighting	ng.					
	Underground tank capacity	1,00,000 lts	Provided	MR			
	> Draw-off connection	Required	Provided	MR			
	> Fire service inlet	Required	Provided	MR			
	> Access to tank	N/A	Provided	MR			
	Overhead Tank capacity	10,000 lts	10,000 lts	MR			

		MI.	18			
16	Provision of Lifts.					
0	a a south of Bit blut	N/A	N/A	N/A		
	<ul> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul>	N/A	N/A	N/A		
		Required	Provided	MR		
		Required	Provided	MR		
		Required	Provided	MR		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel     Patter has leave	N/A	N/A	N/A		
	<ul><li>Batter backup</li><li>Building Floor Plans</li></ul>	N/A	N/A	N/A		
		N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. panel	MR		

The fire protection systems provided in the building were checked and found functional at the time of inspection.

All the shortcomings pointed out by this department vide letter No. F.6/DFS/MS/2021/15 dated 04.01.2021 have been rectified by the building management.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act-2007 & Rules- 2010.

Note: - Kitchen on terrace floor removed & the management has submitted undertaking for not to use. Photographs enclosed.

DFA is put up for approval & signature please

SARABJEET SINGH Astt. Div. Officer (Moti Nagar)

D.O (West

MADOLMIN