## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2021 / 2 3

Dated: 1 / 2 /2021

## **FIRE SAFETY CERTIFICATE**

Certified that the M/s Barshala (A Unit of Indospirit Bars Pvt. Ltd.), located at Ground floor, Plot no. 02, LSC Centre, Mukherjee Nagar, Delhi-110009 of a building comprised of Ground+ 03 upper floors owned/ occupied by M/s Barshala (A Unit of Indospirit Bars Pvt. Ltd.) have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules,2010 and verified by the officer concerned of Fire Service on 21.01.2021 in the presence of Sh. Sushant, Manager and that the building/ premise is fit for occupancy Class Assembly restaurant at ground floor only with effect from 1 2 1 for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(AtulGarg)
Director

Ph-011-23414000

Copy to:-

- M/s Barshala (A Unit of Indospirit Bars Pvt. Ltd.), at Ground floor, Plot no. 02, LSC Centre, Mukherjee Nagar, Delhi-110009.
- 2. The Dy. Health Officer, NDMC, Public Health Department City S.P.Zone, Old Hindu College, Kashmere Gate, Delhi.
- 3. Joint CP(Lic.) P.S. Defence Colony, New Delhi (Ref. Application no. 2020101507729). Conditions for the validity of Fire Safety Certificate:
  - 1 All the means of escape/entry/exit shall be kept free from any obstruction.
  - 2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
  - 3 All the staff members must know the correct method of operation of firefighting system.
  - 4 The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="http://delhi.gov.in./wps/wcm/connect/doit">http://delhi.gov.in./wps/wcm/connect/doit</a> fire/FIRE/Home/Forms.
  - 5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
  - 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, **six months** prior to its expiry".

## **INSPECTION REPORT**

Name& address of the building : M/s Barshala (A Unit of Indospirit Bars Pvt. Ltd.), at Ground floor, Plot no. 02,

LSC Centre, Mukherjee Nagar, Delhi-110009.

2. Type of Occupancy

: Assembly (Restaurant)

3. Type of Case

: New Case (Ground floor only) G+03 upper floor

4. Details of previous NOC

Fire Safety directives letter No

: Nil

6. Date of inspection

: 21.01.2021

Name of the Inspecting Officers

: ADO (RN)

8. Name and designation of officers

from the building side

: Mr. Sushant (Manager)

9. Year of Construction

: 2006

10. Applicant's letter No.

: Online portal no.2020101507729 dated 15.10.2020 & E-mail I. D. dated 07.01.2021

	Minimum Standards on fire prevention at fire safety U/R 33	nd BBL/NBC requirement	Provided at site	Remarks MR/NMR		
	Access to building					
	Road width	06m	06	MR		
	Gate width	NA	NA	NA		
	Width of internal road	NA	NA	NA		
	Number, Width, Type & Arrangement of Exits (Restaurant at GF only)					
	a. Number of staircases					
	Upper Floors	NA	NA	NA		
	Basements	NA	NA	NA		
	b. Width of staircases					
	Upper Floors	NA	NA	NA		
	Basements	NA	NA	NA		
	c. Protection of exits					
	Fire check door	NA	NA	NA		
	Pressurization	NA	NA	NA		
	d. No. of continuous staircases to terrace	NA	1m	NA		
	e. Width of Corridor	NA	NA	NA		
	f. Door Size	2m & 1.50m	2.0m & 1.50m	MR		
	Compartmentation.					
	Fire check door	Required	Provided	MR		
	<ul> <li>Sealing of electrical shafts</li> </ul>	NA	NA	NA		
	Fire Rating of shaft door	NA	NA	NA		
	Water Curtain	NA	NA	NA		
	Fire Dampers	NA	NA	NA		
	Smoke Management System.					
	Basements	30 a/c per hour	NA	NA		
	Upper floors	12 a/c per hour	NA	NA		
	Fire Extinguishers					
	Total numbers	05nos	06nos	MR		
	• Types	ABC/Co2	ABC-5	MR		
	ISI marking	Yes	Co2-1 Yes	MR		

				MD		
	Total numbers on each floor	01	01	MR		
	Length of hose reel hose	30m	30m	MR		
	Nozzle diameter	5mm	5mm	MR		
	Automatic fire detection and alarming system.					
	Type of detectors	NA	NA	NA		
	Location of Main Panel	NA	NA	NA		
	Location of Repeater Panel	NA	NA	NA /		
	Alternate source of power	NA	NA	NA		
	Hooters' Location	NA	NA	NA		
}	MOEFA	Required	Provided	MR		
)	Public Address System.	NA	NA	NA		
10	Automatic Sprinkler System.					
	Basement	NA	NA	NA		
	Upper Floor(Ground floor)	NA	NA	NA		
	Sprinkler above false ceiling			NA		
	Sprinker deeve kinds seeming	NA	NA	NA		
11	Internal Hydrants					
	Size of riser/down-comer	100mm	Provided	MR		
	Number of hydrants per floor	01	Provided	MR		
	Hose Box	01	Provided	MR		
12	Yard Hydrants.					
		27.4	NIA	NA		
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA		
13	Pumping Arrangements.					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	➤ Head of Main pump	N/A	N/A	N/A		
	> Number of main pumps	N/A	N/A	N/A		
	> Jockey Pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A N/A		
	Standby Pump out put	N/A	N/A N/A	N/A N/A		
	Standby Pump Head	N/A				
	➤ Auto Starting/ Manual stopping	N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace level	450lpm	Provided	MR		
	> Discharge of pump	4501pm 40m	Provided	' MR		
	> Head of the pump					
	> Power Supply	Required	Provided	MR		
		Required	Provided	MR		

1	Captive Water Storage for fire fighting.					
	Underground tank capacity	NA	NA	NA		
	> Draw-off connection > Fire service inlet > Access to tank • Overhead Tank capacity	NA	NA	NA		
		NA	NA	NA		
		NA	NA	NA		
		20,000 ltr	20,000 ltr.	MR		
5	Exit Signage.	Required	Provided	MR		
6	Provision of Lifts.					
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul>	N/A	N/A	N/A		
		N/A	N/A	N/A		
		NA	NA	NA		
		NA	NA	NA		
		NA	NA	NA		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA		

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no. 5173 dated 28.12.2018 have been compiled by the management.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

28/1/2/

Do (M/W)

Dy (80 1/22)

27/1702)

Signature of the Inspecting Officer
Name: - C.L. Meena

Designation:- ADO/RN

f [P]