GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2021/ W2 / 67 H / 42

Dated 27 /01/2021

FIRE SAFETY CERTIFICATE

Certified that the Globus Suite located at A-82, Gujrawala Town, Part-I, Main G.T. Karnal Road, Delhi-110009. comprised of basement, ground and three upper floors (guest house 1st 2nd & 3rd upper floor only) owned/occupied by Globus Suite have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules,2010 and verified by the officer concerned of Fire Service on 14.01.2021 in the presence of Sh. Parmeet Singh Anand and that the building/ premise is fit for occupancy Residential (Rooming & Lodging) for total 28 guest rooms (1st floor- 08 guest rooms, 2nd floor- 10 guest rooms & 3rd floor- 10 guest rooms only) with effect from 2 0 2 0 202 for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 21 2021. at New Delhi by

(AtulGarg) Director

Ph: 011-23414000

Copy to:-

1. Sh. Parmeet Singh Anand, at A-82, Gujrawala Town, Delhi-110033.

2. The Dy. Health Officer, NDMC, Public Health Department City S.P.Zone, Old Hindu College, Kashmere Gate, Delhi.

3. The Addl. Commissioner of Police/ Lic, 1st Floor, Police Station, Defence Colony, New Delhi.

Conditions for the validity of Fire Safety Certificate:

1 All the means of escape/entry/exit shall be kept free from any obstruction.

- 2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3 All the staff members must know the correct method of operation of firefighting system.
- 4 The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- 5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, **six months** prior to its expiry".

1. Name & address of the building : Globus Suites at A-82, Gujrawala Town, Part-I, G.T.K Road, Delhi-110033. : Residential B+G+03 upper floor only (guest house1st 2nd & 3rd floor only) 2. Type of Occupancy 3. Type of Case : New Case **Basement-Vacant** 4.Details of previous NOC : Nil **Ground - Vacant** 5. Fire Safety directives letter No : NBC Part IV Firs Floor- 08 Guest Rooms 6.Date of inspection : 14.01.2021 Second Floor- 10 Guest Rooms 7. Name of the Inspecting Officers : ADO (RN) Third Floor - 10 Guest Rooms 8. Name and designation of officers from the building side : Sh. Paramjeet Singh Anand 9. Year of Construction :2009 10. Date of conversion of occupancy of the establishment proposed 31.05.2019 as per online application 11. Applicant's letter No. : Nil dated: 04.01.2021 Minimum Standards on fire prevention and **UBBL/NBC** Part-Provided at site Remarks fire safety U/R 33 MR/NMR Requirement Access to building Road width 06m MR 06m Gate width 4.5m Directly Accessible MR Width of internal road NA NA NA Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 02 02 MR Basements NA NA NA b. Width of staircases Upper Floors 1.50m 1.50m each MR Basements NA NA NA c. Protection of exits Fire check door Required Provided MR Pressurization NA NA NA 02 02 d. No. of continuous staircases to terrace MR Required Provided MR e. Width of Corridor f. Door Size 01m 01m MR Compartmentation. Fire check door Required Provided MR Sealing of electrical shafts Required Provided MR Fire Rating of shaft door Required Provided MR NA NA NA Water Curtain NA NA NA Fire Dampers

2

3

4

Smoke Management System.

- 10-02-03-03	Basements	12 a/c per hour	NA	NA			
- 10	Upper floors	12 a/c per hour	Natural ventilation	MR			
5	Fire Extinguishers						
-	Total numbers	06nos	08nos	MR			
	• Types	ABC & WCo2	ABC – 8	MR			
	ISI marking	Yes	Yes	MR			
	First-Aid Hose Reels.						
	Total numbers on each floor 01 01						
	 Length of hose reel hose 	30m	30m	MR			
	Nozzle diameter	5mm	5mm	MR			
	Automatic fire detection and alarming system.	Jiiiii	Jim				
and the second							
	Type of detectors	Required (carbon monoxide)	Provided	MR			
	Location of Main Panel	Required	Provided	MR			
	Location of Repeater Panel	NA	NA	NA			
	Alternate source of power	NA	NA	NA			
	Hooters' Location	NA NA	NA NA	NA			
	MOEFA .	Required	Provided	MR			
	Public Address System.	NA	NA	NA			
0	Automatic Sprinkler System.						
	Basement	NA	NA I	NA			
		NA	NA	NA			
	Upper Floor	IVA					
	Sprinkler above false ceiling	NA	NA	NA			
	Internal Hydrants						
	Size of riser/down-comer	100mm	100mm	MR			
	Number of hydrants per floor	01	01	MR			
	Hose Box	01	01	MR			
12	Yard Hydrants.						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
13	Pumping Arrangements.						
	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	> Head of Main pump	N/A	N/A	N/A			
	Number of main pumps		N/A	N/A			
	> Jockey Pump out put	N/A					
	> Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	> Standby Pump Head	N/A	N/A	N/A			
	Auto Starting/ Manual stopping	N/A	N/A	N/A			
	> Pump House Access	N/A	N/A	N/A			
	Terrace level						
	> Discharge of pump	450lpm	450lpm	MR			
	Head of the numn	40m	40m	MR			

		N D C 1	D : 1	D :1.1	100		
		> Power Supply	Required	Provided	MR		
		> Auto Starting of pump	Required	Provided	MR		
14	Captive Water Storage for firefighting.						
	•	Underground tank capacity	NA	NA	NA		
	>	Draw-off connection	NA	NA	NA		
	>	Fire service inlet	NA	NA	NA		
	>	Access to tank	. NA	NA · · · · ·	NA		
	•	Overhead Tank capacity	10,000ltr	10,000ltr	MR		
15	Exit Sig	nage.	Required	Provided	MR		
16	Provision of Lifts. 1.no Passenger lift						
	•	Pressurization of Lift Shaft	N/A	N/A	N/A		
	•	Pressurization of Lift lobby	N/A	N/A	N/A		
	•	Communication In lift Car	Required	Provided	MR		
	•	Fireman's Grounding Switch	Required	Provided	MR		
	•/	Lift Signage	Required	Provided	MR		
17	Standby	power supply	Required	Provided	MR		
18	Refuge Area.						
	> '	Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
19	Fire Control Room						
	•	Detector System Panel	N/A	N/A	N/A		
		Flow Switch Panel	N/A	N/A	N/A		
	•	PA System Panel	N/A	N/A	N/A		
		Batter backup	N/A	N/A	N/A		
		Building Floor Plans	N/A	N/A	N/A		
20		rire Protection Systems for n of special Risks, if any:	NA	NA	NA		

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no. 1314 dated 18.12.2020 have been compiled by the management.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Date SEALING TO SS 2 OF THE STATE OF THE STA

DO(1/10)

20/1/2071

Signature of the Inspecting Officer Name: - C.L. Meena

Designation:- ADO/RN