GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

No. F6/DFS/MS/NDZ/2020/ 46

Dated: 1/2/2/

FIRE SAFETY CERTIFICATE

(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Tel: 011-23412025

Copy to:-

- 1. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi.
- 2. The Licensee, M/s Gulistan Guest House situated at 3861,Khirki Taffazzul Hussain, Jama Masjid Delhi

Condition for the validity of fire safety certificate

- 1. This clearance/FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 and any violation of clarification issued on 25.09.2019 & 17.12.2020 latest by 31.03.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

 Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained there to before occupancy of the same.

		PECTION REPORT			
1	Name & address of the building	M/s Gulistan Guest House situated at 3861,Khirk Taffazzul Hussain, Jama Masjid Delhi			
2	Building is comprised of	Ground + 04 upper floor	•	la Mar	
0		Ground floor – reception 1 st floor - 02 guest rooms 2 nd floor - 02 guest rooms 3 rd floor - 02 guest rooms 4 th floor – staff room		domitor	
3	Type of Occupancy	Residential Group A-1		* * * *	
4	Type of Case	Renewal	N all		
5	Details of Previous FSC	F6/DFS/MS/GH/2017/NDZ/1064 dated 19.07.2017			
6	Fire Safety direction letter No	Nil	22/1001 dated 19107		
	Date of Inspection	1 (The South	H N N N		
7		18.01.2021			
8	Name of the Inspecting Officers	Rajesh Kumar Shukla AD	O (SPM)		
9	Name of the designation of Officer from the building side	Mohd Tauffiq			
10	Year of Construction	1972			
11	Applicant's letter No	Online I.D. No. 20210107	709495 dated 08 01 2	021	
S.N		Requirement/ Existing	Provided at Site	Remarks	
D.11	Prevention and fire safety	fire safety	1 Tovided at Site	MR/NMF	
		F 10 10 41	7	WINTE	
12	requirements U/R 33	arrangements			
1	Access to building	* 14 1 2			
	Road width	NA	03 m	MR	
	Gate width	NA	NA	NA	
	Width of internal road	NA	NA	NA	
2	Number, Width, Type and Arran				
	A. Number of Staircases		A STATE OF THE STA		
	Upper Floor	01 no.	01 no.	MR	
	Basement	NA	NA	NA	
	B. Width of Staircases	5 2 4 4	2 %		
	Upper Floor	80 cms	86 to 88 cms	MR	
	Basement	NA	NA	NA	
	C. Protection of exits	3 S S S S S S S S S S S S S S S S S S S	8 7 - 4 4.		
	Fire check door	NA	NA	NA	
	Pressurization	NA	NA	NA '	
	D. No. of continuous staircases to	01 no.	01 no.	MR	
	terrace E. Width of Corridor	NA	NA	NA	
	2 2 2	1 m	1 m	MR	
2	G. Door size	1 m	1 III	IVIK	
3	Compartmentation	NIA	I NIA	NIA	
	Fire check door	NA NA	NA NA	NA NA	
	Sealing of electrical shafts		NA	NA NA	
	Fire rating of shaft door	NA	NA NA	NA NA	
	Water curtain	NA		NA NA	
1	Fire Dampers	NA	NA	INA	
4	Smoke Management System. Basement	30a/c per hour	NA	NA	
	Upper floor	(Required as per GN dated 27.05.2019)	Not Provided	Last date o compliance extended till 31.03.2021 vide order dated	
				vic	

5.	Fire Extinguisher					
	Total numbers	08 no.	08 no.	MR		
	types	CO ₂ & ABC	CO ₂ & ABC	MR		
	IS marking	ISI marked	ISI marked	MR		
6	First-aid-Hose Reels.			TITAL .		
	Total numbers of each floor	NA	01 no. at 1 st floor	NA		
	Length of hose reel hose	NA	30 m	NA NA		
	Nozzle diameter	NA	2	Co. 1985 100 8		
7	2		5 mm	NA		
/	Automatic fire detection and alarming					
	Type of detectors	CO detectors (required as per GN dated 27.05.2019)	Not Provided	Last date of compliance extended til 31.03.2021 vide order dated 17.12.2020		
	Location of main panel	NA	NA	NA		
	Location of repeater panel	NA	NA	NA		
	Alternate source of power Hooters	NA	NA	NA		
3	MOEFA	NA NA	NA	NA		
9			NA	NA		
	Public address System.	Required	Provided	MR		
10	Automatic Sprinkler System.	1	1 p as 1	9		
	basement	NA	NA	NA		
	upper floor	NA ·	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
11	Internal Hydrants					
200	size of riser/down-comer	NA	NA	NA		
	Number of hydrants per floor	NA	NA	NA		
	Hose Box	NA	NA	NA		
12	Yard Hydrants.					
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA		
13		INA	INA	INA		
J	Pumping Arrangements.					
	• Ground Level	NIA	NIA			
	Discharge of main Pump	NA	NA	NA		
	> Head of Main Pump	NA	NA	NA		
	> Number of main pumps	NA	NA	NA		
	> Jockey pump out put	NA	NA	NA		
	> Jockey pump head	NA	NA	NA		
	Standby pump out put	NA	NA	NA		
	> Standby pump Head	NA	NA	NA		
	 Auto Starting / Manual stopping Pump House Access 	NA NA	NA	NA		
		NA	NA	NA		
		NA	225 I DM	NIA		
	Discharge of pumpHead of the Pump	NA NA	225 LPM 40 m	NA NA		
	The state of the s					
	> Power supply	NA	Provided	NA		
	> Auto Starting of pump	NA	NA	NA		

14	Captive Water Storage for Fire Fighting.	8° .			
	Underground tank capacity	NA	NA	NA	
	Draw-off connection	NA	NA	NA	
	Fire service inlet	NA	NA	NA	
	Access to tank	NA	NA	NA	
	Overhead Tank capacity	NA	2500 ltrs	NA	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.				
- 10	Pressurization of Lift Shaft	NA	NA	NA	
	Pressurization of Lift lobby	NA	NA	NA	
	Communication in lift car	NA	NA	NA	
	Firemen's grounding switch	NA	NA a	NA	
	Lift Signage	NA	NA A A A A A A A A A A A A A A A A A A	NA	
17	Standby power supply	NA	Provided	NA	
18	Refuge Area.				
	Total area	N.A	N.A	N.A	
	Location	N.A	N.A	N.A	
19	Fire Control Room				
	Detector system panel	NA	NA	NA	
	Flow switch panel	NA	NA	NA	
	PA system panel	NA	NA	NA	
	Section Control of the Control of th	NA	NA	NA	
		NA	NA	NA	
20	Special Fire Protection systems for protect Risks, if any:	ion of special	NA	NA	

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of minimum standards of fire prevention and fire safety issued vide the Rules, the **FSC** letter measures required F6/DFS/MS/GH/2017/NDZ/1064 dated 19.07.2017 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name

Rajesh Kumar Shukla

Designation

ADO (SPM)

(CRO CMOZ)

Pl. Apeak about ground floor occuparin

- Il as there is Reception and Hall (3 Repts)