GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No. F.6/DFS/MS/GH/2021/SZ/ 53

Dated: 1.1.2/2/

FIRE SAFETY CERTIFICATE

Certified that M/s Hotel Emblem located at E-5, Kalindi Colon New Friends Colony, New Delhi-110065 comprised of Basement, Stilt, Ground + 3 Upper floors was granted FSC by this department vide letter No. F.6/DFS/MS/GH/2018/SZ/247 dated 15/02/2018. The premise was re-inspected by officer concerned of this department on 21/01/2021 in the presence of Mr. Parveen (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that premises is fit for occupancy class "Residential & Lodging Building, Group- A" with effect from for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued 1 21 at New Delhi by

(Sunil Chawdhary) Dy. Chief Fire Officer **Delhi Fire Service**

Copy to: -

- 1. M/s Hotel Emblem located at E-5, Kalindi Colon, Near New Friends Colony, New Delhi-
- 2. The Joint Commissioner of Police, Licensing Branch, 1st floor P.S. Defence Colony, New Delhi.

Conditions for the validity of Fire Safety Certificate:

1. This FSC shall stand null & void without further communication after three months from the date of issue, if the requirements as stipulated in Gazette notification no. F.5(189)/AD/LB/2016/710-725 dated 17/12/2020 is not implemented under intimation to Delhi Fire Service.

2. All the means of escape/entry/exit shall be kept from any obstruction.

3.All the fire safety arrangements provided therein shall be maintained in good working condition at all times. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4.All the staff members must know the correct method of operation of fore fighting system.

5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rule of 2010. The form is available on www.dfs.delhigovt.nic.in.

6. The certificate may not be treated in any case for the regularization (clause 2.8 & UBBL-2016) of the unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if

7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

1	Name & Address of the Building M/s Hotel Emblem, E-5, Kalindi Colony (Near New				
-1		Friends Colony), New Delhi-110065			
2	Type of Occupancy	Residential Group-A (Guest House)			
3	Building Comprised of	Basement, Stilt, Ground + 3 Upper floors.			
4	Type of Case	Renewal			
5	Details of Previous NOC	F.6/DFS/MS/GH/2018/SZ/247 dated 15/02/2018			2018
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	21/01/2021			
8	Name of the Inspecting Officers	ADO Avtar Singh			
9	Name & Designation of Officers from the building side	Mr. Parveen (Manager)			
10	Year of construction	Basement (stroage), Stilt floor (Parking), Ground floor (Rec. & 02 G/Rooms), 1 st floor (06 G/Room), 2 nd floor (06 G/Room) & 3 rd floor (06 G/Rooms) Total 20 Guest Rooms			
11	Applicant letter No.	Application no. 2021011109574 dated 15/01/2021			
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33		NOC rements	Provided at Site	Remarks MR/NMR
1	Access to Building.				
	Road width	Required		6 mtr	MR
	Gate width	-N	I/A-	Accessible form main road	-N/A-
	Width of internal road	-N	J/A-	-N/A-	-N/A-
	Number, width, type & arrangemen		17.2.2		
2	0.00	t of cares.			
		Rec	quired	02 nos	MR
	Upper floorsBasement floor		quired	02 nos	MR
		Roc	quired		
	b) Width of Staircase	1.25 m		1.25 m each	MR
	Upper floorsBasement floor		25 m	1.15-1.25 m & 1.25 m (Iron)	n MR
	c) Protection of exits		1		
	Fire check door	Red	quired	Not Provided	NMR (
	> Pressurization	-N/A		-N/A-	-N/A-
	d)No. of continuous staircase to	Required		02 nos	MR
	terrace	-N/A-		-N/A-	-N/A-
	e) Width of corridor		mtr	1.15 m (final exit)	MR
	f) Door size	1	11111	2.1.2 2.1.	
3	Compartmentation.	RA	quired	Not Provided	NMR
-	• Fire check door.		N/A-	-N/A-	-N/A-
	Sealing of electrical shafts. Fina rating of shaft door. The rating of shaft door.		N/A-	-N/A-	-N/A-
	Fire rating of shaft door. Weter curtain.		N/A-	-N/A-	-N/A-
	Water curtainFire dampers.		N/A-	-N/A-	-N/A-
4			- W		
4.		30	ACPH	Exhaust fan provided	d MR
	Basement Linear George		ACPH	-N/A-	-N/A-
	• Upper floors	12	ACITI		
5.				20 nos	MR
	Total numbers			20 1100	

	ISI Marking	ISI marked	W.CO2-10	04 ,	MR
	A CONTROL OF THE CONT		Provided		MR
6.	First Aid Hose Reels.			y .	
	 Total numbers on each floor 	01	01		MR
	 Length of hose-reel hose. 	30 m	30 m	· ·	MR
	Nozzle Diameter	5 mm	5 mm		MR
7	Automatic fire detection & alarming	system.			
	Type of detectors	Carbon monoxide	Provided		MR
	Location of Main Panel	(CO) type		8	IVIK
	• Location of Repeater Panel	-N/A-	Ground floor		-N/A-
	Alternate source of power	-N/A-	-N/A-		-N/A-
	Hooter's location	-N/A-	Provided		-N/A-
		-N/A-	Each floor		-N/A-
-8.	MOEFA	Required	Provided		MR
9.	Public Address System	Required	Provided		MR
10.	Automatic Sprinkler System				
	Basement.	Required	Provided		MR
	• Upper floors	-N/A-	-N/A-		-N/A-
	Sprinkler above false ceiling	-N/A-	-N/A-		-N/A-
11.	Internal Hydrants.				
	Size of Riser / Down-comer	Required	100 mm		MR
	Number of Hydrant per floor	One	One		MR
	Hose box.	One	One		MR
12.	Yard Hydrants.				
	 Total number of hydrants. 	-N/A-	-N/A-		-N/A-
12	Hose box.	-N/A-	-N/A-	3	-N/A-
13.	Pumping arrangements.				
	Ground Level				
	Discharge of main pump.	-N/A-	-N/A-		-N/A-
	Head of main pump.Number of main pumps.	-N/A-	-N/A-		-N/A-
	Jockey Pump output.	-N/A-	-N/A-		-N/A-
	> Jockey Pump head.	-N/A-	-N/A-		-N/A-
	Standby Pump output.	-N/A-	-N/A-		-N/A-
	Standby Pump head.	-N/A-	-N/A-		-N/A-
	> Auto Starting/Manual	-N/A-	-N/A-		-N/A-
	Stopping.	-N/A-	-N/A-		-N/A-
	Pump house access.	-N/A-	-N/A-		-N/A-
	Terrace Level		271 - 101 - 100 -		
	Discharge of pump.	900 LPM	900 & 180 LPM		MR
	Head of pump.	40 mtr	40 mtr each		MR
	Power supply.	Required	Provided		MR
	Auto starting of pump.	Required	Provided		MR
14.	Captive water storage for firefighting.				
	Underground tank capacity.	-N/A-	-N/A-		-N/A-
	> Draw-off connection.	-N/A-	-N/A-		-N/A-
	Fire Service Inlet.	-N/A-	-N/A-		-N/A-
				and the second second	the state of the s

-						
and the second second	1	Access to tank.	-N/A-		-N/A-	-N/A-
	•	Overhead tank capacity.	10,000 ltrs		10,000 ltrs	MR
15.	E	kit Signage.	Required		Provided	MR
16.	Pr	ovision of Lifts.				
		 Pressurization of lift shaft. 	-N/A-		-N/A-	-N/A-
		 Pressurization of lift lobby. 	-N/A-		-N/A-	-N/A-
		• Communication in lift car.	Required	1	Provided	MR
		• Fireman's switch.	Required		Provided	MR
		• Lift signage.	Required	1	Provided	MR
17	St	andby Power Supply	Required Provided		MR	
18.	Re	Refuge Area				
		Total area	-N/A-		-N/A-	-N/A-
90		 Location 	-N/A-		-N/A-	-N/A-
19.	Fi	Fire Control Room.				
		Detector System Panel.	-N/A-	-N/A-		-N/A-
		• Flow Switch Panel.	-N/A-	-N/A-		-N/A-
		• PA system Panel.	-N/A-	-N/A-		-N/A-
		 Battery backup 	-N/A-	-N/A-		-N/A-
		Building floor plan	-N/A-	-N/A-		-N/A-
20.	-	ecial Fire Protection System for Protection of special Risk, if any.	Required	prov	type fire extinguisher ided near rical panel	MR

The Fire protection systems provided in the premises were checked / operated at random and found functional at the time of inspection..

The condition of the Gazette notification dated 27/05/2019 on mentioned below found complied.

1.	No Kitchen	on rooftop/baseme	nt.
----	------------	-------------------	-----

2. No Storage of inflammable material on rooftop.

3. No temporary roofing over the rooftop.

4. No Inflammable material of construction in passage/corridor.

5. Gas Bank, if any

6. Carbon Monoxide type Detectors.7. Fire Doors of min. 01 hr. rating

(If number of occupants more than 10 on each floor)

MR No Kitchen Provided

MR No Storage Provided

MR Not Provided

MR Not Provided

MR No Gas Bank provided

MR Provided

NMR Not Provided

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/GH/2018/SZ/247 dated 15/02/2018, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name : Avtar Singh

25/0

Difo (34)

DE 1)

MB d