GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

No. F6/DFS/MS/GH/NDZ/2021/ 60

Dated: 2/2/21

FIRE SAFETY CERTIFICATE

Certified that the M/s Shan Guest House, situated at 753, Old Motor Market, Jama Masjid, Delhi -06, comprised of Ground + 03 upper floor: Ground floor- commercial use, 1st floor- 05 guest rooms + reception + office, 2nd floor - 06 guest rooms, 3rd floor - 06 guest rooms, total 17 guest rooms was granted FSC by this department vide letter no. F6/DFS/MS/GH/2018/NDZ/486 dated 23.03.2018. The building/premises was re-inspected by Assistant Divisional Officer (SPM) from this department on 19.01.2021 in presence of Mohd. Anzan Alam, and found that the building is now comprised of Ground plus 04 upper floor having 01 room at terrace floor the owner has submitted an affidavit dated 19.11.2019 not to use any floor above third floor for any purpose in accordance with clarification of Gazette Notification dated 27.05.2019 and its subsequent clarification dated 25.09.2019. The building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of "Group A-1 (Residential)" for total 17 guest rooms (Ground floor-commercial use, 1st floor-05 guest rooms + reception + office, 2nd floor-06 guest rooms, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued onat New Delhi by

(**Dr. S.K. Tomar**)

Dy. Chief Fire Officer

Tel: 011-23412025

Copy to:-

1. The Commissioner, North DMC, SPM Civic Center, near Kamla Market, Delhi.

ofe Bla

- 2. The Joint Commissioner of police (Licensing),

 1st Floor, Police Station Defence Colony, New Delhi for Online application I.D.2020031704002 dated
 07.01.2021
- 3. The Licensee, M/s Shan Guest House, situated at 753, Old Motor Market, Jama Masjid, Delhi -06

Condition for the validity of fire safety certificate

- 1. This clearance/FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 and any violation of clarification issued on 25.09.2019 & 17.12.2020 latest by 31.03.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry".

 Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained there to before occupancy of the same.
- 9. A room constructed at 4th floor shall be removed as the same was not in existence at the time of issue of previous Fire Safety certificate dated 23.03.2018.

		INSP	ECTION REPORT			
1	Na	me & address of the building	M/s Shaan Guest House	, situated at 753,	Old Motor	
			Market, Jama Masjid, Delhi -06			
2	Bu	ilding is comprised of	Ground + 04 upper floor			
4	Du	numg is comprised of	Ground floor - commercia	luse		
			1 st floor - 05 guest rooms +			
			2 nd floor - 06 guest rooms	reception office		
					• 1	
			3 rd floor - 06 guest rooms			
			4 th floor – 01 room			
3	Ty	pe of Occupancy	Residential Group A-1 Renewal F6/DFS/MS/GH/2018/NDZ/486 dated 23.03.2018 Nil			
4 .	Ty	pe of Case				
5	De	etails of Previous FSC				
6	Fi	re Safety direction letter No				
7	Date of Inspection		19.01.2021			
		ame of the Inspecting Officers	Rajesh Kumar Shukla ADO (SPM)			
8	1	1	Mohd. Anzan Alam			
9		ame of the designation of Officer	Mond. Anzan Alam			
		om the building side				
10	K	ear of Construction	Old.			
11	A	oplicant's letter No	Online application I.D.2020031704002 dated 07.01.2021			
S.N	lo	Minimum Standards on fire	Requirement/ Existing	Provided at Site	Remarks	
		Prevention and fire safety	fire safety		MR/NMR	
		requirements U/R 33	arrangements		•	
1		Access to building			*	
		Road width	NA	06 m (approx)	NA	
		Gate width	NA	NA	NA	
	-	Width of internal road	NA	NA	NA	
2		Number, Width, Type and Arran				
4	22	A. Number of Staircases				
			01 no.	01 no.	MR	
		Upper Floor	NA	NA	NA	
		Basement	IVA	1171	- 1	
		B. Width of Staircases	88 cms	85 cms	MR	
8		Upper Floor	NA	NA	NA	
		Basement C. Protection of exits	IVA	1171		
		Fire check door	(required as per GN dated	Not Provided	Last date of	
		Fire check door	27.05.2019)		compliance	
					extended	
		Visit			till 31.03.2021	
					vide order	
					dated	
					17.12.2020	
		Pressurization	NA	NA	NA	
		D. No. of continuous staircases to	NA	NA	NA	
		terrace	L 14 X			
		E. Width of Corridor	NA	NA	NA	
		G. Door size	1 m	1 m	MR	
2			A AAA D BE			
3		Compartmentation	NA	NA	NA	
		Fire check door	NA NA	NA	NA	
		Sealing of electrical shafts			NA	
		Fire rating of shaft door	NA	NA		
		Water curtain	NA	NA	NA	
		Fire Dampers	NA	NA	NA .	
4	· ·	Smoke Management System.		Tee	Tara	
		Basement	30a/cper hour	NA	NA	
		Upper floor	Required as per GN dated	Provided	MR	
			27.05.2019)			
			· ·			

5.	Fire Extinguisher						
	Total numbers	06 no.	08 no.	MR			
	types	CO ₂ & ABC	CO ₂ & ABC	MR			
	IS marking	ISI marked	ISI marked	MR			
6	First-aid-Hose Reels.						
2	Total numbers of each floor	01	01 no.	MR			
	Length of hose reel hose	30 m	30 m	MR			
	Nozzle diameter	5 mm	5 mm	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors	CO detectors (required as per GN dated 27.05.2019)	Not Provided	Last date of compliance extended till 31.03.2021 vide order dated 17.12.2020			
	Location of main panel	NA	NA	NA			
	Location of repeater panel	NA	NA	NA			
	Alternate source of power	NA	NA	NA			
	Hooters	NA	NA	NA NA			
8	MOEFA	NA	NA Described	MR			
9	Public address System.	Required	Provided	MIK			
10	Automatic Sprinkler System.	a a a a a a a a a a a a a a a a a a a		NIA			
	basement	NA	NA	NA			
	upper floor	NA	NA	NA			
	Sprinkler above false ceiling	NA	NA	NA			
11	Internal Hydrants		200				
	size of riser/down-comer	NA	NA	NA			
	Number of hydrants per floor	NA	NA	NA			
	Hose Box	NA	NA	NA			
12	Yard Hydrants.						
14	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
12		a se					
13	Pumping Arrangements.						
	Ground LevelDischarge of main Pump	NA	NA	NA			
0 =	Head of Main Pump	NA	NA	NA			
		NA	NA	NA			
		NA	NA	NA			
		NA	NA	NA			
	Jockey pump headStandby pump out put	NA NA	NA	NA			
	> Standby pump Head	NA	NA	NA			
	Standby pump freadAuto Starting /Manual stopping	NA ·	NA	NA			
	> Pump House Access	NA	NA	NA			
	Terrace Level	4 4 4		N N			
	> Discharge of pump	225 LPM	225 LPM	MR			
	> Head of the Pump	40 m	40 m	MR			
	> Power supply	Required	Provided	MR			
	> Auto Starting of pump	Required	Provided	MR			



14	Captive Water Storage for Fire Fighting.					
	Underground tank capacity	NA	NA	1		
	Draw-off connection	NA	NA	NA		
	Fire service inlet	NA	NA	NA		
	Access to tank	NA	NA	NA		
	Overhead Tank capacity	2,500 ltrs	2,500 ltrs	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
10	Pressurization of Lift Shaft	NA	NA	NA		
	Pressurization of Lift lobby	NA	NA	NA		
	Communication in lift car	NA	NA	NA		
	Firemen's grounding switch	NA	NA	NA		
	Lift Signage	NA	NA	NA		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
10	Total area	N.A	N.A	N.A		
	Location	N.A	N.A	N.A		
19	Fire Control Room					
	Detector system panel	NA	NA .	NA		
	Flow switch panel	NA	NA	NA		
	PA system panel	NA	NA	NA		
	Batter backup	NA	NA	NA		
	Building Floor Plans	NA	NA	NA		
20	Special Fire Protection systems for pro Risks, if any:	NA	NA			

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/GH/2018/NDZ/486 dated 23.03.2018 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name

Rajesh Kumar Shukla

Designation AD

ADO (SPM)

DO/(CD)

22/1

Pl. Apeak about I room at with bloom

The same

Dof CD) I Spoken Hed as dinated