GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 66

Dated :-- 4/2/21

FIRE SAFETY CERTIFICATE

Certified that the Corus Guest House located at B-49, Connaught Place, New Delhi comprised of Ground + Mezzanine + 02 Upper floors, Ground floor (Use for commercial purpose), Mezzanine floor (offices), 1st floor (19 guest rooms), 2nd floor (11 guest rooms), total 30 guest rooms was granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/NDZ/322 dated 27/02/18. The premises was re-inspected by the officer concerned of this department on 20/01/21 in the presence of Sh. Pradeep Jha (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 1st floor (19 guest rooms), 2nd floor (11 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 2nd floor (11 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 2nd floor (11 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 2nd floor (11 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 2nd floor (11 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 2nd floor (11 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 30 guest rooms only with effect from - 4 floor (19 guest rooms), 30 guest rooms only with e

Issued -7-12-1---at New Delhi by.

(Dr. S. K. Tomar) Dy. Chief Fire Officer Delhi Fire Service

(K John

Copy to:-

- The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID NO 2020031904185 dated 30/06/2020
- 2. The Manager,
 Corus Guest House at R-49

Corus Guest House at B-49, Connaught Place, New Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. Any flammable material for interior or any other purpose shall be strictly prohibited.

		P(12)		9		
	INS	PECTION REPO	RT			
1.	Name & address of the buildin		t House at B-49, C	'onnought		
	and the same of th	Place, New		omaugm		
2.	Type of occupancy:-			, E		
	Type of occupancy.	Residential, Sub Division-A-1 Gr. +Mezzanine + 02 Upper floors (total 30 Guest rooms				
		ourpose),				
		Mezzanine flo	oor (offices), 1st floor	(19 guest rooms),		
2	2 nd floor (11 guest rooms)					
	Type of case:-	Renewal No. F6/DFS/MS/GH/2018/NDZ/322 dated				
4.	Details of previous FSC:-	OZ/322 dated				
5.	Fire safety directives No					
6.		0 N/A 20/01/21.				
7.	Name of the inspecting officer		er Atwal (DO/CD)	&		
	1 8		er Singh (ADO/CO			
8.	Name & designation of officer	•				
	From the building side:- Sh. Pradeep Jha (Manager)					
9.	Year of construction:-					
	Applicant's letter No:-		0031904185 dated	30/06/2020		
		10 110 2020	7031701103 dated	Old Case		
.No.	Minimum Standards on fire	Requirement/	Provided at site	Remarks		
	Prevention and fire safety U/R 33	Existing fire safety	Trovided de Site	MR/NMR		
	A	arrangements				
•	Access to Building					
	1) Road width	Main Road	Main Road	MR		
	2) Gate width	N/A	N/A	N/A		
	3) Width of internal road	N/A	N/A	N/A		
2.	Number, Width Type & Arrangement of Exits					
	A. Number of staircases					
	1. Upper floors	02 Nos.	02 Nos.(01	MR(old		
			from gr. to	case)		
	e o "es		second and			
			other from gr.	2		
			to first floor			
	2. Basements	N/A	N/A	N/A		
	B. Width of staircase	14/21	10/71	N/ / X		
	1. Upper floors	1.20 mtr.	1.20 mtr.each	MR(old		
	1. Opper moors	1.20 11111.	1.20 IIII. Cacii			
	2 Pagamants	NI/A	NI/A	case)		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits	27/4	27/1	7/1		
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous	01	01	MR		
	staircase to terrace					
	E. Width of corridor	0.85 mtr.	0.85 mtr.	N/A		
	F. Door size	01 mtr.	01 mtr.	MR		
	Compartmentation					
	1) Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		

N/A

4) Water curtain
5) Fire Dampers

N/A

N/A

4/22

4.	Smoke Management System					
	1) Basements	30 ACPH	N/A	N/A		
	2) Upper floors	12 ACPH	Natural	N/A MR		
			racarar	IVIK		
5.	Fire Extinguish					
J.	Fire Extinguishers 1) Total numbers	10.37				
	2) Types	10 Nos.	10 Nos.	MR		
		ABC & CO2	ABC & CO2	MR		
6.	3) ISI marking Required First-Aid Hose Reel		Provided	MR		
0.			* *			
	1) Total number at each floor	01each at 1 st & 2 nd floor	01each at.1 st & 2 nd floor	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
_	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection & Alarming System					
	1) Type of detectors	N/A	N/A	N/A		
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System					
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A N/A		
	3) Sprinkler above false	N/A	N/A			
	ceiling	I V/A	1N/A	N/A		
11.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A	N/A		
	2) Number of hydrants per	N/A	N/A			
	floor	1 1/ /1	IN/A	N/A		
	3) Hose box	N/A	N/A	NI/A		
12.	Yard Hydrants	1 1/ 1/1	IN/A	N/A		
	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A		
3.	Pumping Arrangement		x 11 2 k	1 1/ / 1		
	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A	N/A		
	pump	IVA	IN/A	IN/A		
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main pump	N/A	N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A N/A	N/A	N/A		
		N/A N/A				
	g) Stand by pump head		N/A	N/A		
	h) Auto starting/Manual stopping	N/A	N/A	N/A		
	2) Terrace level		*	,		

	a) Discharge of pump	450 & 180	450 & 180 LPM	MR		
		LPM	130 & 160 LI WI	IVIK		
	b) Head of pump	40 mtr.	40 mtr.	MR		
	c) Power supply	Required	Provided	MR		
	d) Auto starting of pump	Required	Provided	MR		
14.	Captive Water Storage for Fire Fighting					
	 Under ground tank capacity 	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	Required	Provided	MR		
	d) Over head tank capacity	10000 ltr.	10000 ltr.	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
	a) Pressurization of lift shaft	N/A	Ņ/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A	N/A	N/A		
17.	Stand by Power Supply	Required	Provided	MR		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		
20.	Special Fire Protection System any:	f special Risk, if	N/A			

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/322 dated 27/02/18, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval.

Signature of the Inspecting Officer

Signature of the Inspeating Officer

Name :- Rajinder Atwal Designation :- DO (CD)

Name:- Ravinder Singh 19:1:1

Designation :- ADO (CC)

on but up for kendpuned en henry