

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/EH/2021/SZ/ 27

Dated: 4/2/21

FIRE SAFETY CERTIFICATE

Certified that the **M/s Om Sweets Pvt. Ltd.,** GL-23, Shaheed Bhagat Singh Marg, Jail Road, Hari Nagar, New Delhi-110064 the building comprised of Basement, ground floor plus three upper floors, but restaurant is running at First floor only. The restaurant was issued FSC by this department vide letter no. F.6/DFS/MS/EH/2017/SZ/1069 dated 26/04/17 owned/occupied by M/s Om Sweets Pvt. Ltd. The building was re-inspected by the officers concerned of this department on 29/01/2021 in presence of Sh. Ajeem Khan (Unit Manager) and found that the management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi fire service Rules 2010 and that the building/premises (**First floor only**) is fit for occupancy class Group D "Assembly Building" w.e.f the date of issue of this certificate for a period of three years, subject to the conditions printed overleaf.

Issued on ______ at New Delhi.


(Sunil Chawdhary) Dy. Chief Fire Officer

5 km

Copy to: -

- The Manager,
 M/s Om Sweets Pvt. Ltd., GL-23,
 Shaheed Bhagat Singh Marg, Jail Road,
 Hari Nagar, New Delhi-110064
- The Dy. Health Officer, South Delhi Municipal Corporation, West Zone, Rajouri Garden, New Delhi-110027

Following fire safety directives must be adhered to:-



2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of

occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized

construction, if any.

7. Basement shall be used as per the building bye laws.

8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on

www.dfs.delhigovt.nic.in.

9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Name & address of the building: M/s Om Sweets Pvt. Ltd., GL-23, Shaheed Bhagat Shigh Warg, Jah Road, Hari Nagar, New Delhi-110064 Basement, ground plus three upper floors but restaurant is Building is comprised of running at first floor only. Group D (Assembly Building) Type of Occupancy Renewal Type of Case F.6/DFS/MS/EH/2017/SZ/1069 dated 26/04/17 5. Details of Previous NOC N/A 6. Fire Safety directives letter No: 28/01/2021 7. Date of inspection A.D.O. R.K. Yadav 8. Name of Inspecting Officer 9. Name and designation of officers Sh. Ajeem Khan (Unit Manager) From the building side 2009-10 10. Year of Construction 2021010509424 dated 08/01/2021 11. Applicant's letter No. Building is comprised of basement (store), ground floor (sweet shop), First floor (restaurant), second floor (kitchen), third floor (store) & terrace (two rooms sealed). Provided at Remarks Minimum Standards on fire prevention and fire Requirement S. MR/NMR site safety U/R 33 No. Access to building 1. MR 12 mtrs 09 mtrs Road width Provided MR 4.5 mtrs Gate width N/A N/A N/A Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases MR 02 No.'s 02 No.'s Upper Floors 02 No.'s MR Basements 02 No.'s b. Width of staircases 1.11 to 1.50 m & MR Two staircases Upper Floor 85 cms 1.30 m & .85 m MR Basements Two staircases c. Protection of exits MR Provided Required Fire check door N/A N/A N/A Pressurization d. No. of continuous staircases to MR One Required terrace MR Width of Corridor 1.60 m 1.50 m MR .92 & 1.15 m Two exits Door Size Compartmentation 3. MR Provided Required Fire check door N/A N/A N/A Sealing of electrical shafts Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System 4. MR Exhaust fans Required Basements are provided Natural MR Required Upper floors Ventilation Fire Extinguishers 5. Provided MR 03 No.'s/floor Total numbers ABC/CO₂ Provided MR Types ISI marked MR ISI marked IS marking First-Aid Hose Reels 6. MR Provided One Total numbers on ground floor MR Provided 30 mtrs I enoth of hose reel hose

	 Location of Main Panel 	Dagwined	C. Fl	1.00
3 - 42 30	 Location of Main Panel Location of Repeater Panel 	Required N/A	G. Floor	MR
	Alternate source of power	Required	N/A	N/A
	Hooters' Location	Required	Provided Provided Near exit	MR MR
8.	MOEFA	Required	Provided	MR
0.	WICEFA	Required		
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			1.00
	Basement	Required	Provided	MR
	Ground Floor	Required	Provided	MR
	Sprinkler above false ceiling	Required	Provided	MR
11.	Internal Hydrants	100 mm	Provided	MR
	Size of riser/down-comer Number of hydronts	One	Provided	MR
21	Number of hydrantsHose Box	One	Provided	MR
12.	Yard Hydrants		Tiovided	
12.	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements	11111		
13.	Ground Level			
	Discharge of main Pump	1620 LPM	Provided	MR
	➤ Head of Main pump	70 mtrs	Provided	MR
	Number of main pumps	One	Provided	MR
	➤ Jockey Pump out put	180 LPM	Provided	MR
	> Jockey pump head			MR
	Standby Pump out put	40 mtrs	Provided	
1.57	Standby Pump Head	1620 LPM	Provided	MR
*	Water Curtain Pump	70 mtrs	Provided	MR
1	> Auto Starting/Manual Stopping	N/A	N/A	N/A
		Required	Provided	MR
	> Pump House Access	Required	Provided	MR
	Terrace level			
	> Discharge of pump	900 LPM	Provided	MR
	> Head of the pump	40 mtrs	Provided	MR
	> Power Supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire fighting		2	
	Underground tank capacity	70000 Ltrs	Provided	MR
	Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	10000 ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	*		ot in use)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	 Pressurization of Lift lobby 	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
1	Fireman's Grounding Switch Line Signature The Signature State of the State o	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17.	Standby power supply	Required	Provided	MR
			1	
18.	Refuge Area. > Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
		IN/A	IN/A	11/11

19.	Fire Control Room			3
• Do • Fl • PA • Ba	 Detector System Panel Flow Switch Panel PA System Panel 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	Ņ/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2017/SZ/1069 dated 26/04/2017 renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Signature of Inspecting Office

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

DO(South West)

03/02/2021

Dy cfo/52)

F,7 Jolease

FI better to put up for ng

pycrofs2)

G. Ull