GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No. F.6/DFS/MS/GH/2021/SZ/ 44

Dated: 1/2/2/

FIRE SAFETY CERTIFICATE

Certified that Diplomat Residency Guest House located at BP-56 (Right Half), Ring Road, Lajpat Nagar-III, New Delhi comprised of Basement (Showroom), Ground floor (Showroom & reception in rear side), First floor (06 guest rooms), second floor (06 guest rooms), Third floor (06 guest rooms) was granted FSC by this department vide letter No. F.6/DFS/MS/GH/2017/SZ/1705 dated 27/11/2017. The premise was re-inspected by officer concerned of this department on 22:01:2021 ... in the presence of Sh. Ravindes Ahya and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that premises is fit for occupancy class "Residential & Lodging Building, Group- A" with effect from for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued 1/2/21 at New Delhi by

(Sunil Chawdhary) Dy. Chief Fire Officer **Delhi Fire Service**

Copy to: -

oy to:
1. Diplomat Residency Guest House located at BP-56 (Right Half), Ring Road, Lajpat Nagar-III, New Delhi.

2. The Joint Commissioner of Police, Licensing Branch, 1st floor P.S. Defence Colony, New

Conditions for the validity of Fire Safety Certificate:

- 1. This FSC shall stand null & void without further communication after three months from the date of issue, if the requirements as stipulated in Gazette notification no. F.5(189)/AD/LB/2016/710-725 dated 17/12/2020 is not implemented under intimation to Delhi Fire Service.
- 2. All the means of escape/entry/exit shall be kept from any obstruction.
- 3.All the fire safety arrangements provided therein shall be maintained in good working condition at all times. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. All the staff members must know the correct method of operation of fore fighting system.
- 5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rule of 2010. The form is available on www.dfs.delhigovt.nic.in.
- 6. The certificate may not be treated in any case for the regularization (clause 2.8 & UBBL-2016) of the unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

1	Name & Address of the Building	Diplomat Residency Guest House, BP-56 (Right Half			
2	Type of Occupancy		ipat Nagar-III, New Delhi al & Lodging, Group-A		
3	Building Comprised of				
4	Type of Case	Basement, Ground + 03 Upper floors Renewal/Revalidation			
5	Details of Previous NOC	F.6/DFS/MS/GH/2017/SZ/1705 dated 27/11/2017			
6	Fire Safety Directives Letter No	Nil		(1	
7	Date of Inspection	22/01/2021			
	Name of the Inspecting Officers	ADO Avtar Singh			
8		Mr. Ravinder Ahuja	a (Manager)	anager)	
9	Name & Designation of Officers from the building side	Wii. Ravinder Midja (Manager)			
10	Year of construction	Basement (Showroom), Ground floo (Showroom & Reception at rear side) 1 st floo (06 G/Rooms), 2 nd floor (06 G/Room), 3 rd floor (06 G/Room), Total 18 Guest Rooms			
11	Applicant letter No		9918 dated 17/12/2020	uest Rooms	
11	Applicant letter No. Minimum standards on Fire	OLD NOC	Provided at Site	Remarks	
S. No	Prevention and Fire Safety U/R 33	Requirements	Trovidou at Save	MR/NMR	
1	Access to Building.				
	Road width	Required	6 mtr.	MR	
	Gate width	-N/A-	-N/A-	-N/A-	
	Width of internal road	-N/A-	-N/A-	-N/A-	
2	Number, width, type & arrangemen	nt of exits.			
	a) Number of Staircase				
	> Upper floors	Required	One	MR	
	> Basement floor	Required	Two	MR	
	b) Width of Staircase				
	> Upper floors	1.0 mtr	1.30 mtr	MR	
	> Basement floor	1.0 mtr	1.22 mtr & 1.0 mtr	MR	
	c) Protection of exits				
	> Fire check door	Required	Not Provided	NMR	
il a	> Pressurization	-N/A-	-N/A-	-N/A-	
	d)No. of continuous staircase to terrace	Required	One	MR	
	e) Width of corridor	-N/A-	-N/A-	-N/A-	
	f) Door size	1 m	1.53 m (final exit)	MR	
3	Compartmentation.				
	Fire check door.	Required	Not Provided ,	NMR /	
	Sealing of electrical shafts.	-N/A-	-N/A-	-N/A-	
	Fire rating of shaft door.	-N/A-	-N/A-	-N/A-	
	Water curtain Fine dampers	-N/A-	-N/A-	-N/A-	
	• Fire dampers.	-N/A-	-N/A-	-N/A-	
4.	Smoke Management system.				
	Basement	30 ACPH	Exhaust fan Provided	MR	
	Upper floors	12 ACPH	Exhaust fan Provided	MR	
5.	Fire Extinguishers.		(
	Total numbers	10 Nos.	10 Nos	MR	
	• Types	ABC/Co2	ABC-6, & CO ₂ -4	MR	
. 14	• ISI Marking	ISI marked	Provided	MR	
6.					
0.					

	Total numbers on each floor	One	Provided	MI		
	• Length of hose-reel hose.	30 m	30 m	MR		
	Nozzle Diameter	5 mm	5 mm	MR		
7	Automatic fire detection & alarming	system.				
/	Type of detectors Carbon monoxide Provided /					
	Location of Main Panel	(CO) type				
	 Location of Repeater Panel 	Required	Ground floor	MR		
	 Alternate source of power 	-N/A-	-N/A-	-N/A-		
	 Hooter's location 	Required	Provided	MR		
		Required	Provided	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	-N/A-	Provided /	MR		
10.	Automatic Sprinkler System					
Comp. (Classical)	Basement	Required	Provided	MR		
	 Upper floors 	Required	Provided	MR		
	 Sprinkler above false ceiling 	-N/A-	-N/A-	-N/A-		
11.	Internal Hydrants.					
1.0	Size of Riser / Down-comer	Required	100 mm	MR		
	Number of Hydrant per floor	Required	One	MR		
	Hose box.	Required	One	MR		
12.	Yard Hydrants.					
12.	Total number of hydrants.	-NA-	-NA-	-NA-		
	Hose box.	-NA-	-NA-	-NA-		
13.	Pumping arrangements.					
13.	Ground Level					
	• Ground Ecver	-N/A-	1200 LPM	-N/A-		
	Discharge of main pump.	-N/A-	50 mtr /	-N/A-		
	Head of main pump.Number of main pumps.	-N/A-	One	-N/A-		
	Jockey Pump output.	-N/A-	180 LPM	-N/A-		
	Jockey Pump head.	-N/A-	50 mtr	-N/A-		
	Standby Pump output.	-N/A-	-N/A-	-N/A-		
	Standby Pump head.Auto Starting/Manual	-N/A-	-N/A-	-N/A-		
	Auto Starting/Manual Stopping.	-N/A-	Provided	-N/A-		
	Pump house access.	-N/A-	Provided	-N/A-		
	Towns Level					
	Terrace Level Discharge of nump	900 LPM	900 LPM	MR		
	Discharge of pump.Head of pump.	40 mtr	40 mtr	MR		
	> Power supply.	Required	Provided (MR		
	> Auto starting of pump.	Required	Provided	MR		
14.	Captive water storage for firefighting					
	Underground tank capacity.	35,000 ltrs	Provided	MR		
	Draw-off connection.	-N/A-	-N/A-	-N/A-		
	Fire Service Inlet.	Required	Provided /	MR		
	Access to tank.Overhead tank capacity.	Required	Provided	MR		
	Overnead tank capacity.	10,000 ltrs	10,000 ltrs /	MR		
15	. Exit Signage.	Required	Provided	MR		
16	interest to					
10	Provision of Lifts.Pressurization of lift shaft.	-N/A-	-N/A-	-N/A-		
	 Pressurization of lift lobby. 	-N/A-	-N/A-	-N/A-		

			- 10)				
36	•	Fireman's switch.	Required	Provided	MR		
	•	Lift signage.	Required	Provided	MR		
17	Stand	l <mark>by Power</mark> Supply	Required	Provided	MR		
18.	Refuge Area						
	•	Total area	-N/A-	-N/A-	-N/A-		
	•	Location	-N/A-	-N/A-	-N/A-		
19.	Fire	Fire Control Room.					
	•	 Detector System Panel. Flow Switch Panel. PA system Panel. Battery backup Building floor plan 	-N/A-	-N/A-	-N/A-		
			-N/A-	-N/A-	-N/A-		
			-N/A-	-N/A-	-N/A-		
			-N/A-	-N/A-	-N/A-		
	Sullang Hoor plan	-N/A-	-N/A-	-N/A-			
20.		cial Fire Protection System for rotection of special Risk, if any.	N/A	ABC type fire extinguisher provided near electric panel	N/A		

The Fire protection systems provided in the premises were checked / operated at random and found functional at the time of inspection.

The condition of the Gazette notification dated 27/05/2019 on mentioned below found complied.

1. No Kitchen on rooftop/basement.

MR No Kitchen Provided MR No Storage Provided

2. No Storage of inflammable material on rooftop.

MR No Storage Pro MR Not Provided

3. No temporary roofing over the rooftop.4. No Inflammable material of construction in passage/corridor.

MR Not Provided

5. Gas Bank, if any

MR No Gas Bank provided

6. Carbon Monoxide type Detectors.

MR Provided

7. Fire Doors of min. 01 hr. rating

NMR Not Provided

(If number of occupants more than 10 on each floor)

In view of the substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules of NOC issued vide letter no. F6/DFS/MS/GH/2017/SZ/1705 dated 27/11/20 7, renewal under rule 37 of the Delhi Fire Service rule 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name : Avtar Singh

Designation: ADO (M.Rd)

DO (SD

Difo(sy)

F. J. Ja

ADO MRd,

MATA