## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2021/ 🙎

Dated: 11 02 2021

## **FIRE SAFETY CERTIFICATE**

Certified that M/s. Hotel Pooja Palace located at 15A/11, W.E.A, Karol Bagh, New Delhi- 110005 comprised of basement, ground plus three upper floors, using basement floor as storage, ground floor as reception, 02 guest rooms, first, second & third floor having 09 guest rooms respectively (total 29 guest rooms) was granted FSC by this department vide letter No. F6/DFS/MS/GH/SZ/2018/233 dated 09.02.2018. The premises was re-inspected by the officer concerned of this department on 03.02.2021 in presence of Sh. Munish Chawla, Owner/Occupier of the guest house and found that the said guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) with effect from 1102 2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 11/02/2021 at New Delhi by.

(Sunil Chaudhary)

Dy. Chief Fire Officer (SZ)

Copy to:-

- 1. Shri Munish Chawla (Owner), M/s. Hotel Pooja located at 15A/11, W.E.A, Karol Bagh, New Delhi- 110005
- 2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

## Conditions for the Validity of Fire Safety Certificate

- 1. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 10. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

**INSPECTION REPORT** 

1. Name & address of the building : M/s. Hotel Pooja Palace, 15A/11, WEA, Karol Bagh,

New Delhi- 05.

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : F.6/DFS/MS/GH/SZ/2018/233 dated 09.02.2018

5. Fire Safety directives letter No : Nil

6. Date of inspection : 03.02.2021

7. Name of the Inspecting Officers : P.V. Rathee, Asstt. Div. Officer (SRD)

8. Name and designation of officers

from the building side : Sh. Munish Chawla, Owner/Occupier

9. Year of Construction : Before 2001

10. Applicant's letter No. : Online Application ID 2021012009790 dated25.01.2021

The said guest house is comprised of basement, ground plus three upper floors.

S. No.		linimum Standards on fire ention and fire safety U/R 33	Fire safety arrangements as per FSC dt. 25.11.2014	Provided at s	ite	Remarks MR/NMR	
1	Access to building						
		Road width	Old case	Provided		MR	
	•	Gate width	required	Directly accessib	ole	MR	
	•	Width of internal road	N/A	N/A		N/A	
2	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	•	Upper Floors	Old case	01	MR beir	ng old case	
	•	Basements	01	02		MR	
	b. Wid	th of staircases	-,				
	•	Upper Floors	Old case	1.20 mts	MR	being old case	
	•	Basements	Old case	1.20 & 1.24 mts	MR	being old case	
	c. Prot	ection of exits		-		-	
		Fire check door	Required	Not Provided		ompliance has bee	
	•	Pressurization	N/A	N/A	extended	N/A	
	e. No terrace	. of continuous staircases to	01	01	MR being old case		
		th of Corridor	Old case	1.90 mts		MR	
	h. Doo		Old case	0.90 mts	MR	being old case	
,	Comp	artmentation.			date of compliance has be extended up to 31.03.202		
	•	Fire check door	Required	Not Provided			
	•	Sealing of electrical shafts	N/A	N/A			
	•	Fire Rating of shaft door	N/A	N/A		N/A	
	•	Water Curtain	N/A	N/A	N/A		
	•	Fire Dampers	N/A	N/A		N/A	
	Smoke	Management System.					
	•	Basements	30 a/c per hour	Exhaust fan provid	led	MR	
	•	Upper floors	12 a/c per hour	Natural Ventilati			
	Fire E	xtinguishers		contractor describe			
	•	Total numbers	12	Provided		MR	
	•	Types	CO <sub>2</sub> , ABC, WCO <sub>2</sub>	Provided		MR	
	100	**	ISI marked	D '11		MD	

* 1		• lotal numbers on each floor	01	Provided	MR		
		<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR		
		Nozzle diameter	5 mm	Provided	MR		
	7	Automatic fire detection and alarming					
		Type of detectors	Carbon Monoxide	Not Provided	date of compliance has been extended up to 31.03.2021		
		Location of Main Panel	Required	Not Provided	date of compliance has been extended up to 31.03.2021		
		• Location of Repeater Panel	N/A	N/A	N/A		
		Alternate source of power	Required	D.G. set 72 KVA	MR		
		Hooters' Location	N/A	N/A	N/A		
	8	MOEFA	Required	Provided	MR		
	9	Public Address System.	Required	Provided	MR		
	10	Automatic Sprinkler System.					
		Basement	Required	Provided	MR		
		Upper Floor	N/A	N/A	N/A		
		Sprinkler above false ceiling	N/A	N/A	N/A		
-	11	Internal Hydrants					
		Size of riser/down-comer	N/A	N/A	N/A		
		Number of hydrants per floor	N/A	N/A	N/A		
		Hose Box	N/A	N/A	N/A		
	12	Yard Hydrants.					
-		Total number of hydrants	N/A	N/A	N/A		
		Hose Box	N/A	N/A			
-	13		IV/A	IV/A	N/A		
-	13 Pumping Arrangements.						
		<ul><li>Ground Level</li><li>Discharge of main Pump</li></ul>	N/A	N/A	N/A		
		Head of Main pump	N/A	N/A	N/A N/A		
-		Number of main pumps	N/A	N/A	N/A N/A		
		Jockey Pump out put	N/A	N/A			
		> Jockey pump head	N/A	N/A	N/A		
		Standby Pump out put	N/A		N/A		
		Standby Pump Head	N/A	N/A	N/A		
		<ul><li>Auto Starting/ Manual stopping</li></ul>		N/A	N/A		
		> Pump House Access	N/A N/A	N/A N/A	N/A		
		Terrace level		IN/A	N/A		
		Discharge of pump	450 LPM	450 LPM	MR		
		Head of the pump	30 mts	30 mts	MR		
		Power Supply	Required	Provided	MR		
		Auto Starting of pump	Required	Provided	MR		
	14	Captive Water Storage for fire fighting	5.				
		Underground tank capacity	N/A	N/A	N/A		
* 11 %		Draw-off connection	N/A	N/A	N/A		
		> Fire service inlet	N/A	N/A	N/A		
		> Access to tank	N/A	N/A	N/A		
	1.5	Overhead Tank capacity	5000 lts	provided	MR		
	15	Exit Signage.	Required	Provided	MR		

N/34

16	Provis	Provision of Lifts.				
	•	Pressurization of Lift Shaft	N/A	N/A	N/A	
	•	Pressurization of Lift lobby	N/A	N/A	N/A	
	•	Communication In lift Car	N/A	N/A	N/A	
	•	Fireman's Grounding Switch	N/A	N/A	N/A	
19		Lift Signage	N/A	N/A	N/A	
17	Stand	by power supply	Required	Provided	MR	
18	Refug	Refuge Area.				
	>	Total Area	N/A	N/A	N/A	
	>	Location	N/A	N/A	N/A	
19	Fire Control Room					
	•	Detector System Panel	N/A	N/A	N/A	
	•	Flow Switch Panel	N/A	N/A	N/A	
	•	PA System Panel	N/A	N/A	N/A	
		Battery backup	Required	Provided	MR	
	•	Building Floor Plans	N/A	N/A	N/A	
20	-	l Fire Protection Systems for tion of special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The management has given an undertaking not to use any occupancy above third floor & basement as storage purpose.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/SZ/2018/233 dated 09.02.2018, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer Name P.V. Rathee

Asstt. Div. Officer (SRD)

My 10212021

Dy eso (f2)

F.t. p-lease