

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001**

No.F6/DFS/MS/2021/NDZ | 117

Dated :-----12/02/2021

**FIRE SAFETY CERTIFICATE**

Certified that the **All India Woman's Conference, Sarojni House** Located at 6 ,Bhagwan Das Road , New Delhi comprised of **Basement + Ground + 06 Upper floors** was issued FSC by this department vide letter No.F6/DFS/MS/2013/NDZ/1112 dated **22/10/2013**. The premises was re-inspected by the officer concerned of this department on **03/02/21** in the presence of **Sh. Naresh Kumar Aggrawal** and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Hostel Building with effect from ~~---~~12/02/2021~~---~~ for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued ~~---~~12/02/2021~~---~~ at New Delhi by.

(Atul Garg)  
DIRECTOR  
Delhi Fire Service

Copy to:-

- 1) The MHO, N.D.M.C, New Delhi.
- 2) Ms. Sheela Kadke, President,  
All India Woman Conference,  
6 Bhagwan Das Road,  
New Delhi – 110001.

**Condition for the validity of fire safety certificate**

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1. Name & address of the building : All India Women's Conference at Sarojini House, 6, Bhagwan Dass Road, New Delhi B+Gr.+6th upper floor
2. Type of occupancy : Residential ( hostel)
3. Type of case:- : Renewal
4. Details of previous FSC : F6/DFS/MS/2013/NDZ/1112 dated 22/10/2013
5. Fire safety directives No. : N/A
6. Date of inspection:- 03/02/21
7. Name of the inspecting officer : Sh. Rajinder Atwal DO/CD & Sh. Ravinder Singh ADO/CC
8. Name & designation of officer  
From the building side : Sh Naresh Kumar Aggrawal
9. Year of construction : 1977
10. Applicant's letter No : No 186/2021/AIWC dated 13/01/2021

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	06 mtr.	12 mtr.	MR
	2) Gate width	06 mtr.	6 mtr.	MR
	3) Width of internal road	06 mtr.	6 mtr.	MR
2.	Number, Width Type & Arrangement of Exits			
	A. Number of staircases			
	1. Upper floors	04	04	MR
	2. Basements	02	02	MR
	B. Width of staircase			
	1. Upper floors	100cms	02 of 125cms each & 2 of 90cms each.	MR
	2. Basements	100cms.	Two staircases 170 cms each	MR
	C. Protection of exits			
	1. Fire check door	Required	Provided	MR
	2. Pressurization	NA	NA	NA
	D. No. of continuous staircase to terrace	03	03	MR
	E. Width of corridor	190 cms & 140 cms	Provided	MR
	F. Door size	NA	NA	NA
3.	Compartmentation			
	1) Fire check door	Required	Provided	MR
	2) Sealing of electrical shafts	Required	Provided	MR
	3) Fire rating of shaft door	One hour	Provided	MR
	4) Water curtain	NA	NA	NA

A



	5) Fire Dampers	NA	NA	NA
4.	Smoke Management System			
	1) Basements	30 ACPH	Exhaust fan.	MR
	2) Upper floors	12 ACPH	Natural	MR
5.	Fire Extinguishers			
	1) Total numbers	36 Nos.	104 Nos.	MR
	2) Types	ABC, CO2, W.CO2 & DCP	ABC, CO2, W.CO2 & DCP	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			
	1) Total number	3 nos	Provided	MR
	2) Length of hose reel hose	30 m	Provided	MR
	3) Nozzle diameter	5 mm	Provided	MR
7.	Automatic Fire Detection & Alarming System			
	1) Type of detectors	Smoke	Provided	MR
	2) Location of main panel	Gr. Floor	Provided	MR
	3) Location of repeater panel	NA	NA	NA
	4) Alternate source of power	UPS	Provided	MR
	5) Hooter's Location	Near gate	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	Required	Provided	MR
	2) Upper floors	NA	NA	NA
	3) Sprinkler above false ceiling	NA	NA	NA
11.	Internal Hydrants			
	1) Size of riser/down-comer	100 MM	100MM	MR
	2) Number of hydrants per floor	03nos	Provided	MR
	3) Hose box each floor	Required	Provided	MR
12.	Yard Hydrants			
	1) Total number of hydrants	N/A	04nos	N/A
	2) Hose box	N/A	04nos	N/A
13.	Pumping Arrangement			
	1) Ground level			
	a) Discharge of main pump	2280 LPM	Provided	MR
	b) Head of main pump	70 mtr.	Provided	MR
	c) Number of main pump	01	Provided	MR
	d) Jockey pump out put	180 LPM	Provided	MR
	e) Jockey pump head	70 mtr.	Provided	MR
	f) Stand by pump output	2280 LPM	Provided	MR
	g) Stand by pump head	70mtr.	Provided	MR
	h) Auto starting/Manual stopping	Required	Provided	MR
	2) Terrace level			



	a) Discharge of pump	N/A	N/A	N/A
	b) Head of pump	N/A	N/A	N/A
	c) Power supply	N/A	N/A	N/A
	d) Auto starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for Fire Fighting			
	1) Under ground tank capacity	1,00,000 ltr.	Provided	MR
	a) Draw-off connection	Required	Provided	MR
	b) Fire service inlet	Required	Provided	MR
	c) Access to tank	Required	Provided	MR
	d) Over head tank capacity	10,000 ltr.	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	03 Nos. Lift		
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room			
	a) Detector system panel	Required	Provided at G.F.	MR
	b) Flow switch panel	Required	Provided at G.F.	MR
	c) PA system panel	Required	Provided at G.F.	MR
	d) Battery backup	Required	Provided	MR
	e) Building floor plan	N/A	N/A	N/A
20.	<b>Special Fire Protection System for Protection of special Risk, if any:</b>			MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2013/NDZ/1112 dated 22/10/13, if agreed, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval .

Signature of the Inspecting officer

Name: - Rajinder Atwal  
Designation: - DO (CD)

*Rajinder Atwal*

*Inspector*  
9/2/21

*CFO (CD)*

*Atwal*

Signature of the Inspecting Officer

Name: Ravinder Singh  
Designation: ADO (CC)

*Ravinder Singh*  
8/2/21

