GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2021/ND2/71

Dated: 05 02 2021

FIRE SAFETY CERTIFICATE

Certified that the Hotel Sai International located at 7864, Arakashan Road, Pahar Ganj, New Delhi. comprised of Ground floor (02 guest rooms + Reception), 1st floor to 4th floor (04 guest rooms at each floor), Total 18 guest rooms, was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/52 dated 05/01/18. The premises was re-inspected by the officer concerned of this department on 27/01/21 in the presence of Mr. Raju Saluja and found that the building having Ground floor - 02 guest rooms + reception, 1st to 3rd floor 04 guest rooms at each floor, total 14 guest rooms only and 4th floor (not in use as per affidavit dated 26.09.2019 submitted by applicant),. The said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential Group A-1 Ground floor – 02 guest rooms + reception, 1st to 3rd floor 04 guest rooms at each floor, total 14 guest rooms only with effect from 05 22 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 05 02 2021 at New Delhi by.

(Dr S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

0

- 1. The Joint Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID NO. 2021011009558 dated 11.01.2021.
- 2. The Manager,

Hotel Sai International located at 7864, Arakashan Road, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other condition mentioned in the gazette notification dated 27.05.2019 & clarification issued dated on 25.09.2019 & 17.12.2020 latest by 31.03.2021.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.

9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

10. The owner shall not use any floor above third floor for any purpose and same shall

remain closed/locked.

INSPECTION REPORT

1. Name & address of the building Hotel Sai International located at 7864,

2. Type of occupancy:
Arakashan Road, Pahar Ganj, New Delhi.
Residential Group A-1 Ground + 3rd Upper

floor (14 guest rooms)

Ground floor – 02 guest rooms + reception, 1st to 3rd^h Floor 04 guest rooms at each floor.

4th floor not in use as per affidavit)

3. Type of case:-

4. Details of previous FSC:-

5. Fire safety directives No.-

6. Date of inspection:7. Name of the inspecting of

7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

9. Year of construction:-

10. Applicant's letter No:-

Renewal No. F6/DFS/MS/GH/2018/52 dated 05/01/18.

N/A 27/01/21

Sh. Ravinder Singh (ADO/CC)

Sh. Rajinder Atwal(DO/CD)

Mr. Raju Saluja 2002

ID NO. 2021011009558 dated 11.01.2021...

Building is comprised of ground and five upper floors and 4th & 5th (1/2 terrace) floor not in use as per affidavit dated 26.09.2019 submitted by applicant.

S.No.	M: Contact			Old Case
	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	N/A	08 mtr.	N/A
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arrai	ngement of Exits		INA
	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			IVA
	1. Upper floors	80 cms.	92 to 109 cms.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			14/74
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous	N/A	N/A	N/A
	staircase to terrace			1 1/7 1
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	01 mtr.	01 mtr.	MR
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
2	5) Fire Dampers	N/A	N/A	N/A
	Smoke Management System		В	
	1) Basements	30 ACPH	N/A	N/A
	2) Upper floors	12 ACPH	Natural	MR
•	Fire Extinguishers			4
	1) Total numbers	10 Nos.	10 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR



	3) ISI marking	Required	Duaridad				
6.	First-Aid Hose Reel	required	Provided	MF			
	1) Total number at each floor	1) Total number at each floor					
	2) Length of hose reel hose	30 mtr.	01 no.	MR			
	3) Nozzle diameter	05 mm	Provided	MR			
7.	Automatic Fire Detection & A	U3 mm	Provided	MR			
	1) Type of detectors CO type						
	2) Location of main panel	Required as per G.N dated 27.05.19	Not provided	Last dt. of compliance extended vide order dt.			
-	3) Location of repeater panel	N/A	N/A	N/A			
	4) Alternate source of power	N/A	N/A	N/A			
	5) Hooter's Location	N/A	N/A	N/A			
. 0		N/A	N/A	N/A			
8.	MOEFA	N/A	N/A	N/A			
9.	Public Address System	N/A	N/A	N/A			
10.	Automatic Sprinkler System						
	1) Basement	N/A	N/A	N/A			
	2) Upper floors	N/A	N/A	N/A			
11	3) Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants			2			
	1) Size of riser/down-comer	N/A	N/A	N/A			
	2) Number of hydrants per floor	N/A	N/A	N/A			
10	3) Hose box	N/A	N/A	N/A			
12.	Yard Hydrants						
	1) Total number of hydrants	N/A	N/A	N/A			
	2) Hose box	N/A	N/A	N/A			
13.	Pumping Arrangement						
	1) Ground level	N/A	N/A	N/A			
	a) Discharge of main	N/A	N/A	N/A			
	pump						
	b) Head of main pump	N/A	N/A	N/A			
	c) Number of main pump	N/A	N/A	N/A			
	d) Jockey pump out put	N/A	N/A	N/A			
	e) Jockey pump head	N/A	N/A	N/A			
	f) Stand by pump output	N/A	N/A	N/A			
	g) Stand by pump head	N/A	N/A	N/A			
	h) Auto starting/Manual	N/A	N/A	N/A			
	stopping		1				
	2) Terrace level						
	a) Discharge of pump	225 LPM	225 LPM	MR			
	b) Head of pump	40 mtr.	40 mtr.	MR			
	c) Power supply	Required	Provided	MR			
	d) Auto starting of pump	Required	Provided	MR			
14.	Captive Water Storage for Fire						
	Under ground tank capacity	N/A	N/A	N/A			
	a) Draw-off connection	N/A	N/A	N/A			
	b) Fire service inlet	N/A	N/A	N/A			
	c) Access to tank	Required	Provided	MR			
	d) Over head tank capacity	2,500 ltr.	2,500 ltr.	MR			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.						

	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System fo any: ABC & CO ²	MR		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/52 dated 05/01/18., renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only.

Signature of the inspecting officer

Signature of the Inspecting Officer

Name: - Rajinder Atwal Designation: - DO (CD) Name: Ravinder Singh Designation: ADO (CC)

Aso les As apporved, strupulip for ken Pensie and Synghmi Pl.