### FORM 'H': FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[See sub-rule (1) of rule 35]

# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/GH/2021/SZ/ 04

Dated: 5 /2 /2021

#### FIRE SAFETY CERTIFICATE

Certified that the M/S Pride Hotel located at Asset No.5A, Hospitality District, Aerocity, IGI Airport, New Delhi 110037 comprised of Three tier Basement, Ground Floor, Service Floor & Seven Upper Floors only owned / occupied by Pride Plaza Hotel, has already been issued Fire Safety Certificate Vide letter No. F6/DFS/MS/Mixed/SZ/2018/1272 dated 31/05/2018. The premises was re-inspected by the officer concerned of Fire Service on 21.01.2021 in the presence of Sh. Sh. Mohmd. Shoaib (AVP) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of the Delhi Fire Service Rule, 2010and that the building / premises is fit for occupancy class "Mixed" (Hotel & Commercial) with effect from 5/2/2021 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010.

(ATUL GARG) DIRECTOR

Copy to:-

1. Authorized Signatory, M/S Pride Plaza Hotel, Asset No.5A, Hospitality District, Aerocity, IGI Airport, New Delhi 110037.

2. Joint Commissioner of Police (Lic.), 1st Floor, PS Defence Colony, New Delhi-110049.

#### Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. The basement shall be used strictly as per the provision of building bye laws.

6. This certificate cannot be treated in any case for regularizations of unauthorized construction.

7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on <a href="https://www.dfs.Delhigovt.nic.in"><u>WWW.dfs.Delhigovt.nic.in</u></a>

1/125

## **INSPECTION REPORT**

1. Name & address of the building

: M/S Pride Plaza Hotel, Asset No.5A, Hospitality District, Aerocity, IGI Airport, New Delhi 110037.

2. Building is comprised of

: B1+B2 (With Mezzanine)+B3+G+S+7 upper floors.

3. Type of Occupancy

: Mixed (Hotel and Commercial).

4. Type of Case

: Renewal

5. Details of Previous NOC

: F6/DFS/MS/Mixed/SZ/2018/1272 dated31/05/2018

6. Fire Safety direction letter No

: F.6/DFS/MS/BP/2010/3290, Dated 01.12.2010

7. Date of Inspection

: 21.01.2021

8. Name of the Inspecting Officers:

: A.D.O.(S.J.)

9. Name and designation of Officer from the building side

: Sh. Mohmd. Shoaib (AVP)

10. Year of Construction 11. Applicant's letter No

: Nil, dated 14.01.2021 outdoor diary No. 10455 dated 15/01/2021.

S.No	Minimum Standards on fir prevention and fire safety U/R-33	re Requirement F		Pro	ovided at Site	Remarks MR/NMR		
	Access to building							
	Road width		12-111		ovided	MR		
	Gate width		4.5m		ovided	MR		
	Width of internal road		6m ·	Pr	ovided	MR		
)	Number, Width, Type and Arrangement of Exits.							
	a. Number of Staircases		03nos.		Provided		MR	
	Upper Floor	B3 to B2- 4 Nos			Provided		MR	
	Basement	B2	B2 to B1-5 Nos					
		B1	B1 to GF-8 Nos					
	B. Width of Staircases	1.5m(each)		1.5m(each)		MR		
	Upper Floor	1.5m(each)		1.5m(each)+7.5m ramp		MR		
	Basement	Required			Provided		MR	
	c. Protection of exits	Required			Provided		MR	
	Fire check door	Required			Provided		MR	
	Pressurization	03nos.		03nos.		MR		
	e. No. of continuous staircases		71100.		8			
	to terrace floor.	1.5m			1.5m		MR	
	g. Width of Corridor	1m & in Banquet hall 2m		2m	1m & in banquet hall 2m		MR	
	h. Door Size	Till & III Ballquot han 2						
3	Compartmentation						ID.	
	Fire check door		Required		rovided		IR .	
	Sealing of electrical shafts		Required		rovided		1R	
	Fire rating of shaft door		Required	P	rovided	IV	1R	
	Water curtain		Required	P	rovided	N	1R	
	Fire Dananara		Required	P	rovided	N	1R	
	Fire Dampers							
4	Smoke Management System.		30a/c per hour		Provided		1R	
	Basement	000,000,000			1 10 110 00		/IR	
	Upper floor	12 a/c per flour			1011404		-	



11.26

# M/S Pride Hotel at Asset No.5A, Hospitality District, IGI Airport, New Delhi 110037.

5.	Fire Extinguisher	000		244 222	MD			
	Total numbers		00011001		MR			
	Types	WCO <sub>2</sub> , CO <sub>2</sub> & Al	3C	ABC Type				
	ISI marking	ISI marked ISI marked		MR				
6	First-aid-Hose Reels.  Total numbers of each floor 05nos.in basements 05nos.in basements MR							
	Total numbers of each floor	Control of the second of the s	05nos.in basements			MR		
		04nos in upper floors		04nos in upper f	loors	MD		
	Length of hose reel hose	30m		30m		MR		
	Nozzle diameter	5mm		5mm		MR		
7	Automatic fire detection and alarming system.							
	Type of detectors	Smoke & Heat		Smoke & Heat				
	Location of main panel	Ground Floor		Ground Floor	MR			
	Location of repeater panel	Fire Control Room		FCR	MR			
	Alternate source of power	Required .		Provided	MR			
	Hooters	On each floor		Provided	MR			
2	MOEFA	Required		Provided	MR			
3		Required Provided  Required Provided		MR				
9	Public address System.  Automatic Sprinkler System.	Nequiled		1 Tovided	1011	Y .		
	Basement	Required Provided		MR				
	upper floor	Required		Provided	MR			
					1			
	sprinkler above false ceiling Required Provided MR							
11	Internal Hydrants			150	LA4D			
	size of riser/down-comer	100mm 150mm			MR			
		5 No's in basement &		Provided	MR			
	Number of hydrants per floor		4 No's in upper floors 5 No's in basement &		MR			
		4 No's in upper floors		Provided	VIGGO			
	HOSE DOX							
12	Yard Hydrants.			107	MD	-		
	Total number of hydrants	07nos.	07nos.		MR			
	Hose Box	07nos.	07nos.		MR			
13	Pumping Arrangements.							
	Ground Level	-			-			
	Discharge of main Pump	2280lpm(Two)	2850lpm(Two),1800l			MR		
	Head of Main Pump	70m(Two)	88m(Two), 40m (one		)	MR		
	Number of main pumps	02nos.		02nos.+01no.		MR		
	Jockey pump out put	180 LPM(Two)	180LPM(Two)			MR		
	Jockey pump head	70m	88m			MR		
	> Standby pump out put	2280 LPM	2850LPM			MR		
	> Standby pump Head	70m	88m			MR		
	> Auto Starting /Manual	Required	Provided			MR		
	stopping	Required	Provided			MR		
	> Pump House Access	Required	Provided			MR		
	> Terrace Level	900LPM	900LPM			MR		
	Discharge of pump	40m	40m			MR		
	> Head of the Pump	Required	Provided			MR		
	> Power supply	Required	Provided			MR		
	Auto Starting of pump							



M/S Pride Hotel at Asset No.5A, Hospitality District, IGI Airport, New Delhi 110037.

14	Captive Water Storage for Fire Fighting	<b>]</b> .			MD	
	Underground tank capacity	1,50,000Liters		2,00000Litrs.	MR	
	Draw-off connection	Required		Provided	MR	
	Fire service inlet	Required		Provided	MR	
	Access to tank	Required		Provided	MR	
	Overhead Tank capacity	20,000Liters		Provided	MR	
15	Exit Signage.	Required		Provided	MR	
16	Provision of Lifts.					
	Pressurization of Lift Shaft	Required		Provided	MR	
	Pressurization of Lift lobby	Required		Provided	MR	
	Communication in lift car	Required		Provided	MR	
	Firemen's grounding switch	Required		Provided	MR	
	Lift Signage	Required		Provided	MR	
17	Standby power supply	Required		1250KVA(Two)	MR	
18	Refuge Area.					
	Total area	103sqm.		103sqm.	MR	
	Location	7 <sup>th</sup> Floor		7 <sup>th</sup> Floor	MR	
19	Fire Control Room					
	Detector system panel	Required		Provided	MR	
	Flow switch panel	Required		Provided	MR	
	PA system panel	Required		Provided	MR	
	Battery backup	Required		Provided	MR	
	Building Floor Plans	Required		Provided	MR	
20	Special Fire Protection systems for	Required	for	Provided( CO <sub>2</sub> flooding	MR	
	protection of special Risks, if any:	transformers,	LT	system auto mode)		
		&HT panels				

Note: Shortcomings issued by this department F6/DFS/Ms/2020/SZ/Hotel/3085 dated 17/12/2020 have been complied.

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. F6/DFS/MS/Mixed/SZ/2018/1272 dated 31/05/2018 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

4

Signature of the Inspecting Officer Name : Ashok Kumar Jaiswal

Designation: A.D.O. (S.J.)

This is a high rise blog. The competency to dispose off the Case is with with with Kirlson

by pyckot DO+ ADD earlier and

11