## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2021/97

Dated: -18/02/2021

## FIRE SAFETY CERTIFICATE

Certified that the M/S G. S. Guest House located at 908 & 937, Mantola, Gali Harimandir, Pahar Ganj, New Delhi, Gr+ 4<sup>th</sup> upper floor, Ground – 03 room + reception, Ist to 3<sup>rd</sup> floor – 04 guest room at each floor, fourth floor – servant room Total -15 guest rooms, was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2017/NDZ/1055 dated 19/07/17. The premises was re-inspected by the officer concerned of this department on 09/02/21 in the presence of Mr.Ganesh Aggrawal and found that the said guest house building having ground floor – 02 room and reception /office, Ist to 3<sup>rd</sup> floor -4 guest room at each floor and 4th (not in use as per affidavit dated 12.10.2019 submitted by applicant), total -14 guest room only, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 ground floor - 02 room and reception /office, Ist to 3rd, floor -4 guest room at each floor for total 14 guest rooms only with effect from 18/02/2021-for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below. Issued --/-2-/-2-2-at New Delhi by.

(Dr S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

0210mm

Copy to:-

- 1. The Joint Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID NO. 2021011309647dated 13.01.2021.
- 2. The Manager,
  - G. S. Guest House located at 908 & 937, Mantola, Gali Harimandir, Pahar Ganj, New

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other condition mentioned in the gazette notification dated 27.05.2019 & clarification issued dated on 25.09.2019 & 17.12.2020 latest by 31.03.2021.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 10. The owner shall not use any floor above third floor for any purpose and same shall remain closed/locked.

	INSPEC	CTION REPORT
1.	Name & address of the building	M/S G. S Guest House located at 908 & 937, Mantola, Gali Harimandir, Pahar Ganj, New Delhi, Gr+ 4 <sup>th</sup> upper floor
2.	Type of occupancy:-	Residential Group A-1, ground floor – 02 guest rooms + Reception/office, 1 <sup>st</sup> floorto 3 <sup>rd</sup> floor 4 guest rooms at each floor, Total -14 room, fourth floor(servant rooms) not in use as per affidavit 12.10.2019.
3	Type of case:-	Renewal
4	Details of previous FSC:-	No. F6/DFS/MS/GH/2017/NDZ/1055 dated 19/07/17.
5	Fire safety directives No	N/A
6	Date of inspection:-	09.02.2021
7	Name of the inspecting officer:-	Sh. Ravinder Singh (ADO/CC)
8	Name & designation of officer From the building side:-	Mr, Ganesh Agrawal
9	Year of construction:-	2013
10	Applicant's letter No:-	ID NO. 2021011309647dated 13.01.2021

Building is comprised of basement, ground and four upper floors and 4<sup>th</sup> floor not in use as per affidavit dated **12.10.2019** submitted by applicant.

Old case

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	N/A	04 mtr.	N/A
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arrar			
	A. Number of staircases		,	
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	150cms.	150 cms	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits	N/A	N/A	N/A
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	01 mtr.	01 mtr.	MR
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A

1/12

	4) Water curtain	N/A	N/A	N/A
n .	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
7.	1) Basements	N/A	N/A	N/A
	2) Upper floors	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03/21 of compliance extended vide order dt. 17.12.2020
5.	Fire Extinguishers		10 N	MR
	1) Total numbers	08 Nos.	10 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MIK
6.	First-Aid Hose Reel			T/A
	1) Total number at each floor	N/A	N/A	N/A
	2) Length of hose reel hose	N/A	N/A	N/A
	3) Nozzle diameter	N/A	N/A	N/A
7.	Automatic Fire Detection & Ala	arming System		
	1) Type of detectors CO type	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03/21 of compliance extended vide order dt. 17.12.2020
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
		N/A	N/A	N/A
8.	MOEFA Public Address System	N/A	N/A	N/A
9.	Automatic Sprinkler System	11/22		
10.	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants	11/11		
11.	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per floor	N/A	N/A	N/A
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	1 1/1 2		· ·
12.	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
12	Pumping Arrangement			
13.		N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A N/A	N/A	N/A
	g) Stand by pump head h) Auto starting/Manual stopping	N/A N/A	N/A N/A	N/A
	2) Terrace level		7	
	a) Discharge of pump	N/A	N/A	N/A

	b) Head of pump	N/A	N/A	·N/A		
	c) Power supply	N/A	N/A	N/A		
	d) Auto starting of pump	N/A	N/A	N/A		
14.	Captive Water Storage for Fire Fighting					
14.	Under ground tank     capacity	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank capacity	N/A	N/A	N/A		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
	a) Pressurization of lift shat	t N/A	N/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift ca	r N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A	N/A	N/A		
17.	Stand by Power Supply	N/A	N/A	N/A		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system panel	Ņ/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		
20.	Special Fire Protection System any: ABC & CO <sup>2</sup>	N/A				

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2017/NDZ/1055 dated 19/07/17, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only.

Signature of the Inspecting Officer

Name: Ravinder Singh Designation: ADO (CC)

DoceD 12/2 Dych (MO2)

F.M. PI