GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No. F.6/DFS/MS/GH/2021/SZ/ 89

Dated: 1.7./2/.21

FIRE SAFETY CERTIFICATE

Certified that M/s Hira Palace Guest House located at 1010/121, Chauhan Mohalla, Madanpur Khadar, New Delhi-110076, comprised of Ground floor (Reception), 1st floor (06 G/rooms), 2nd floor (05 G/rooms), 3rd floor (05 G/rooms) total 16 G/rooms was granted FSC by this department vide letter No. F.6/DFS/MS/GH/2018/SZ/1449 dated 20/06/2018. The premises was re-inspected by the officer concerned of this department on 22/01/2021 in the presence of Mr. Vivek Kumar and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that premises is fit for occupancy class "Residential (Guest House) Group- A" (FSC renewed for Ground floor (05 G/rooms), 1st floor (08 G/rooms), 2nd floor (08 G/rooms), 3rd Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 17/2/21 at New Delhi by

Copy to: -

1. M/s Hira Palace Guest House located at 1010/121, Chauhan Mohalla, Madanpur Khadar, New Delhi-110076

2. The Joint Commissioner of Police, Licensing Branch, 1st floor P.S. Defence Colony, New Delhi.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

3. All the staff members must know the correct method of operation of fore fighting system.

4. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rule of 2010. The form is available on www.dfs.delhigovt.nic.in.

5. The certificate may not be treated in any case for the regularization (clause 2.8 & UBBL-2016) of the unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if

6. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

	INSP	ECTION REPORT		,		
1	Name & Address of the Building	M/s Hira Palace Guest House, 1010/121, Chauhan Mohalla, Madanpur Khadar, New Delhi-110076				
2	Type of Occupancy	Residential & Lodging, Group-A(Guest House)				
3	Building Comprised of		Ground + 03 Upper floors			
4	Type of Case		Addition/Alteration			
5	Details of Previous NOC	F.6/DFS/MS/GH	I/2018/SZ/1449 dated 20/	06/2018		
6	Fire Safety Directives Letter No		11201010211117 dated 201	00/2016		
7	Date of Inspection	Nil				
8	Name of the Inspecting Officers	22/01/2021				
9		ADO Avtar Singh				
	Name & Designation of Officers from the building side	Mr. Vivek Kumar				
10	Year of construction	Ground floor (05 G/rooms), 1 st floor (0 G/rooms), 2 nd floor (08 G/rooms), 3 rd floor (08 G/rooms) total 29 G/rooms				
11	Applicant letter No.	Application No.	2020102608028 dated 27	/10/2020		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	NBC/BBL Requirements	Provided at Site	Remarks MR/NMR		
1	Access to Building.					
	Road width	09 m	Provided	MR		
	Gate width	-N/A-	-N/A-	-N/A-		
	Width of internal road	-N/A-	-N/A-	-N/A-		
2	Number, width, type & arrangement		-14/A-	-1N/A-		
	a) Number of Staircase					
	> Upper floors	Two	D 111			
	Basement floor		Provided	MR		
	b) Width of Staircase	-N/A-	-N/AN/A			
	> Upper floor	1.05	120 0170			
	> Basement floor	1.25m & 1.50m -N/A-	1.30m & 1.50m (iron)	MR		
	c) Protection of exits	-N/AN/A-		-N/A-		
	Fire check door	Dogwins	D :1.1			
	> Pressurization	Required	Provided	MR		
	d) No. of continuous staircase to	-N/A-	-N/A-	-N/A-		
	terrace	One	One	MR		
	e) Width of corridor	1.0 m 1.80m		MR		
	f) Door size	1.0 m	1.10 m (final exit)	MR		
3	Compartmentation.	1.0 111	1.10 m (mai exit)	IVIK		
	Fire check door.	Required	Provided	MR		
	 Sealing of electrical shafts. 	-N/A-	-N/A-	-N/A-		
	• Fire rating of shaft door.	-N/A-	-N/A-	-N/A-		
	Water curtain	-N/A-	-N/A-	-N/A-		
1	• Fire dampers.	-N/A-	-N/A-	-N/A-		
4.	Smoke Management system. • Basement	20 A CIDIA				
	BasementUpper floors	30 ACPH 12 ACPH	-N/A-	-N/A-		
5.	Fire Extinguishers.	12 ACFH	-N/A-	-N/A-		
	Total numbers	08nos	1400	3.00		
	• Types	ABC/ CO ₂	08Nos	MR		
	ISI Marking	ISI Marked	ABC/ CO ₂ Provided	MR MR		
6.	First Aid Hose Reels.	151 Iviai Keu	riovided	IVIK		
	Total numbers on each floor	01	01	MD		
34	I could be of hear and 1	VI	UI	MR		

7	Automatic fire detection & alarming	system.				
	• Type of detectors	Carbon Monoxide (CO) type	Provided	MR		
	 Location of Main Panel 	-N/A-	-N/A-	-N/A-		
	 Location of Repeater Panel 	-N/A-	-N/A-	-N/A-		
	 Alternate source of power 	-N/A-	-N/A-	-N/A-		
	 Hooter's location 	-N/A-	-N/A-	-N/A-		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	-N/A-	-N/A-	-N/A-		
10.	Automatic Sprinkler System					
10.	Basement	-N/A-	-N/A-	-N/A-		
	Upper floors	-N/A-	-N/A-	-N/A-		
	Sprinkler above false ceiling	-N/A-	-N/A-	-N/A-		
¥	•	-IN/A-	-IN/A-	1 1771		
11.	Internal Hydrants.	27/4	-N/A-	-N/A-		
	Size of Riser / Down-comer	-N/A-				
	Number of Hydrant per floor	-N/A-	-N/A-	-N/A-		
	Hose box.	-N/A-	-N/A-	-N/A-		
12.	Yard Hydrants.	-				
	Total number of hydrants.	-NA-	-NA-	-NA-		
	Hose box.	-NA-	-NA-	-NA-		
13.	Pumping arrangements.					
15.	Ground Level					
	• Ground Level	-N/A-	-N/A-	-N/A-		
	Discharge of main pump.	-N/A-	-N/A-	-N/A-		
	Head of main pump.		-N/A-	-N/A-		
	Number of main pumps.	-N/A-				
	> Jockey Pump output.	-N/A-	-N/A-	-N/A-		
	Jockey Pump head.Standby Pump output.	-N/A-	-N/A-	-N/A-		
	Standby Pump bead.	-N/A-	-N/A-	-N/A-		
	> Auto Starting/Manual	-N/A-	-N/A-	-N/A-		
	Stopping.	-N/A-	-N/A-	-N/A-		
	Pump house access.	-N/A-	-N/A-	-N/A-		
	Terrace LevelDischarge of pump.	450 LPM	450 LPM	MR		
	Head of pump.	40 m	40 m	MR		
	> Power supply.	Required	Provided	MR		
	> Auto starting of pump.	Required	Provided	MR		
14.	Captive water storage for firefighting	ng.				
17.	• Underground tank capacity.	-N/A-	-N/A-	-N/A-		
	Draw-off connection.	-N/A-	-N/A-	-N/A-		
	> Fire Service Inlet.	-N/A-	-N/A-	-N/A-		
	Access to tank.	-N/A-	-N/A-	-N/A-		
	 Overhead tank capacity. 	5,000 ltrs	Provided	MR		
15.	0 0	Required	Provided	MR		
16		-N/A-	-N/A-	-N/A		
	Pressurization of lift labby	-N/A-	-N/A-	-N/A		
	Pressurization of lift lobby.Communication in lift car.	-N/A-	-N/A-	-N/A		
	• Communication in fitt car. • Fireman's switch.	-N/A-	-N/A-	-N/		
1		-N/A-	-N/A-	-N/		
1'	Lift signage.Standby Power Supply	Required	Provided	M		
		Required	11011404			
18		-N/A-	-N/A-	-]		
All las	Total area	-N/A-	-IN/A-			

19.	Fire Control Room.			
	Detector System Panel. Flow Switch Panel. PA system Panel. Battery backup Building floor plan	-N/A-	-N/A-	-N/A-
		-N/A-	-N/A-	-N/A-
		-N/A-	-N/A-	-N/A-
		-N/A-	-N/A-	-N/A-
		-N/A-	-N/A-	-N/A-
20.	Special Fire Protection System for the Protection of special Risk, if any.	-N/A-	-N/A-	-N/A-

The Fire protection systems provided in the premises were checked / operated at random and found functional at the time of inspection.

The condition of the Gazette notification dated 27/05/2019 on mentioned below found complied.

1.	No Kitchen on rooftop/basement.	MR	No Kitchen Provided
	No Storage of inflammable material on rooftop.		No Storage Provided
3.	No temporary roofing over the rooftop.		Not Provided
4.	No Inflammable material of construction in passage/corridor.		Not Provided
5.	Gas Bank, if any		No Gas Bank provided
6.	Carbon Monoxide type Detectors.	MR	Provided
7.	Fire Doors of min. 01 hr. rating	MR	Provided

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F.6/DFS/MS/GH/2018/SZ/1449 dated 20/06/2018, renewal under rule 37 of the Delhi Fire Service rule 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

(If number of occupants more than 10 on each floor)

23/01/2021 Signature of the Inspecting Officer

: Avtar Singh

Designation: ADO (M. Rd)

DO (SD) - This is case of Addition of Rooms.

Competency to dispose off the Cerse is with upprector-