## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2021/ND2 69

Dated: 05 | 02 | 202 |

## FIRE SAFETY CERTIFICATE

Certified that the M/S Kamal Place Guest House located at 3339, Gali Hari Mandir, Pahar Ganj, New Delhi comprised of Ground floor (01 room + Reception), 1st floor to 3rd floor (06 guest rooms at each floor) and 4<sup>th</sup> floor (not in use as per affidavit submitted by applicant), total 19 guest rooms was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2017/NDZ/1066 dated 19/07/17. The premises was re-inspected by the officer concerned of this department on 25/01/21 in the presence of Mr. Manish Kumar and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (01 room + Reception), 1<sup>st</sup> floor to 3rd floor (06 guest rooms at each floor) for 19 guest rooms only with effect from 02 | 02 | 202 | -for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 05 02 12021 at New Delhi by.

(Dr S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

3. The Manager,

- 1. The commissioner, North MCD, : With a request to take n/a as fourth floor is added Civic Centre, New Delhi which was not in existence in last inspection on dt 14.07.17
- 2. The Joint Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID NO. 2020110808368 dated 09.11.2020.

M/S Kamal Place located at 3339, Gali Hari Mandir, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other condition mentioned in the gazette notification dated 27.05.2019 & clarification issued dated on 25.09.2019 & 17.12.2020 latest by 31.03.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its
- 10. The owner shall not use any floor above third floor for any purpose and same shall remain closed/locked.

	INC	PECTION REP	ODT				
	Name & address of the building			1			
1.							
	3339 Gali Hari Mandir Pahar Ganj, New Delhi						
2.							
	Type of occupancy:-  Residential, Sub Division-A-1  Ground floor – Reception and 01 Room,						
	1 <sup>st</sup> floor to 3rd floor (06 guest rooms at each floor)						
	4 <sup>th</sup> floor not in use as per affidavit, total 19						
3.	Type of case:-	guest room:	S.				
4.	Type of case:-  Details of previous FSC:-  Renewal  No. F6/DFS/MS/GH/2017/NDZ/1066 dated						
т.	Details of previous FSC	19/07/17.	S/MS/GH/201 //ND	2/1066 dated			
5.	Fire safety directives No	19/0//1/. N/A					
6.	-	25/01/21					
7.	Name of the inspecting officer:- Sh. Ravinder singh (ADO/CC)						
	Sh. Rajinder Atwal, DO (CD)						
8.	Name & designation of officer	on. Rajine	iei Atwai , DO (CD				
	From the building side:- Mr. Manish Kumar						
9.	Year of construction:-						
	Applicant's letter No:-		020110808368 dated	109.11.2020			
				*			
Buildi	ng is comprised of ground and for	our upper floors	and 4 <sup>th</sup> floor not in	use as per			
affidav	it submitted by applicant.						
G N I			*	Old Case			
S.No.	Minimum Standards on fire	Requirement/	Provided at site	Remarks			
	Prevention and fire safety	Existing fire safety		MR/NMR			
	U/R 33	arrangements					
1.	Access to Building	-		а			
	1) Road width	N/A	03 mtr.	N/A			
	2) Gate width	N/A	N/A	N/A			
	3)Width of internal road	N/A	N/A	N/A			
2.	Number, Width Type & Arrangement of Exits						
	A. Number of staircases						
	1. Upper floors	01 Nos.	01 Nos.	MR			
	2. Basements	N/A	N/A	N/A			
	B. Width of staircase						
	1. Upper floors	0.80 mtr.	.83 mtr.	MR			
	2. Basements	N/A	N/A	N/A			
	C. Protection of exits						
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous	01	01	MR			
	staircase to terrace						
	E. Width of corridor	N/A	N/A	N/A			
	F. Door size	01 mtr.	01 mtr.	01 mtr.			
3.	Compartmentation						
	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System	1					
	1) Basements	30 ACPH	N/A	N/A			
	/						

	2) Upper floors	12 ACPH	Natural	MR
5.	Fire Extinguishers			
	1) Total numbers	12 Nos.	14 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			
	1) Total number at each floor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	Alarming Syst	em	
	1) Type of detectors	Required as per G.N dated 27.05.19	Not provided	Last dt. of compliance extended vide order dt. 17.12.2020
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
0 ,	MOEFA	N/A	Provided	N/A
8.	Public Address System	N/A	N/A	N/A
9.	Automatic Sprinkler System		11/11	4
10.	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants	i)		
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor		•	
	3) Hose box	N/A -	N/A	N/A
12.	Yard Hydrants			
14.	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
13.	1) Ground level	N/A	N/A	N/A
	a) Discharge of main pump	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pu		N/A	N/A
	d) Jockey pump out pu	1	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump out		N/A	N/A
	0 11 1		N/A	N/A
	b) Stand by pump hear h) Auto starting/Manustopping		N/A	N/A
	2) Terrace level			
		450 LPM	450 LPM	MR
	a) Discharge of pump			MR.

		*				
	a) Discharge of pump	450 LPM	450,LPM	MR		
	b) Head of pump	30 mtr.	30 mtr.	MR		
	c) Power supply	Required	Provided	MR		
	d) Auto starting of pump	Required	Provided	MR		
14.	Captive Water Storage for Fire Fighting					
	Under ground tank capacity	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	Required	Provided	MR		
	d) Over head tank capacity	5,000 ltr.	5,000 ltr.*	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
œ	a) Pressurization of lift shaft	N/A	N/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A	N/A	N/A		
17.	Stand by Power Supply	Required	Provided	MR		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		
20.	Special Fire Protection Sys Risk, if any: ABC & CO <sup>2</sup>	tem for Prote	ction of special	MR		

The fire protection systems provided in the building were randomly tested,

checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2017/NDZ/1066 dated 19/07/17, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only.

ignature of the inspecting officer

wa.

Name: - Rajinder Atwal Designation: - DO (CD)

Name: Ravinger Singh Designation: ADO (CC)

Signature of the Inspecting Officer

Dycho (moz)