GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2021/ NO2/67

Dated :-- 4/2/21

FIRE SAFETY CERTIFICATE

Issued ------at New Delhi by.

(Dr. S.K Tomar) Dy. Chief Fire Officer Ph. No. 011-23412025

0x19mm

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi ID NO. 2021012009792 dated 20.01.2021.
- 2. The Manager, Kiran Guest House located at 4473-75, Main Bazar, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other condition mentioned in the gazette notification dated 27.05.2019 & clarification issued dated on 25.09.2019 & 17.12.2020 latest by 31.03.2021.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

3. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.

9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

10. The owner shall not use any floor above third floor for any purpose and same shall remain

closed/locked.

		Name & address of the building	Kiran Guest	House located at	4473-74-75,		
			Main Bazar,	Pahar Ganj, New	Delhi		
1	2.	Type of occupancy:-	Residential, Sub Division-A-1				
				r floors (total 08 Gu			
			Ground floor (S	Shop), 1 st floor (02 gu	est rooms +		
			reception), 2 nd	to 3rd floor (03 guest	rooms at each		
			20.12.2020).	th floor (not in use as	s per affidavit dt		
	3	Type of case:-	Renewal				
		Details of previous FSC:-		/MS/GH/2017/12	14 dated		
	т.	Details of previous 1 Se	14/08/17.	/WIS/OH/2017/12	1 + dated		
	5	Fire safety directives No	N/A				
		Date of inspection:-	28/01/21				
	7.	Name of the inspecting officer:- Sh. Ravinder Singh (ADO/CC) Sh. Rajinder Atwal (DO/CD)					
	7.						
	8	Name & designation of officer					
	0.	From the building side:-	Mr. Mubara	k (Manager)			
	9	Year of construction:-	1982	(
		Applicant's letter No:-	12009792 dated 2	92 dated 20.01.2021.			
	10.	rippiream s retter 1.0.	10110.20210				
					Old Case		
	S.No.	Minimum Standards on fire	Requirement/	Provided at site	Remarks		
		Prevention and fire safety U/R 33	Existing fire		MR/NMR		
			safety		9 9 9		
-	1	A goos to Ruilding	arrangements				
	1.	Access to Building	N. 1. 1.	00	NAID.		
		1) Road width	N/A	09 mtr.	MR		
		2) Gate width	N/A	N/A	N/A		
		3)Width of internal road	N/A	N/A	N/A		
	2.	Number, Width Type & Arra	angement of Ex	its	2		
		A. Number of staircases					
		1. Upper floors	01 Nos.	01 Nos.	MR		
		2. Basements	N/A	N/A	N/A		
		B. Width of staircase					
		1. Upper floors	0.80 mtr.	1.05 mtr.	MR		
		2. Basements	N/A	N/A	N/A		
		C. Protection of exits			100		
		1. Fire check door	N/A	N/A	N/A		
		2. Pressurization	N/A	N/A	N/A		
		D. No. of continuous	01	01	MR		
		staircase to terrace					
		E. Width of corridor	1.0 mtr.	1.0 mtr.	MR		
		F. Door size	1.0 mtr.	1.0 mtr.	MR		
	3.	Compartmentation	d	8 g			
		1) Fire check door	N/A	N/A	N/A		
		2) Sealing of electrical shafts	N/A	N/A	- N/A		
-		3) Fire rating of shaft door	N/A	N/A	N/A		
		4) Water curtain	N/A	N/A	N/A		
		5) Fire Dampers	N/A	N/A	N/A		
	4.	Smoke Management System	×				
	4.	1) Basements	30 ACPH	N/A	N/A		
		2) Upper floors	12 ACPH	Natural	MR		
	_		12710171	*			
	5.	Fire Extinguishers 1) Total numbers	08 Nos.	10 Nos.	MR		
			ABC & CO2	ABC & CO2	MR		
		2) Types	Required	Provided	MR		
MANAGEMENT OF STREET		3) ISI marking	Required	110 1100			
	6.	First-Aid Hose Reel	N/A	01	N/A		
-		1) Total number of eachfloor		30 mtr.	N/A		
		2) Length of hose reel hose	N/A	05 mm	N/A		
		3) Nozzle diameter	N/A				
	7.	Automatic Fire Detection &	Alarming Syst	NI/A	N/A		

0.	MODIA	IN/ FA	IN/A	IN/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A.
	3) Sprinkler above false	N/A	N/A	N/A
2	ceiling			
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor			11/11
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	1 1/2 1	11/11	TWA.
12.	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement	IN/A	IN/A	1N/A
13.		NI/A	NI/A	2//
		N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level			
	a) Discharge of pump	N/A	180 LPM	N/A
	b) Head of pump	N/A	30 mtr.	N'A
		N/A	Provided	N/A
	c) Power supply			N/A
	d) Auto starting of pump	N/A	Provided	IV/A
14.	Captive Water Storage for Fi		NI/A	N/A
	1) Under ground tank	N/A	N/A	N/A
	capacity		27/4	27/4
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity		1500 ltr.	N/A
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift	N/A	N/A	. N/A
	shaft			
	b) Pressurization of lift	N/A	N/A	N/A
	lobby	A 3/ A &		
	c) Communication in lift	N/A	N/A	N/A
		1 1/11	1 1/1 1	
	d) Fireman's switch	N/A	N/A	N/A
	,	N/A N/A	N/A	N/A
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	*		N/A
18.	Refuge Area	N/A	N/A	
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	1	N/A	N/A	N/A
	a) Detector system panel	IN/A	1 N/ / 1	1 1/11
		NI/A	NI/A	N/A
	b) Flow switch panel	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A

Mhs

20. Special Fire Protection System for Protection of special MR Risk, if any: ABC & CO₂.

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2017/1214 dated 14/08/17, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the inspecting officer

Signature of the Inspecting Officer

Name: - Rajinder Atwal Designation: - DO (CD)

Name: Ravinder Singh Designation: ADO (CC)

DOCCO)

As approved for pertup forker penulan