GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/GH/SZ/2021/

Dated: 23 \ 02 \ 2021

FIRE SAFETY CERTIFICATE

Certified that M/s. Hotel Indraprastha located at 17A/54, WEA, Karol Bagh, New Delhi- 110005 comprised of basement (storage), ground floor (reception & 03 guest rooms), first floor (06 guest room), second floor (06 guest rooms) and third floor (03 guest rooms) and a pantry for staff (total 18 guest rooms) was granted FSC by this department vide letter No. F.6/DFS/MS/GH/SZ/2017/1254 dated 22.08.2017. The premises was re-inspected by the officer concerned of this department on 17.02.2021 in presence of Sh. Rakesh Sharma, manager of the guest house and found that deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class group-A, residential (guest house) for Basement (Storage), Ground floor (03 guest rooms), 1st & 2nd floor each have 06 guest rooms, 3rd floor (03 guest rooms) total 18 guest rooms only with effect from 33 02 2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued $\frac{23}{2}$ 22 at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to:-

- 1. The Manager, M/s. Hotel Indraprastha, 17A/54, WEA, Karol Bagh, New Delhi- 110005.
- 2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

Following Fire Safety Directives must be adhered to: -

- 1. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 10. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

1. Name & address of the building . W/s Hotel indiaplastila located at 17A/54, WEA, Kalol Bagh, New Delhi- 110005 2. Type of Occupancy : Lodging House : Renewal 3. Type of Case 4. Details of previous NOC : F.6/DFS/MS/GH/SZ/2017/1254 dated 22.08.2017 5. Fire Safety directives letter No : N/A. 6. Date of inspection : 17.02.2021 7. Name of the Inspecting Officer: P.V. Rathee, Asstt. Div. Officer (SRD) 8. Name and designation of officers from the building side : Sh. Rakesh Sharma, Manager 9. Year of Construction : 2000-01 10. Applicant's letter No. : Online Email Id ajaymadan@slf.in dated 02.02.2021 The said guest house is comprised of basement, ground plus three upper floors. S. Minimum Standards on fire Requirement as Remarks per FSC dt.-Provided at site No. prevention and fire safety U/R 33 MR/NMR 21.08.2014 1 Access to building Road width 06 mts Provided MR 05 mts Directly accessible Gate width MR N/A N/A Width of internal road N/A 2 Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 01 Provided MR being old case Basements 01 Provided MR being old case b. Width of staircases Upper Floors Old case 1.18 mts MR being old case Basements MR being old case Old case 1.25 mts c. Protection of exits date of compliance has been Required Not Provided Fire check door extended up to 31.03.2021 Pressurization N/A N/A N/A e. No. of continuous staircases to 01 01 MR terrace 1.25 mts 2.30 mts MR g. Width of Corridor Old case Provided (0.88 mt.) MR being old case h. Door Size 3 Compartmentation. date of compliance has been Fire check door Required Not Provided extended up to 31.03.2021 Sealing of electrical shafts Sealed Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4 Smoke Management System. Basements 30 a/c per hour Exhaust fan provided MR 12 a/c per hour Natural ventilation Upper floors MR 5 Fire Extinguishers Total numbers 14 Provided MR CO₂, ABC type Types Provided MR ISI marked IS marking Provided MR

	Total numbers on each floor	01	Provided		MR 🔵			
	 Length of hose reel hose 	30 m	Provided		MR			
	Nozzle diameter	5 mm	Provided		MR			
7	Automatic fire detection and alarming system.							
	Type of detectors	Carbon Monoxide	Not Provided		ompliance has been d up to 31.03.2021			
	• Location of Main Panel	Required	Not Provided		ompliance has been d up to 31.03.2021			
	• Location of Repeater Panel	N/A	N/A		N/A			
	Alternate source of power	N/A	N/A	_	N/A			
	Hooters' Location	N/A	N/A		N/A			
8	MOEFA	Required	Provided	-	MR			
9	Public Address System.	Required	Provided		MR			
10	Automatic Sprinkler System.	tomatic Sprinkler System.						
	Basement	Required	Provided		MR			
	 Upper Floor 	N/A	N/A		N/A			
	 Sprinkler above false ceiling 	N/A	N/A		N/A			
11	Internal Hydrants							
_	Size of riser/down-comer	N/A	N/A		N/A			
	 Number of hydrants per floor 	N/A	N/A		N/A			
	Hose Box	N/A	N/A		N/A			
12	Yard Hydrants.							
	Total number of hydrants	N/A	N/A		N/A			
	Hose Box	N/A	N/A	1	N/A			
13	Pumping Arrangements.							
	Ground Level							
	Discharge of main Pump	N/A	N/A		N/A			
	Head of Main pump	N/A	N/A		N/A			
	Number of main pumps	N/A	N/A		N/A			
	Jockey Pump out put	N/A	N/A		N/A			
	Jockey pump headStandby Pump out put	N/A	N/A		N/A			
	Standby Pump out putStandby Pump Head	N/A	N/A		N/A			
×	Auto Starting/ Manual stopping	N/A	N/A		N/A			
*,	> Pump House Access	N/A	N/A		N/A			
	Terrace level	N/A	N/A		N/A			
	Discharge of pump	450 LPM	Provided		MR			
•	Head of the pump	30 mts	Provided		MR			
	Power Supply	Required	Provided		MR			
	Auto Starting of pump	Required	Provided	7154	MR			
14	Captive Water Storage for fire fighting	Captive Water Storage for fire fighting.						
	Underground tank capacity	N/A	N/A		N/A			
	> Draw-off connection	. N/A	N/A		N/A			
	Fire service inlet	N/A	N/A		N/A			
	Access to tank	N/A	N/A		N/A			

				N/26				
16	Pro	vision of Lifts.						
	•	Pressurization of Lift Shaft	N/A	N/A	N/A			
	•	Pressurization of Lift lobby	N/A	N/A	N/A			
	•	Communication In lift Car	N/A	N/A	N/A			
	•	Fireman's Grounding Switch	N/A	N/A	N/A			
	•	Lift Signage	N/A	N/A	N/A			
17	Stan	dby power supply	Required	Provided (D.G. set 82.5 KVA)	MR			
18	Refu	fuge Area.						
	3	Total Area	N/A	N/A	N/A			
	7	Location	N/A	N/A	N/A			
19	Fire	e Control Room						
		Detector System Panel	N/A	N/A	N/A			
		Flow Switch Panel	N/A	N/A	N/A			
		PA System Panel	N/A	N/A	N/A			
		Batter backup	N/A	N/A	N/A			
		Building Floor Plans	N/A	N/A	N/A			
20	_	ial Fire Protection Systems for ection of special Risks, if any:	Required	Two ABC type fire extinguisher found	MR			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The management has given an undertaking not to use any occupancy above third floor & basement as storage purpose.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/SZ/2017/1254 dated 22.08.2017, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer Name P.V. Rathee

provided near elect, panel

Asstt. Div. Officer (SRD)

18/02/2021

यम ८०० (९२)

F.t. please