GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE **NEW DELHI- 110001** Dated: 22/02/2021

No.F.6/DFS/MS/2021/SZ/

FIRE SAFETY CERTIFICATE

Certified that the M/s RCube Mall, (RCube Projects Pvt. Ltd.,) Janak Puri East Metro Station, P.B. area New Delhi-110058, comprised of ground plus first floor, owned/occupied by M/s RCube Projects Pvt. Ltd. have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and verified by the officer concerned of this department on 07/02/2021 in the presence of Mr. Sujeet Singh (Manager) and found that the building is fit for occupancy 'Group D "Assembly Building" with effect from 29 82 201 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below.

at New Delhi by

Director

Delhi Fire Officer Ole (A

To,

The Manager, M/s RCube Mall, (RCube Projects Pvt. Ltd.,) Janak Puri East Metro Station, P.B. area New Delhi-110058

Following fire safety directives must be adhered to:-

- The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J° [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- All the means of escape shall be kept free of all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

M/s RCube Mall, Janak Puri East Metro Station, P.B. area Name & address of the building: New Delhi-110058 Building comprised of Ground plus one upper floor Assembly Type of Occupancy Type of Case New 5. Details of Previous NOC Nil 6. Fire Safety directives letter No: Nil : 07/02/2021 Date of inspection 8. Name of Inspecting Officer : A.D.O.R.K.Yadav & DO D.B.Mukharjee 9. Name and designation of officers From the building side : Sh. Sujeet Singh (Manager) : 2006 10. Year of Construction 11. Applicant's letter No. : Nil dated 23/12/2020 Requirement Provided at Remarks Minimum Standards on fire prevention and S. MR/NMR site No. fire safety U/R 33 Access to building 1. M/R Accessible 18 mtrs Road width Open to road M/R Gate width 05 mtrs. N/A Width of internal road N/A N/A Number, Width, Type & Arrangement of Exits 2. a. Number of staircases Upper Floors M/R 02 No's 02 No's Basements N/A N/A N/A Width of staircases M/R Upper Floor 1.5 m 1.5 m Basements N/A N/A N/A Protection of exits N/A N/A N/A Fire check door Pressurization N/A N/A N/A d. No. of continuous staircases to N/A N/A N/A terrace M/R 1.5 m 1.5 m Width of Corridor f. Door Size M/R 2 m 2 m Compartmentation 3. Required Provided M/R Fire check door Sealed M/R Sealing of electrical shafts Required Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. **Smoke Management System** N/A N/A N/A Basements M/R Required Natural Upper floors ventilation **Fire Extinguishers** 5. 10 no.'s Provided M/R Total numbers ABC/CO₂ type Provided M/R Types IS marking M/R ISI marked ISI marked (One common staircase 4 M width passing through ground to concourse level)

6.	First-Aid Hose Reels (Specially for RCube but fu	nction of DMRC sy	stem)			
	Total numbers on each floor	2 no.	Provided	M/R	11	
	• Length of hose reel hose	30 m	Provided	M/R		
7	Nozzle diameter Automotic five detection and clarming system	5 mm	Provided	M/R	-	
7.	Automatic fire detection and alarming system	Required	Provided	M/R	-	
	Type of detectors (smoke/Heat)Location of Main Panel	N/A	Ground floor	N/A		
	Location of Repeater Panel	N/A				
	Alternate source of power	Required	N/A	N/A		
	 Hooters' Location 	Required	Provided Provided	M/R		
		·	Provided	M/R M/R		
3.	MOEFA	Required	Provided	M/R		
9.	Public Address System	Required	Provided	IVI/K		
LO.	Automatic Sprinkler System	NI/A	NI/A	N/A	_	
	BasementGround Floor	N/A	N/A	N/A		
	 Ground Floor Sprinkler above false ceiling	N/A	N/A		_	
		N/A	N/A	N/A	4	
l1.						
	Size of riser/down-comer	100 mm	Provided	M/R		
	 Number of hydrants per floor 	2 no.	Provided	M/R		
	Hose Box	2 no.	Provided	M/R		
2.	3	on for DMRC				
	Total number of hydrants	Required	Provided	M/R		
	Hose Box	Required	Provided	M/R		
13.		for DMRC				
	Ground Level					
	Discharge of main Pump	1800 LPM	Provided	MR		
	➤ Head of Main pump	40 mtrs	Provided	MR	2.5	
	Number of main pumps	01 no	Provided	MR		
	Jockey Pump out put	180 LPM	Provided	MR	12.1	
	Jockey pump head	40 mtrs	Provided	MR	,	
	> Standby Pump out put	1800 LPM	Provided	MR		
	Standby Pump Head	40 mtrs	Provided	MR		
	> Auto Starting/Manual Stopping	Required	Provided	MR		
		N/A	N/A	N/A		
	> Pump House Access					
	Terrace level	N/A	N/A	N/A		
	➤ Discharge of pump	N/A	N/A	N/A		
	Head of the pump	N/A	N/A	N/A	. 5	
	> Power Supply	N/A	N/A	N/A	, A	
	> Auto Starting of pump	IV/A	11//	A CONTRACTOR OF THE	A	
1.1	Captive Water Storage for fire fighting	Common for I	DMRC	and the same of th		
14.	Underground tank capacity	50000 ltrs	100000 ltrs	M/R		
	 Underground tank capacity Draw-off connection 	Required	Provided	M/R		
	> Fire service inlet	Required	Provided	M/R		
	> Access to tank	Required	Provided	M/R		
	Overhead Tank capacity	Required	Provided	. M/R	N. Z.	
		Required	Provided	M/R	45	
15.	Exit Signage.	neganea	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			

MIT

	21/0	N/A
N/A	N/A	
N/A	N/A	N/A
N/A	N/A	N/A
Required	d Provided	M/R
Require		M/R
Require		M/R
Require	d Hovidas	
	21/0	N/A
N/A	N/A	
N/A	N/A	N/A
N/A	N/A	N/A
N/A	N/A	N/A
	N/A	N/A
N/A		
N/A	N/A	N/A
N/A	N/A	N/A
tion of N/A	N/A	N/A
	ion of N/A	ion of 19/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of Inspecting Officer

Name - R.K.Yadav

Designation:- Asstt.Divisional Officer

Signature of Inspecting Officer

Name:-D.B.Makharjee

Designation:- Divisional Officer

mg / 1/13/2,1

APH

1/40