GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2021/ | 06

Dated: 24/2/21

FIRE SAFETY CERTIFICATE

Certified that M/s. Hotel Golden Grand (A unit of Sukhmani Inns Pvt. Ltd.) located at W-1/10, Main Patel Road, West Patel Nagar, New Delhi- 110008 comprised of basement, stilt, ground plus three upper floors, using basement as storage, stilt as parking, ground floor as main reception, kitchen with eating/dining facility & offices, first, second and third floor each having 11guest rooms respectively (total 33 guest rooms) was granted FSC by this department vide letter No.F6/DFS/MS/GH/SZ/2018/164 dated 24.01.2018. The premises was re-inspected by the officer concerned of this department on 02.02.2021 in presence of Sh. Gurpreet Singh, Owner/Occupier of the guest house and found that deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for Basement (Storage), Stilt (Parking), ground floor (reception & office without Kitchen), first, second & third floor each having 11 guest rooms receptively (total 33guest rooms) with effect from 24/2/21 for valid up to 31.03.2021 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued 24/2/2) at New Delhi by.

(Sunil Chaudhary) Dy. Chief Fire Officer (SZ)

Copy to:-

- 1. The Owner/Occupier, M/s. Hotel Golden Grand, W-1/10, Main Patel Road, West Patel Nagar, New Delhi- 110008.
- 2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

Conditions for the Validity of Fire Safety Certificate

- 1. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053- 65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 10. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

1. Name & address of the building : M/s. Hotel Golden Grand, W-1/10, Main Patel Road, West Patel Nagar, New Delhi- 110008 2. Type of Occupancy : Lodging House 3. Building Composition : Basement (Storage), Stilt (Parking), Ground floor (Reception), First, Second & Third floor Each having 11 guest rooms respectively (without kitchen). 4. Type of Case : Renewal 5. Details of previous NOC : F6/DFS/MS/GH/SZ/2018/164 dated 24.01.2018 6. Fire Safety directives letter No : Nil 7. Date of inspection : 02.02.2021 8. Name of the Inspecting Officers : P.V. Rathee, Asstt. Division Officer (SRD) 9. Name and designation of officers from the building side : Sh. Gurpreet Singh, Owner/Occupier 9. Year of Construction : Building plan sanctioned vide letter no. 132/B/ HQ/2009/D/255 / AE (B) HQ dt. 08.02.2010. 10. Applicant's letter No. : Online Application ID 2020122209147 dated 06.01.2021 S. Fire safety Minimum Standards on fire Provided at site Remarks arrangements as No. prevention and fire safety U/R 33 per Noc dt. MR/NMR 24.01.2018 1 Access to building Road width 06 mts Provided MR Gate width ----Directly accessible MR Width of internal road N/A N/A N/A Number, Width, Type & Arrangement of Exits 2 a. Number of staircases Upper Floors 01 01 MR Basements 02 02 MR b. Width of staircases Upper Floors 1.25 mts. 1.50 mts MR Basements 1.25 mts each 1.55, 1.50 mts MR c. Protection of exits date of compliance has been Fire check door Required Not Provided extended up to 31.03.2021 Pressurization N/A N/A N/A e. No. of continuous staircases to 01 01 terrace MR N/A g. Width of Corridor N/A N/A h. Door Size Old case 0.90 mts MR being old case 3 Compartmentation. date of compliance has been Fire check door Required Restt. Area is not segregated extended up to 31.03.2021 from guest house area (NMR) Sealing of electrical shafts Required Sealed MR Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4 Smoke Management System. Basements 30 a/c per hour Exhaust fan provided MR Upper floors 12 a/c per hour Natural Ventilation MR

	• Total numbers	20)	Dnovid	- 1		9				
	• Types	CO ₂ , ABC	, WCO ₂	Provided Provided		MF					
	IS marking	ISI ma	irked			MF					
(First-Aid Hose Reels.			Provid	ed	MF	{				
	 Total numbers on each floor 	01		Provide	ad	MR					
	 Length of hose reel hose 		30 m		Provided						
	 Nozzle diameter 	5 mr		Provided		MR					
7	Automatic fire detection and alarm	ning system		TTOVIDED		MR					
	• Type of detectors	Carbon Mo	noxide	Not Provided	extend	compliance has ed up to 31.03.2	2021				
	• Location of Main Panel	Required		Not Provided date of		compliance has been ded up to 31.03.2021					
	• Location of Repeater Panel	N/A		N/A	CXICITA	N/A	2021				
	Alternate source of power	Requir	ed	D.G. set 200 KVA		MR					
8	Hooters' Location MOEFA	N/A		N/A		N/A					
9	Control Contro	Requir		Provided		MR					
10	Public Address System.	Require	ed	Provided		MR					
	Automatic Sprinkler System. • Basement						0				
		Require	ed	Provided	i	MR	. 2				
	opper rittor	N/A		Provided	l		12				
11	• Sprinkler above false ceiling	N/A		N/A		N/A	-				
11	Internal Hydrants					11/12					
	• Size of riser/down-comer	N/A		100 mm		- <u>- 1</u>					
	Number of hydrants per floor	N/A		01							
12	Hose Box Vord H. J.	N/A		01							
12	Yard Hydrants.		-	,		V					
	• Total number of hydrants	N/A		01							
13	Hose Box	N/A		01							
13	- amping Arrangements.										
	• Ground Level Discharge of main Pump										
	- somarge of main fullip	N/A		N/A	and the second	N/A					
	Head of Main pumpNumber of main pumps	N/A		N/A		N/A					
	Jockey Pump out put	N/A		N/A		N/A					
	Jockey pump head	N/A		N/A		N/A					
	Standby Pump out put	N/A		N/A		N/A					
	Standby Pump Head	N/A		N/A		N/A N/A N/A					
	Auto Starting/ Manual stoppi	N/A		N/A							
	Pump House Access	11/21		N/A							
	Terrace level	N/A		N/A		N/A					
	Discharge of pump) /								
	Head of the pump	900 LP 30 mts		900, 220 LPN	1	MR					
	Power Supply	Require		30 mts each		MR					
	Auto Starting of pump	Require		Provided Provided		MR					
14				riovided		MR					
	• Underground took correct										
	Underground tank capacityDraw-off connection	N/A		N/A		N/A					
	Fire service inlet	N/A		N/A		N/A					
	Access to tank	N/A		Provided							
	Overhead Tank capacity	N/A		N/A		N/A	7				
1.5	- Tank capacity	15,000 lts		15 000 lts		MD					

16	Provision of Lifts.						
	 Pressurization of Lift Shaft 	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	Required	Provided	MR			
	Fireman's Grounding Switch	Required	Provided	MR			
	Lift Signage	Required	Provided	MR			
17	Standby power supply	Required	Provided				
18	Refuge Area.	Tiovided	MR				
	Total Area	N/A	N/A	N/A			
	> Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	Provided				
	• Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	Required	Provided	MR			
	Battery backup	Required	Provided	MR			
0	Building Floor Plans	N/A	N/A	N/A			
0	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. Fire safety certificate was issued vide letter no. F6/DFS/MS/GH/SZ/2018/164 dated 24.01.2018 renewal under rule 35 of the Delhi Fire Sarvice rule 2010 is recommended without kitchen at ground floor.

Accordingly DFA has been prepared & put up for signature please

Dy efo (SZ).

Signature of the Inspecting Officer Name P.V. Rathee

Asstt. Div. Officer (SRD)