GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/NDZ/2021/94

Dated: 18/02/2021

FIRE SAFETY CERTIFICATE

Certified that the M/s Metro Guest House, 639, Churiwalan, Jama Masjid, Delhi-06, comprised of Ground + 03 upper floors: Ground floor - commercial use, 1st floor - 06 guest rooms, 2nd floor -06 guest rooms, 3rd floor - 04 guest rooms total 16 guest rooms was granted FSC by this department vide letter no. F6/DFS/MS/GH//NDZ/2018/924 dated 04.05.2018. The building/premises was re-inspected by Assistant Divisional Officer (SPM) from this department on 12.02.2021 in presence of owner Md. Hafiz Akram Zamal and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of "Group A-1 (Residential)" for total 16 guest rooms (1st floor - 06 guest rooms, 2nd floor - 06 guest rooms, 3rd accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on 18 02 2021 at New Delhi by

(Dr. S.K. Tomar)

Dy. Chief Fire Officer

Tel: 011-23412025

CIC Ala

Copy to:-

1. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi

2. The Licensee, M/s Metro Guest House, 639, Churiwalan, Jama Masjid, Delhi-06

Condition for the validity of fire safety certificate

- This clearance/FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 and any violation of clarification issued on 25.09.2019 & 17.12.2020 latest by 31.03.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry". Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained there to before occupancy of the same.

	N. O. dd	NOI ECTION KETOKI	7		
1	Name & address of the building	M/s Metro Guest	House, 639, Chur	iwalan, Jama	
2	Duilding is seen in 1 C	Masjid, Delhi-06			
	Building is comprised of	Ground + 03 upper f	loors 16 guest rooms	5	
		(1 st floor – 06 guest r	ooms, 2 nd floor -06 g	uest rooms, 3 rd	
		floor – 04 guest room			
		Ground floor – comm	ercial use		
		1 st floor – 06 guest roo	ms + reception + 01 s	store room	
		2 nd floor – 12 rooms (04 store rooms)	06 guest rooms + 0	2 staff rooms +	
.			0.4		
		3 rd floor – 17 rooms (04 guest rooms + 13 rooms owner's personal use)			
3	Type of Occupancy	Residential Group A-1	,	2 2 2	
4	Type of Case	Renewal		2 2 0	
5	Details of Previous FSC	F6/DFS/MS/GH//NDZ/	/2018/024 datad 04 04	5 2010	
6	Fire Safety direction letter No	Nil	2016/924 dated 04.0.	0.2018	
7	Date of Inspection	12.02.2021			
8	Name of the Inspecting Officers	Rajesh Kumar Shukla A	ADO (SPM)	*	
9	Name of the designation of Officer	Manager	ibo (STIVI)	, i i i i i i i i i i i i i i i i i i i	
	from the building side				
10	Year of Construction	old			
11	Applicant's letter No	Online I.D No. 2021020	0210099 dated 04 02	2021	
S.N	Standards on mi	e Requirement/ Existing	Provided at Site	Remarks	
	Prevention and fire safety			MR/NMR	
200	requirements U/R 33	arrangements	9		
1	Access to building	10 m			
	Road width	05 m	05 m	MR	
	Gate width	NA	NA	NA .	
2	Width of internal road	NA	NA	NA	
2	Number, Width, Type and Arra A. Number of Staircases	ingement of Exits			
	Upper Floor	01			
	Basement	01 no.	01 no.	MR	
	B. Width of Staircases	IVA .	NA	NA	
	Upper Floor	80 cms	96 to 112 cms	MR	
	Basement	NA	NA NA	NA NA	
	C. Protection of exits	A : 2			
	Fire check door	(required as per point no. x	Not Provided	Last date of	
		of GN dated 27.05.2019)	2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	compliance	
	4		b 1	extended till	
			*	31.03.2021	
				vide order	
		* e 20		dated 17.12.2020	
	Pressurization	NA	NA	NA NA	
	D. No. of continuous staircases to terrace	NA	NA	NA	
	E. Width of Corridor	NA	NIA		
	G. Door size	1 m	NA	NA	
3	Compartmentation	1 III	1 m	MR	
	Fire check door	NA	NA	NIA	
	Sealing of electrical shafts	NA	NA	NA NA	
	Fire rating of shaft door	NA	NA	NA NA	
	Water curtain .	NA	NA	NA	
4	Fire Dampers	NA	NA	NA	
4	Smoke Management System.				
	Basement	30a/cper hour	NA	NA	
	Upper floor	(required as per point no. ix of GN dated 27.05.2019)	Not Provided	Last date of	
		or, dated 27.05.2019)	A STATE OF THE STA	compliance extended till	

5.	Fire Extinguisher					
8 8	Total numbers	06 no.	10 no.	MR		
	types.	CO ₂ & ABC	CO ₂ & ABC	MR		
	IS marking	ISI marked	ISI marked	MR		
6	First-aid-Hose Reels.					
	Total numbers of each floor	2 no.	02	MR		
	Length of hose reel hose	30 m	30 m	MR		
	Nozzle diameter	5 mm	5 mm	MR		
7	Automatic fire detection and alarming s	vstem.	2			
	Type of detectors	CO detectors (required as per point no. viii of GN dated 27.05.2019)	Not Provided	Last date of compliance extended till 31.03.2021 vide order dated 17.12.2020		
	Location of main panel	NA	NA	NA		
	Location of repeater panel	NA .	NA	NA		
	Alternate source of power	NA	NA	NA		
	Hooters	NA	NA	NA NA		
8	MOEFA	NA	NA	NA		
9	Public address System.	Required	Provided	MR		
10	Automatic Sprinkler System.			Taxa .		
10	basement	NA	Provided	NA		
	upper floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
11	Internal Hydrants					
	size of riser/down-comer	NA	NA	NA		
	Number of hydrants per floor	NA	NA	NA		
	Hose Box	NA	NA	NA		
12	Yard Hydrants.					
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA ·	NA	NA		
13	Pumping Arrangements.		/ -	3 3 3		
13	Ground Level					
	Discharge of main Pump	NA	NA	NA		
	> Head of Main Pump	NA	NA	NA		
	Number of main pumps	NA	NA	NA		
	> Jockey pump out put	NA	NA	NA		
		NA	NA	NA		
	Jockey pump headStandby pump out put	NA	NA NA	NA		
	Standby pump Head	NA	NA	NA		
	> Auto Starting /Manual stopping	NA	NA	NA		
•	> Pump House Access	NA	NA	NA		
	Terrace Level	2				
	Discharge of pump	225 LPM	225 LPM	MR		
	> Head of the Pump	40 m	40 m	MR		
	> Power supply	Required	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR		



14	Captive Water Storage for Fire Fighting.				
	Underground tank capacity	NA	NA	100 100 III 100	
	Draw-off connection	NA	NA	NA	
	Fire service inlet	NA	NA	NA	
	Access to tank	NA	NA	NA	
	Overhead Tank capacity	2500 ltrs	2500 ltrs	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.				
	Pressurization of Lift Shaft	NA	NA	NA	
	Pressurization of Lift lobby	NA	NA	NA	
	Communication in lift car	NA	NA	NA	
	Firemen's grounding switch	NA	NA	NA	
	Lift Signage	NA	NA	ŅA	
17	Standby power supply	Required	Provided	MR	
18	Refuge Area.				
7	Total area	N.A	N.A	N.A	
•	Location	N.A	N.A	N.A	
19	Fire Control Room				
	Detector system panel	NA	NA	NA	
	Flow switch panel	NA	NA	NA	
	PA system panel	NA	NA	NA	
	Batter backup	NA	NA .	NA	
	Building Floor Plans	NA NA	NA	NA	
20	Special Fire Protection systems for protection of special		NA	NA	
	Risks, if any:		- 10		

The guest house had been initially issued FSC for 36 guest rooms vide letter no. F6/MS/DFS/GH/08/2770 dated 01/10/08 which was later converted to 16 guest rooms in FSC issued vide letter no. F6/DFS/MS/GH/2015/NDZ/309 dated 05/03/15 onwards. During the inspection dated 12.02.2021 it was noticed that the existing extra rooms (rooms other than 16 guest rooms as mentioned in the previous FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/924 dated 04/05/2018) are being used by the owner for other purposes. Owner has also submitted an affidavit regarding floor wise occupancy of the premises also stating that there has been no addition alteration in the building ever since the Guest house is running in the building.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/GH//NDZ/2018/924 dated 04.05.2018 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

16/2/21

Signature of the Inspecting Officer

Name

Rajesh Kumar Shukla

Designation

ADO (SPM)

DO (CD)

16/2

04) 12/1/11