## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/NDZ/2021/ 97

Dated: 18/2/2/

## FIRE SAFETY CERTIFICATE

Certified that the M/s Mustafa Guest House, located at 3933, Urdu Bazar, Jama Masjid, Delhi, comprised of Ground + 04 upper floors: Ground floor- reception + 03 guest rooms, 1st floor- 01 Hall, 2<sup>nd</sup> floor - 02 guest rooms, 3<sup>rd</sup> floor - 02 guest rooms, 4<sup>th</sup> floor - 01 guest rooms (not in use) total 08 guest rooms and 01 Hall was granted FSC by this department vide letter no. F6/DFS/MS/GH/2017/NDZ/1532 dated 24.10.2017. The building/premises was re-inspected by Assistant Divisional Officer (SPM) from this department on 11.02.2021 in presence of Manager, and found that the owner had demolished the 5<sup>th</sup> floor and now the building is comprised of ground + 04 upper floors: ground floor- reception + office + 02 guest rooms, 1<sup>st</sup> floor - 01 Hall + 02 stores, 2<sup>nd</sup> floor - 02 guest rooms + 02 stores, 3<sup>rd</sup> floor -02 guest rooms + 02 stores, 4<sup>th</sup> floor -not in use (closed). The building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. The owner has submitted an affidavit dated 12.12.2019 not to use any floor above third floor for any purpose in accordance with Gazette Notification dated 27.05.2019 and its subsequent clarification dated 25.09.2019.. Accordingly, the premises is fit for occupancy of "Group A-1 (Residential)" for total 06 guest rooms + 01 Hall (Ground floor - reception + 02 guest rooms, 1st floor - 01 Hall, 2<sup>nd</sup> floor - 02 guest rooms, 3<sup>rd</sup> floor - 02 guest rooms) only, with effect from for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below. 0×10m6

(Dr. S.K. Tomar) Dy. Chief Fire Officer Tel: 011-23412025

ok 18/2

Copy to:-

The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi

2. The Licensee, M/s Mustafa Guest House, located at 3933, Urdu Bazar, Jama Masjid, Delhi

## Condition for the validity of fire safety certificate

- 1. This clearance/FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 and any violation of clarification issued on 25.09.2019 & 17.12.2020 latest by 31.03.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry". Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained there to before occupancy of the same.

		ECTION REPORT	A 8		
		M/s Mustafa Guest House, located at 3933, Urdu Bazar, Jama Masjid, Delhi Ground + 04 upper floors			
•					
		<b>Ground floor</b> - reception + 02 guest rooms + 01 office			
		1 <sup>st</sup> floor – 01 Hall			
-	T	2 <sup>nd</sup> floor - 02 guest rooms			
25		3 <sup>rd</sup> floor - 02 guest rooms + 01 store			
		4 <sup>th</sup> floor – 01 guest rooms (not in use)			
	T	Residential Group A-1		*N	
3	Type of Occupancy	Renewal			
4	Type of Case				
5	Details of Previous FSC	F6/DFS/MS/GH/2017/NDZ/1532 dated 24.10.2017			
6	Fire Safety direction letter No	Nil			
7	Date of Inspection	11.02.2021			
8	Name of the Inspecting Officers	Rajesh Kumar Shukla ADO (SPM)			
9	Name of the designation of Officer	Manager	2		
	from the building side	· · · · · · · · · · · · · · · · · · ·			
10	Year of Construction	1993		× ×	
10.	- Control of the Cont	Online application I.D.202	1012209831 dated 2	27.01.2021	
11	Applicant's letter No	Requirement/ Existing	Provided at Site	Remarks	
S.N		-	1 Tovided at Site	MR/NM	
	Prevention and fire safety	fire safety		MINITAL	
	requirements U/R 33	arrangements		1 1 N 1 N	
1.	Access to building	Y A CONTRACTOR OF THE PARTY OF	Will State of the		
	Road width	NA	02 m	MR	
	Gate width	NA	NA	NA	
	Width of internal road	NA	NA	NA	
2	Number, Width, Type and Arran	gement of Exits		8	
_	A. Number of Staircases	0 =			
	Upper Floor	01 no.	01 no.	MR	
	Basement	NA	NA	NA	
	B. Width of Staircases				
	Upper Floor	80 cms	98 cms	MR	
	Basement	NA	NA	NA	
	C. Protection of exits			* N	
	Fire check door	(Required as per GN dated 27.05.2019)	Not Provided	Last date compliant extended till 31.03.202 vide order	
	* * * * * * * * * * * * * * * * * * * *	and the second s	, a a	dated	
			w "	17.12.202	
	Pressurization	NA	NA	NA	
	D. No. of continuous staircases to terrace	NA	NA	NA	
	E. Width of Corridor	NA *	NA	NA	
5	G. Door size	1 m	1 m	MR	
2		* ***	8=	26	
3	Compartmentation	NA	NA	NA	
	Fire check door	NA NA	NA .	NA	
	Sealing of electrical shafts		NA NA	NA	
	Fire rating of shaft door	NA	NA NA	NA .	
	Water curtain	NA	NA NA	NA NA	
	Fire Dampers	NA	INA	INA	
4	Smoke Management System.		1 374	NIA	
	Basement	30a/cper hour	NA	NA Leat data	
	Upper floor	(Required as per GN dated 27.05.2019)	Not Provided	Last date complian extended	

5.	Fire Extinguisher	IV a t	8			
13	Total numbers	10 no.	10 no.	MR		
	types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR		
	IS marking	Required	ISI marked	MR		
6	First-aid-Hose Reels.					
	Total numbers of each floor	NA	01 no. at 1 <sup>st</sup> floor	NA		
	Length of hose reel hose	NA	30 m	NA		
	Nozzle diameter	NA	5 mm	NA		
7	Automatic fire detection and alarming	system.				
	Type of detectors	CO detectors (required as per GN dated 27.05.2019)	Not Provided	Last date of compliance extended till 31.03.2021 vide order dated 17.12.2020		
	Location of main panel	NA	NA	NA		
	Location of repeater panel	NA	NA	NA		
	Alternate source of power	NA	NA	NA		
0	Hooters	NA	NA	NA NA		
8	MOEFA	NA	NA	NA		
9	Public address System.	Required	Provided	MR		
10	Automatic Sprinkler System.		Taxa	1274		
	basement	NA	NA	NA		
	upper floor	NA .	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
11	Internal Hydrants					
	size of riser/down-comer	NA	NA	NA		
	Number of hydrants per floor	NA	NA	NA		
	Hose Box	NA	NA	NA		
12	Yard Hydrants.					
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA		
13	Pumping Arrangements.					
15	Ground Level					
	> Discharge of main Pump	NA	NA	NA		
	➤ Head of Main Pump	NA	NA	NA		
	> Number of main pumps	NA	NA	NA		
	> Jockey pump out put	NIA	NA	NA		
	<ul><li>Jockey pump out put</li><li>Jockey pump head</li></ul>	NA .	NA	NA NA		
	<ul><li>Jockey pump nead</li><li>Standby pump out put</li></ul>	NA NA	NA NA	NA NA		
	Standby pump Head	NA	NA	NA		
	> Auto Starting /Manual stopping	NA	NA	NA		
	> Pump House Access	NA	NA	NA		
	Terrace Level	e , a a *		-		
	Discharge of pump	NA	225 LPM	NA		
	➤ Head of the Pump	NA	40 m	NA		
	> Power supply	NA	Provided	NA		
	> Auto Starting of pump	NA	NA	NA		



14	Captive Water Storage for Fire Fighti	Captive Water Storage for Fire Fighting.				
	Underground tank capacity	NA	NA	NA		
	Draw-off connection	NA	NA	NA		
	Fire service inlet	NA	NA	NA		
	Access to tank	NA	NA	NA		
	Overhead Tank capacity	NA	2,500 ltrs	NA		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	NA	NA	NA		
	Pressurization of Lift lobby	NA	NA	NA		
	Communication in lift car	NA	NA	NA		
	Firemen's grounding switch	NA	NA	NA		
	Lift Signage	NA	NA	NA		
17	Standby power supply	NA a	Provided	NA		
18	Refuge Area.					
	Total area	N.A	N.A	N.A		
	Location	N.A	N.A	N.A		
19	Fire Control Room					
	Detector system panel	NA	NA	NA		
	Flow switch panel	NA	NA	NA		
	PA system panel	NA	NA	NA		
	Batter backup	NA	NA	NA		
	Building Floor Plans	NA	NA	NA		
20	Special Fire Protection systems for protection of special Risks, if any:		NA	NA		

The height of the building as submitted by North Delhi Municipal Corporation vide letter no. EE(B)-II/ CSPZ/2020/D-1313 dated 14.01.2020 was 16.95 meters for ground + 5 upper floors. During the inspection dated 11.02.2021 it was found that the owner had demolished the 5<sup>th</sup> floor and now the building is comprised of ground + 4 upper floors for which the previous FSC dated 24.10.2017 had been granted.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

The owner has submitted an affidavit on 28.12.2019 not to use any floor above third floor for any purpose in accordance with Gazette Notification dated 27.05.2019 and its subsequent clarification dated 25.09.2019.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/GH/2017/NDZ/1532 dated 24.10.2017 only upto 3<sup>rd</sup> floor is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Dla 12121

Signature of the Inspecting Officer

Name

Rajesh Kumar Shukla

Designation ADO (SPM)

DO (CD)

Dycho CMD22