

FORM 'H'
FORM FOR ISSUING FIRE SAFETY CERTIFICATE
[Refer sub - rule (1) of rule 35]
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

No: F6/DFS/MS/Instt./SZ/03 NEW DELHI
FIRE SAFETY CERTIFICATE

Dated: 01/03/2021

Certified that the building of Fair Field Institute of Management & Technology, FIMT Campus, Plot No-1037/1, Kapashera, New Delhi-110037 comprised of Basement, Ground & Four Upper floors (03 Blocks) & Basement, Ground & One Upper Floor (01 Block) but Institute is running on Basement, Ground & Three Upper Floors (03 Blocks) & Basement, Ground & One Upper Floor Only (01 Block) owned / Occupied Fair Field Institute of Management & Technology, has already been issued fire safety certificate vide letter no. F6/DFS/MS/Instt./2018/SZ/454 dated 19/03/2018. The premises was re - inspected by the officer from this department on dated 12/02/2021 in the presence of Sh. Vijay Bhardwaj and observed that all the fire prevention & fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy class "Educational" Group-B, with effect from 01/03/2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 01/03/2021 at New Delhi.


(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER (S.Z.).

Copy to:-

1. Authorized Signatory, Fair Field Institute of Management & Technology, FIMT Campus, Plot No-1037/1, Kapashera, New Delhi-110037.

Conditions for the validity of Fire Safety Certificate:

1. The 4th floor is sealed and will not be used for any purpose. As per the undertaking submitted by building owner dated 20/02/2020.
2. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
3. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
4. The trained fire fighting staff should be available round the clock.
5. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
8. There shall not be more than 45 students in class rooms in any case.

2. Type of Occupancy : **Educational**
 3. Building comprised of : Basement, Ground & Four Upper floors (03 Blocks) & Basement, Ground & One Upper Floor (01 Block) **but Institute is running on Basement, Ground & Three Upper Floors (03 Blocks) & Basement, Ground & One Upper Floor Only (01 Block) (4 th floor sealed by the owner)**
 4. Type of Case : **Renewal**
 5. Details of previous NOC : **F6/DFS/MS/Instt./2018/SZ/454 dated 19/03/2018**
 6. Fire Safety directives Letter No. : **F6/DFS/MS/BP/2011/2933 dated 09/11/2011**
 7. Date of inspection : **12/02/2021**
 8. Name of the Inspecting Officer : **A.D.O. (S.J.)**
 9. Name and designation of Officer from the building side : **Sh. Vijay Bhardwaj**
 10. Year of Construction : **2012**
 11. Applicant's letter No. outdoor diary No. 10473 dated 18/01/2021

S No	Minimum standards on fire prevention and fire safety U/R 33	NBC Requirements	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	Required	9 m	MR
	• Gate width	Required	5 m	MR
	• Width of internal road	N/A	N/A	N/A
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	A.Bk-01, B.Bk-02, C.Bk-02 & Cafeteria Bk-02	A.Bk-01, B.Bk-03, C.Bk-02 & Cafeteria Bk-02	MR
	• Basements	A.Bk-01, B.Bk-02, C.Bk-02 & Cafeteria Bk-02	A.Bk-01, B.Bk-02, C.Bk-02 & Cafeteria Bk-02+one ramp for A & B Bk	MR
	b. Width of staircases			
	• Upper floors	1.50m / 0.90m	A & B Bk-1.5, 1.7, 1.27 & 1m, C.Bk-1.5 & 1.4m, Cafeteria Bk-1.5m & 1.0m	MR
	• Basements	1.50m / 0.90m	A.Bk-1.27m & 1.7m ramp, B.Bk-1.5m, 1m & ramp common, C.Bk-1.5m & 1.4m, Cafeteria Bk-1.5m & 1m	MR
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	N/A	N/A	N/A
	d. No of continuous staircase to terrace	Required	1 each block	MR
	e. Width Of Corridor	1.50mtr	1.50 mtr	MR
	f. Door Size	1 mtr	1 mtr	MR
3.	Compartmentation			
	• Fire check door	Required	Provided	MR
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke managements System			
	• Basements	Required	Exhaust fan Provided	MR
	• Upper floors	N/A	N/A	N/A
5.	Fire Extinguishers			
	• Total numbers	36	40	MR

	• Total numbers on each floor	1	1	MR
	• Length of hose reel hose	30 mtr	30 mtr	MR
	• Nozzle diameter	5 mm	5 mm	MR
7.	Automatic fire detection and alarming system			
	• Type of detector	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater	N/A	N/A	N/A
	• Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	• Basements	Required	Provided	M/R
	• Upper Floor	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	• Size of riser/down-comer	N/A	100 mm	N/A
	• Number of hydrants per floor	N/A	1	N/A
	• Hose Box	N/A	1	N/A
12.	Yard Hydrants			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	• Ground Level			
	• Discharge of main pump	2280 LPM	2280 LPM	MR
	➤ Head of main pump	40 m	40 m	MR
	➤ Number of main pumps	1	1	MR
	➤ Jockey pump out put	180 LPM	180 LPM x 2	N/A
	➤ Jockey pump head	40 m	40 m	N/A
	➤ Standby Pump out put	2280 LPM	2850 LPM	N/A
	➤ Standby Pump Head	40 m	40 m	N/A
	➤ Auto Staring/Manual stopping	Required	Provided	MR
	➤ Pump House Access	Required	Provided	MR
	• Terrace level	One in two Block	Provided	MR
	➤ Discharge of pump	900 LPM	900 LPM	MR
	➤ Head of the pump	40MH	40MH	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting			
	• Underground tank capacity	50,000ltr	Provided	MR
	➤ Draw of connection	N/A	N/A	N/A
	➤ Fire service inlet	Required	Provided	MR

15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	N/A	N/A	N/A
	➤ Pressurization of lift lobby	N/A	N/A	N/A
	➤ Communication in lift Car	N/A	N/A	N/A
	➤ Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire control room			
	➤ Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Battery backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A

Note:- As per the undertaking submitted by building owner dated 20/02/2020, in Block A&B, 4th Floor is existing since 2011 as per the MCD record dated 28/05/2014 (C/20-21) and the same is sealed by the owner since beginning and will not be de-sealed or used for any purpose until the same is regularized by concerned authorities.

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC already issued vide letter No. **F6/DFS/MS/Instt./2018/SZ/454** dated 19/03/2018 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

[Signature]
22/02/2021

Signature of the Inspecting Officer
Name : A.K. Jaiswal
Designation: A.D.O. (S.J.)

Pt. spk about uptaking & mcd records.

DO(SD)

Limf
23/02

ADO(SJ)

*spoken to constly D.O.
I) Undertaking of sealing is placed at c/20 & c/21 by Bldg. owner. II) 4th floor is existing since beginning of School/Institute Bldg. and same was not mentioned earlier. III) Proof of 4th floor is placed at c/21 (MCD property tax slip of year 2014.*

[Signature]
24/02/2021

DO(SD)

Limf
25/02

F.T.