GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/GH/2021/SZ/ 113

Dated: 26/.02/2021

FIRE SAFETY CERTIFICATE

Certified that M/s Hotel R. S. Residency Guest House located at Plot No A-151 /152, Road No 4, Street No 9, Mahipalpur Extension, New Delhi - 110037, comprised of Lower Ground Floor, Upper Ground Floor & 1st Floor (others Property), 2nd Floor (11 Guest Room), 3rd Floor (11 Guest Room) Total 22 Guest Rooms, was already been issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/2018/SZ/81 dated 11/01/2018. The premise was reinspected by the officer concerned of this department on 17/02/2021 in the presence of Sh. Ritesh Sehrawat and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential & Lodging, Group-A" (Guest House) with effect from the date of issue 26/02/2021 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on 26/02/21 at New Delhi by

(Sunil Chawdhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to: -

- 1. The Manager, M/s Hotel R. S. Residency Guest House located at Plot No A-151 /152, Road No 4, Street No 9, Mahipalpur Extension, New Delhi 110037.
- 2. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi–110049

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."
- 7. The provision's under clause 7.31 of UBBL-2016 shall be done in the building on or before 31/03/2021 in compliance to the notification dated 27/05/2019 an as approved and extended the deadline for compliance time limit by the Hon'ble Minister (UD) vide letter No F5 (189)/AD/ LB/2016/710-725 dated 17/12/2020

	INSPECTION REPORT						
1	Name &	& address of the building : M/s Hotel R. S. Residency, Plot No – A- 151 & 152, Street No- 9,					
			Road, No 4, Mahipalpur Extn. New Delhi-110037.				
2	Туре о	Occupancy .Re	Residential (Group- A) Guest House				
3	Type of	Case : Re	: Renewal (Lower ground, upper ground plus 03 upper floors)				
4	Details	of previous NOC : F6	: F6/DFS/MS/GH/2018/SZ/81 dated :11.01.2018				
5	Fire Sa	fety directives letter No : NI	: NBC Part- IV				
6	Date of	inspection : 17	: 17.02.2021				
7	Name o	of the Inspecting Officers : Al	DO (E	BCP) Rajesh Kumar			
8	Name a	nd designation of officers : Sl	Sh. Ritesh Sehrawat				
	from th	m the building side					
9.	Year of C	Construction : 2011					
10	. Applicar	cant's letter No. : Online No 202101040988 Dated: 06.01.2021					
	Minim	um Standards on fire prevention and fire safety U/R 33	on	NBC BBL Requirement	Provided at site	Remarks MR/NMR	
1	Access to	building					
	• [Road width		06m	06m	MR	
	• (Gate width		NA	NA	NA	
		Width of internal road		NA	NA	NA	
2	Number	Width, Type & Arrangement of Exits					
	a Numb	er of staircases	T				
		Jpper Floors		91	01	MR	
		Basements		NA	NA	NA	
		of staircases					
		Upper Floors		1.25m	1.45- 1.50 m	MR	
		Basements		NA	NA	NA	
		tion of exits					
		Fire check door		Required	Provided	MR	
		Pressurization		NA	NA	NA	
		f continuous staircases to terrace		01	01	MR	
		of Corridor		NA	NA	NA	
	f. Door S			1m	1.40 m (final exit)	MR	
3	Compai	tmentation.					
	•	Fire check door		NA -	NA	NA	
	•	Sealing of electrical shafts		NA	NA	NA	
	•	Fire Rating of shaft door		NA	NA	NA	
	•	Water Curtain		NA	NA	NA	
	•	Fire Dampers		NA	NA	NA	
4	Smoke	Management System.					
	•	Basements		30 a/c per hour	NA	NA	
	•	Upper floors		12 a/c per hour	NA	NA	

	Dute Dixinguisment						
	Total numbers	06nos	08nos	MR			
	• Types	ABC & Co2	06- ABC & 02- Co2	MR			
	ISI marking	Yes	Yes	MR			
6	First-Aid Hose Reels.			-			
	Total numbers on each floor	01	01	· MR			
	Length of hose reel hose	30 m	30 m	MR			
	Nozzle diameter	5mm	5mm	MR			
	Automatic fire detection and alarming system. Circular date17/12/2020 amendment / modification in (UBBL-2016 till 31/03/2021)						
	Type of detectors	Required	Provided	MR			
	Location of Main Panel	NA	NA	NA			
	Location of Repeater Panel	NA	NA	NA			
and the state of t	Alternate source of power	NA	NA	NA			
	Hooters' Location	NA	NA	NA			
8	MOEFA	Required	Provided	MR			
	Public Address System.	NA	NA	NA			
	Automatic Sprinkler System.						
	• Basement	NA	NA	NA			
	Upper Floor	NA	NA	NA			
	Sprinkler above false ceiling	NA	NA	NA			
11	Internal Hydrants						
	Size of riser/down-comer	NA	NA	NA			
	Number of hydrants per floor	NA	NA	NA			
	Hose Box	NA	NA	NA			
12	Yard Hydrants.						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
13	Pumping Arrangements.						
	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	> Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head	N/A	N/A	N/A			
	Auto Starting/ Manual stoppingPump House Access	N/A	N/A	N/A			
	Terrace level						
	> Discharge of pump	450LPM	450LPM	MR			
	> Head of the pump	30m	30m /	MR			
	> Power Supply	Required	Provided	MR			

1			> Auto Starting of pump	Required	Provided	MR		
-	14	Captive	Water Storage for fire fighting.					
and the second second second		• [Inderground tank capacity	NA	NA	NA		
		> I	Draw-off connection	NA	NA	NA		
-		> I	ire service inlet	NA	NA	NA		
-		> 1	Access to tank	NA	NA	NA		
and other particular special section of		• (Overhead Tank capacity	5,000 ltr	10,000ltr	MR		
-	15	Exit Sign	nage.	Required	Provided	MR.		
-	16	Provision of Lifts.						
- Contraction of the Contraction		• I	ressurization of Lift Shaft	N/A	N/A	N/A		
and an incommendation		• 1	ressurization of Lift lobby	N/A	N/A	N/A		
		• (Communication In lift Car	NA	NA	NA		
		• 1	ireman's Grounding Switch	NA	NA	NA		
and the same of th		• 1	Lift Signage	NA	NA	NA		
	17	Standby	power supply	Required	Provided	MR		
-	18	8 Refuge Area.						
		> :	Total Area	N/A	N/A	N/A		
-		> 1	ocation	Ň/Ă	N/A	N/A		
-	19	9 Fire Control Room						
Sparing transmission discuss		-	Detector System Panel	N/A	N/A	N/A		
-		•	Flow Switch Panel	N/A	N/A	N/A		
		•	PA System Panel	N/A	N/A	N/A		
			Batter backup	N/A	N/A	N/A		
		•	Building Floor Plans	N/A	N/A	N/A		
	20		Fire Protection Systems for n of special Risks, if any:	NA	NA	NA		

The fire protection system provided in the premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/GH/2018/SZ/81 dated 11/01/2018, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: - Rajesh Kumar Designation: - ADO/BCP

22/12

Defin Colon