

No.F6/DFS/MS/EH/2021/WZ/5/

Dated: 02 | 03 | 2021

FIRE SAFETY CERTIFICATE

Property No. 3, Ground Floor, Vaishali Enclave, Pitampura, Delhi-110088, in a building comprised of Basement + Ground + 03 upper Floor, owned/occupied by M/s. Imly (A unit of Green Leaf Hospitality) complied with the fire prevention & fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010, and verified by the officer concerned of this department on 22.02.2021 in the presence of Sh. Banta Singh (Manager) and that the building/Premises is fit for occupancy "Assembly Group-D" with effect from D2 03 2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on 02 03 2021 at New Delhi by

(A**b**il Garg)
Director
Delhi Fire Service

gc

This NOC is Valid only for ground floor..

Copy to:-

- 1. The Addl. Commissioner of Police, Licensing unit, 1st Floor, Police Station Defense Colony, New Delhi.
- 2. The Deputy Health Officer, Keshav Puram Zone, NDMC, Public Health Department, A-1 Block, Keshav Puram Zone, Delhi.
- 3. Sh. Balvinder Singh, M/s. Imly Resraurant, Property No.3, Ground Floor, Vaishali Enclave, Pitampura, Delhi-110088.

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time. It should not bolted /locked.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any loss of life any property due to the non-functional of any fire safety measures, management shall be held responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

Bunil Blatin)

		O LOTION KET OF					
1	Name & address of the building M/s. IMLY (A Unit of Freen Leaf Hospitality) located at						
		No.3, Ground Floor	Vaishali Enclave , Pritam Pura,	Delhi-1100			
2	Type of Occupancy	Assembly D (D)					
3	Type of occupancy Type of case		Assembly D (Restaurant)				
4		New					
-	Details of previous NOC	Nil					
5	Fire safety directives letter No	UBBL/NBC					
6	Date of inspection	22.02.2021					
7	Name of the inspecting Officers :	Satpal Bhardwaj ADO (WP)					
8	Name and designation of officers						
9	from the building side Year of construction	2015					
10	Applicant's letter No.						
10	Applicant's letter No.	Online application no. 2019120900830 dated 10.02.2021					
	Under Consideration	The said restaurant is ruuning at Ground floor of the building					
	onder consideration	comprised of Basement Ground plus 3 upper floors) Covered area 173 Sqm.					
S. NO.	Minimum Standards on fire						
0. 140.	prevention and fire safety U/R 33	Requirements	Provided at site	Remarks			
1	Access to building	requirements		MR / NMF			
•	1) Road width	6 m					
	2) Gate width	4.5 Mtrs.	Provided	MR			
	Width of internal road	4.5 Mitrs.	Direct accessible from road	MR			
	Number, width Type &	IN/A	N/A	N/A			
2	arrangement of exits						
	a. Number of staircases						
	1. Upper floors	N/A	N/A	NA ·			
	2. basements	N/A	NA	N/A			
	b. Width of staircase						
	1. Upper floors	N/A	N/A	N/A			
	2. basements	N/A	N/A	N/A			
	c. Protection of exits						
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircase to	N/A	N/A				
	terrace	14// 1	N/A	N/A			
	e. Width of corridor	NA	NA	NA			
	f. Door size	2 Mtrs. & 1.5 Mtrs.	Provided	MR			
3	Compartmentation.			T WIT			
	Fire check door	N/A	N/A	N/A			
	2. Sealing of electrical shafts	N/A	N/A	N/A			
	3. Fire Rating of shaft door	N/A	N/A	N/A			
	4. water curtain	NA	N/A	NA			
	5. Fire dampers	N/A	N/A	N/A			
4	Smoke Management system.						
_	basement	30 a/c per hour	N/A	N/A			
	upper floors	12 a/c per hour	Provided	MR			
5	Fire Extinguishers						
	total numbers	2 Nos.	Provided	MR			
	Types	CO2 & ABC	Provided	MR			
	ISI marking	Required	Provided	MR			
6	First-Aid Hose Reels.		*				
	total numbers on each floor	One	Provided	MR			
	Length of Hose reel hose	30 Mtrs.	Provided	MR			
	Nozzle Diameter Automatic fire detection and alarming	5 mm	Provided	MR			
7	system.						
	Type of detectors	N/A	Provided	A1/4			
			Provided	N/A			
	location of Main Panel	N/A	GF	N/A			
	location of Repeater panel	NA N/A	N/A	NA			
	Alternate source of power	N/A	Provided	N/A			
	hooter's location	N/A	Near exit	N/A			
	MOEFA	Required	Provided	MR			
9	Public Address System.	NA	N/A	NA			

10	Automatic Sprinkler System.			
	basement	NA	N1/0	
	upper floors	N/A	N/A N/A	NA
	sprinkler above false ceiling	N/A	N/A N/A	N/A
11	Internal Hydrants	1,77	IN/A	N/A
	Size of riser/down-corner	100 mm	Provided	MD
-	Number of Hydrants per floor	1	Provided	MR
40	hose Box	Required	Provided	MR
12	Tara riyarants.		. Totada	MR
	total number of hydrants	NA	N/A	NIA
	hose box	NA	N/A	NA
13	Pumping arrangements			NA NA
	1. Ground level	N/A		
	a. Discharge of main Pump	NA	NIA	
	b.Head of main pump	NA	N/A	NA
	c.Number of main pumps	NA	N/A	NA
	d.jockey pump out put		N/A	NA
	e.jockey pump head	NA	N/A	NA
	f. Standby Pump output	NA	N/A	NA
	g.Stanby Pump head	NA	N/A	NA
	h.Auto Starting/Manual stopping	NA	N/A	NA
	I. pump house access	NA	N/A	NA
	2.Terrace level	NA	N/A	- NA
	a. Discharge of pump		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1.
		450 LPM	900 LPM	MR
	b. head of the pump	40 Mtrs.	Provided	
	c. Power supply	Required	Provided	MR
	d. Auto starting of pump	Required	Provided	MR
14	Captive water storage for fire fighting			
	Underground tank capacity			
	a. Draw-off connection	N/A	N/A	N/A
	b. fire service inlet	NA NA	N/A	N/A
		N/A	Proided	N/A
	c.Access to tank	Required	Provided	MR
15	Over head tank Capacity	20000 Ltrs.	Provided	MR
16	Exit Signage. Provision of lifts.	Required	Provided	MR
10				1 1011 (
17	a. Pressurization of lift shaft b. pressurization of lift lobby	NA	NA	NA
	c. communication in lift car	NA NA	NA	NA
	d. Fireman's grounding switch	NA NA	NA	NA
	e. Lift signage	NA NA	NA	NA
		NA	NA	NA
18	Standby power supply Refuge Area.	Required	Provided	MR
	total area	A LA		
	location	NA	NA	NA
19		NA	NA	NA
	Fire control room			
	a. Detector system Panel	NA	NA	NA
	b. Flow switch Panel	NA	NA	NA
	c. PA system Panel	NA	NA	NA
	d. Battery backup	NA	NA	NA
* _{Ka}	e. Building floor plans	NA	NA	NA
	Special Fig. D. (1)			
20	Special Fire Protection System for	Required	ABC Fire extinguisher provided	MR
	Protection of special Risks, if any: ction systems provided in the building v		noor alastria I	

e Protection systems provided in the building were checked and found functional at the time of inspecton. The Shortcomings vide letter no. F6/DFS/MS/EH/2020/WZ/68 dated 03.02.2021 found rectified.

Keeping in View of the substantial compliance of the minimum standards on fire prevention and fire safety requirments under the rules, grant of FSC is recommended under the rules 35 of the Delhi Fire Service Rules, 2010 and under the DES Act 2007 Accordingly DFA is put up for approval please.

S P Bhardwaj ADO WP