GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/

/2021/SZ/ \ 5°

Dated: .9. / 2021

FIRE SAFETY CERTIFICATE

of Basement, Ground + 02 upper floor was jointly inspected by the officers concerned of this department on 02/03/2021 along with Sh. Sunny Raman (JE/SDMC) in the presence of Mr. Sunil Bhatnagar (VP/PVR) and observed that the said building/premises have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly Building, Group-D" with effect from 05/02 /2021 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 05/63 /2021 at New Delhi by

Director Delhi Fire Service

Copy to: -

- 1. The Executive Engineer (Bldg) HQ, S.D.M.C, 9th Floor, Civic Centre, Minto Road, New Delhi–110002 (Online Request ID: 10072586 dated 26/02/2021)
- 2. Mr. Sunil Bhatnagar (VP/PVR), P. No. 61, Basant Lok, Vasant Vihar, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The Owner/Occupier shall apply FSC for Cinema/Restaurants separately to this department.
- 6. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010.
- 7. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

Z	Name & Address of the Building M/s PVR Priy	M/s PVR Priya Cinema at P. No	M/s PVR Priya Cinema at P. No. 61, Basant	
-		Assembly "Group-D"	-D" (Cinema)	
+		Beenment Ground + 02 upper floors	+ 02 upper floors	
1	prised of	A 14:tion/Alteration		
-		Addition Assessment		
-		1111 T C (C) C (S)	11/102/2020	0
	ves Letter No	F.6/DF3/M3/2020	חווחו משכם דיים	
I	Date of Inspection	02/03/2021	(D/D/ O/ A / A / A / A / A / A / A / A / A /	
_	Name of the Inspecting Officers	DCFO (SZ), DO (ADO (DO	Chail
_		Mr. Sunny Raman	(JE/SDIMC) &	
	from the building side	Bhatnagar (VP/PVK)	(K)	
10	Year of construction	2020	1000,000,00	
<u> </u>	Applicant letter No.	Online ID: 10072:	77	-
_	ds		Provided at Site Re	Kemarks
No.	and Fire Safety U/R 33	Requirement	TIMI	VINIVIV
	Access to Building.			9,
	 Road width 	9m	9m	MIK
	Gate width	em	Provided	MR
	Width of internal road	N/A	N/A	N/A
7	Number, width, type and arrangements of exits.	of exits.	-	
	a. Number of Staircase			
	Upper floors	2 Nos	2 + 1 Spiral (FF–SF)	MR
	Basement floor	2 Nos	2 + 1 Exit	MR
	b. Width of Staircase			
	Upper floors	2m x 2nos	GF to Terrace: 2m x 2	MR
			+	+
	Bacement floor	1.4m, 2m & 1.5m (Pump room)	1 1.4m, 1.5m & 2m (Direct exit)	MIK
	Distortion of exite			
	Fire check door	Required	Provided	MR
		N/A	N/A	N/A
	Pressurization		X7/X7	X7/X1
	d. No. of continuous staircase to terrace	Required	2 Nos	MR
	e. Width of corridor	N/A	N/A	N/A
	f. Door size /Exits	2m	Provided	MR
8	Compartmentation.			
	Fire check door.	Required	Provided	MR
	• Sealing of electrical shafts.	Required	Provided	MR
	• Fire rating of shaft door.	Required	Provided	MR
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	Z/Z
4	Smoke Management system.			
:	Basement	Required	Provided	MR
	• Upper floors	Required	Provided	MR
u	Dire Evtinguishers			
6	Total numbers	20 Nos	30 Nos	MR
	Types	ABC/CO ₂	ABC & CO ₂	MR
		ISI marked	Provided	MR
	• ISI Marking	131 Illained	ponto!!	TIME
9	First Aid Hose Reels.	14.0	2010	W.
	 Total numbers on each floor. 	SON 7	SONI 7	MINI
	 Length of hose-reel hose. 	30m	30m	MK
			Smm	

7	Automatic Fire Detection and Alarming sy	Smoke / Heat	Provided	MR
	Type of detectors		Provided	MR
	 Location of Main Panel 	Required	N/A	N/A
	 Location of Repeater Panel 	N/A	Provided	MR
	Alternate source of power	Required	Provided	MR
	Hooter's location	All floors	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Tiovided	
10.	Automatic Sprinkler System		Davidad	MR
	Basement	Required	Provided	MR
		Required	Provided	MR
	Upper floors	Required	Provided	IVIIC
	Sprinkler above false ceiling			
11.	Internal Hydrants.		1.50	MR
	Size of Riser/Down-comer	Required	150 mm	
	Number of Hydrant per floor	Required	Two	MR
	Hose box.	Required	Two	MR
12.	Yard Hydrants.	-	,	
12.	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
-10				
13.	Pumping arrangements.			
	Ground Level	2280 LPM	2850 LPM	MR
	Discharge of main pump.	70m	70m	MR
	Head of main pump.Number of main pumps.	One	Two	MR
	> Jockey Pump output.	180 LPM	180 LPM	MR
	> Jockey Pump head.	70m	70m	MR
	> Standby Pump output.	2280 LPM	2280 LPM :	MR.
	Standby Pump head.	70m	70m	MR
	Auto Starting/Manual Stopping.	Required	Provided * *	MR
	Pump house access	Required	Provided '	MR
	Terrace Level			2 t, - 1
	Discharge of pump.	900 LPM	Provided	· MR
	> Head of pump.	35m	Provided	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for Fire Fighting			
	Underground tank capacity.	2,00,000 Ltrs	2,00,000 Ltrs	MR
	> Draw-off connection.	Required	Provided	MR
	Fire Service Inlet.	Required	Provided	MR
	· > Access to tank.	Required	Provided	MR
	 Overhead tank capacity. 	20,000 Ltrs	20,000 Ltrs	MR
15.		Required	Provided	MR
16.	0 0			
10.	Pressurization of lift shaft.	Required	Provided	MR
	 Pressurization of lift lobby. 	Required	Provided	MR
	• Communication in lift car.	Required	Provided	MR
			Provided	MR
	• Fireman's switch.	Required		
	• Lift signage.	Required	Provided	MR
17	Standby Power Supply	Required	Provided	MR
18.				
	Total area	N/A	N/A	N/A
	unit 1 : 1 : 1 : 1 : 1 : 1 : 1 : 1 : 1 : 1	N/A	N/A	N/A

		1		
19.	Fire Control Room.			
	Detector System Panel.	N/A	N/A	N/A
	Flow Switch Panel.	N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	N/A	N/A	N/A
20.		Required	Provided	MR
20.	Special Fire Protection System for the Protection of Special Risk, if any:	Required	Tiovided	.,,,,,,
	Trotection of Special Risk, If any .			

The Fire protection systems provided in the building were checked randomly and found functional at the time of inspection.

Keeping in view of the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued under Rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put)up for approval and signature please.

Signature of the Inspecting Officer

Name : Sunil C Designation : DCFO

: Sunil Chawdhary : DCFO (SZ) Signature of the Inspecting Officer

Name : S.K. Dua Designation : DO (SD) Signature of the Inspecting Officer
Name : Rajesh Kumar

Name : I Designation : A

: ADO (BCP)

CFO (HQ)

Directory

the F.f.

F.f. letter is put uto

Scanned with CamScanner