GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/2021/SZ/ 156

Dated: 05/03/2021

FIRE SAFETY CERTIFICATE

Certified that the Chittaranjan Park Bangiya Samaj (Regd.) C-405, C. R Park, New Delhi – 110019 Comprised of Basement, Ground + 03 Upper Floors was issued FSC by this department vide letter No. F6/MS/DFS/2007/859 Dated 23/03/2007. The premises re-inspected by officers concerned of this department on 15/02/2021 in the presence of Sh. G. M Bhattacharya (General Secretary) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that building is fit for occupancy "Assembly Building, Group-D" (Community Hall) as above with effect from of 163/2021 for period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on 05/03/2021 at New Delhi by

(Sunil Chawdhary) Dy. Chief Fire Officer (SZ) Delhi Fire Service

Copy to: -

- 1. The Executive Engineer, (Bldg) HQ-1, South Delhi Municipal Corporation, 8th Floor, Civic Centre, JNL Marg, New Delhi
- 2. Sh. G.M Bhattacharya, (General Secretary) Chittaranjan Park Bangiya Samaj (Regd.) C-405, C. R Park, New Delhi 110019

Conditions for the validity of Fire Safety Certificate: -

- 1. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 2. All the staff members must know the correct method of operation of fire fighting system.
- 3. The basement shall be used strictly as per the provision of Building Bye Laws.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

	INSPECTION REPORT						
1	Name & Address of the Building						
1	Traine de Fradress of the Building	Park, New Delhi - 110019					
2	Type of Occupancy	Group "D" Community Hall					
3	Building Comprised of	Basement, Ground + 03 upper floors.					
4	Type of Case	Renewal					
5	Details of Previous NOC	F.6/DFS/MS/2007/859 dated 23/03/2007					
6	Fire Safety Directives Letter No	F6/DFS/MS/BP/97/396 dated 10.04.1997					
7	Date of Inspection	15/02/2021					
8	Name of the Inspecting Officers	Sh. Rajesh Kumar, ADO (BCP)					
9	Name & Designation of Officers	Sh. G. M Bhattacharya (General Secretary)					
	from the building side						
10	Year of construction	1997 & 2014					
11	Applicant letter No.	Outdoor diary no 10048 dated 24-12-2020					
S. No.	Minimum standards on Fire Prevention	NBC	Provided at Site	Remarks MR/NMF			
-	and Fire Safety U/R 33	requirements		IVLEN/INIVLE			
1	Access to Building.	9 mtr	Provided	MR			
	Road width		Provided				
	Gate width	4.5 mtr		MR			
	Width of internal road	-NA-	-NA-	-NA-			
2	Number, width, type & arrangement of exits.						
	a) Number of Staircase		/-				
	Upper floors.	02 Nos	02 Nos	MR			
	Basement floor.	02 Nos	02 Nos	MR			
	b) Width of Staircase	The state of the s					
	> Upper floors	1.25 mtr	1.23 mtr & 0.75 mtr	MR			
		1.25 IIII		(old case)			
	> Basement floor	1.25 mtr	1.23 mtr, 1.65 mtr &	MR			
		1.25 mg	4.25 mtr	(old case)			
	c) Protection of exits						
	> Fire check door	Required	Provided	MR			
	> Pressurization	-NA-	-NA-	-NA-			
	d) No. of continuous staircase to terrace	Required	01 Nos	MR			
	e) Width of corridor	-NA-	-NA-	-NA-			
	f) Door size (Exits in hall)	-NA-	-NA-	-NA-			
3	Compartmentation.						
	Fire check door.	-NA-	-NA-	-NA-			
	Sealing of electrical shafts.	-NA-	-NA-	-NA-			
	Fire rating of shaft door.	-NA-	-NA-	-NA-			
	Water curtain	-NA-	-NA-	-NA-			
	Fire dampers.	-NA-	-NA-	-NA-			
4.	Smoke Management system.			T			
	Basement	30 ACPH	Provided	MR			
	Upper floors	12 ACPH	Natural	MR			
5.	Fire Extinguishers.						
	Total numbers	Required	15 Nos	MR			
	Types	ISI marked	Co2, ABC & DCP	MR			
		ISI marked	Provided	MR			
	ISI Marking	151 marked	Tiovided	IVIIX			
6.	First Aid Hose Reels.	01 17-	Described	MR			
-	Total numbers on each floor.	01 Nos	Provided				
	Length of hose-reel hose.	30m	Provided	MR			
	Nozzle Diameter	5mm	Provided	MR			

7	Automotic fire detection 0 .1.	1		
/	 Automatic fire detection & alarming system. Type of detectors 	-NA-	NT A	77.4
	Location of Main Panel	-NA-	-NA-	-NA-
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	-NA-	-NA-	-NA-
	Hooter's location		-NA-	-NA-
8.	MOEFA	-NA-	-NA-	-NA-
9.	Public Address System	Required	Provided	MR
10.		-NA-	-NA-	-NA-
10.	Automatic Sprinkler System Basement	D : 1		
		Required	Provided	MR
	• Upper floors.	-NA-	-NA-	-NA-
11.	Sprinkler above false ceiling Internal Hardward Table 1	-NA-	-NA-	-NA-
11.	Internal Hydrants.			
	Size of Riser/Down-comer	-NA-	-NA-	-NA-
	Number of Hydrant per floor	-NA-	-NA-	-NA-
10	Hose box.	-NA-	-NA-	-NA-
12.	Yard Hydrants.			
	 Total number of hydrants. 	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13.	Pumping arrangements.			
	Ground Level			
	Discharge of main pump.	-NA-	-NA-	-NA-
	➤ Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	➤ Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting/Manual Stopping.	DIA		
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level			
	Discharge of pump.	900 LPM	Provided	MR
	➤ Head of pump.	40 m	Provided	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for fire fighting.			
	 Underground tank capacity. 	25,000 Ltr	Provided	MR
	Draw-off connection.	Required	Provided	MR
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	Provided	MR
	 Overhead tank capacity. 	12,500 Ltr	Provided	MR
	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	 Pressurization of lift shaft. 	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
	 Communication in lift car. 	-NA-	-NA-	-NA-
	• Fireman's switch.			
	Lift signage.	Required	Provided	MR
17.	Standby Power Supply	Required	Provided Provided	MR
	Refuge Area	Required	Provided (DG Set)	MR
	Total area	-NA-	NIA	3. T. A.
			-NA-	-NA-
	• Location	-NA-	-NA-	-NA-

19.	Fire Control Room.			
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
	Building floor plan.	-NA-	-NA-	-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/MS/DFS/2007/859 Dated 23/03/2007, renewal under rule 35(6) of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer
Name: Sh. Rajesh Kumar

Design: ADO (BCP)

Defo(sp)

Defo(sp)

A DA (BA)

As approved, F.T. letter in pump for your

signature ?