GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2021/SZ/ \23

Dated: 03 \ 03 \ 202|

FIRE SAFETY CERTIFICATE

Certified that the **Govt. Boys Sr. Sec. School,** Site-2, Clock Tower, Hari Nagar, New Delhi-110064 comprised of basement, ground plus one upper floor, but school is running at ground plus one upper floor, owned/occupied by **Govt. Boys Sr. Sec. School** was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2018/SZ/1176 dated 22/05/2018. The school building was re- inspected by the officer concerned of this department on 19/02/2021 in the presence of Sh. Shree Krishan Yadav (Estate Manager) and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (**Ground plus one upper floor only**) is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 03 03 2021 at New Delhi.

(Sunil Chawdhary) Dy. Chief Fire Officer

9cpe

Copy to:-

- The Principal, Govt. Boys Sr. Sec. School, Site-2, Clock Tower, Hari Nagar, New Delhi-110064
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

2. 3. 4. 5. 6. 7. 8.	Type of Type of Details Fire Saf Date of Name of Name at From the Year of	ame & address of the building : Govt. Boys Sr. Sec. School, Site-2, Clock Tower, Hari Nagar, New Delhi-110064 The pe of Occupancy : Educational Renewal Petails of Previous NOC : F.6/DFS/MS/School/2018/SZ/1176 dated 22/05/2018 The Safety directives letter No : F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 The of inspection : 19/02/2021 The period of Inspecting Officer : A.D.O. R.K. Yadav The building side : Sh. Shree Krishan Yadav (Estate Manager) The period of Construction : 2013					
		nt's letter No. : Form "J" dated		D 11.1	D		
S. No.		um Standards on fire prevention and fety U/R 33	Requirement	Provided at site	Remarks MR/NMR		
1.		to building		Site	17110111111		
					*		
	•	Road width	Accessible 06 mtrs 4.5 mtrs	Provided	MR		
	•	Gate width	N/A	Provided N/A	M/R N/A		
2	Name	Width of internal road	14/11	IN/A	IN/A		
2.	Numb	er, Width, Type & Arrangement of Exits					
	a. Nur	nber of staircases					
	•	Upper Floors	03 no.'s	06 no.'s	MR		
	•	Basements	N/A	N/A	Basement (sealed)		
	1 337	V1. C.4.	2				
	b. W10	th of staircases Upper Floor	1.50 m	1.60, 1.52, 1.50, 1.37, 1.37 & 1.06 m	MR		
		Basements	N/A	N/A	Basement (sealed)		
		tection of exits					
		Fire check door	N/A	N/A	N/A		
	•	Pressurization	N/A	N/A	N/A		
	1 27						
		of continuous staircases to	N/A	N/A	N/A		
		race dth of Corridor	1.50 m	2.25m	MR		
	1	or Size	1.00 m	1.07 M (Double door)	MR		
3.	Comp	artmentation					
	•	Fire check door	N/A	N/A	N/A		
		Sealing of electrical shafts	N/A	N/A	N/A		
	•	Fire Rating of shaft door	N/A	N/A	N/A		
	•	Water Curtain					
	•	Fire Dampers	N/A N/A	N/A N/A	N/A N/A		
4.	Smoke	Management System	11111	1771	11/11		
	•	Basements	N/A	N/A	Basement (sealed)		
	•	Upper floors	Required	Natural Ventilation provided	MR		
5.	Fire E	xtinguishers					
	•	Total numbers	20 No's	Provided	MR		
	•	Types	ABC/CO ₂ type	Provided	MR		
	•	IS marking	ISI marked	ISI marked	MR		
6.	First-A	Aid Hose Reels					
	•	Total numbers on each floor	N/A	N/A	N/A		
	•	Length of hose reel hose	N/A	N/A	N/A		
	•	Nozzle diameter	N/A	N/A	N/A		
7.	Auton	natic fire detection and alarming system					

-

	Location of Main Panel	IN/A	IN/A	N/A
	Location of Main Panel Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A N/A	N/A	N/A
8.	MOEFA	N/A N/A	N/A	N/A
1		IN/A	N/A	N/A
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System			2 1
	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
11	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants	77/4		
	Size of riser/down-comerNumber of hydrants per floor	N/A N/A	N/A	N/A
	Hose Box	N/A N/A	N/A N/A	N/A
12.	Yard Hydrants	IN/A	IN/A	N/A
(and ()))	Total number of hydrants	N/A	N/A	N/A
-	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			17/11
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
	Number of main pumpsJockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
-	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
2	D. D. J.	N/A	N/A	N/A
	Pump House AccessTerrace level			
	> Discharge of pump	N/A	N/A	N/A
	> Head of the pump	N/A·	N/A	N/A
	Power Supply	N/A	N/A	N/A
	➤ Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			
	 Underground tank capacity 	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inletAccess to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
		N/A	N/A	N/A
15.	Exit Signage.	N/A	N/A	N/A
16.	Provision of Lifts.	*		No Lift)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car Firemen's Grounding Switch	N/A	N/A	N/A
	Fireman's Grounding SwitchLift Signage	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
		At the state of th	Santa Maria Cara Cara Cara	

		L .			
	•	Detector System Panel	N/A	N/A	N/A
	•	Flow Switch Panel	N/A	N/A	N/A
	•	PA System Panel	N/A	N/A	N/A
3.		Battery backup	N/A	N/A	N/A
	-	Building Floor Plans	N/A	N/A	N/A
20.		l Fire Protection System for Protection of l Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number <u>F.6/DFS/MS/School/2018/SZ/1176</u> dated <u>22/05/2018</u> renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- Basement is sealed and not in use.

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

The least of the put up for sognature please by CRO(S2)

Dycro(S2)

Dycro(S2)

Manual Officer (South West)

A D O (JKP)

FT Letter & put up for sognature please Regard

Regard

1 3/2021