GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001**

No.F6/DFS/MS/GH/2021/

FIRE SAFETY CERTIFICATE

Street The Grace House located at that Certified Rajguru Road, Chuna Mandi, Paharganj, New Delhi comprised of B+ Stilt +Gr. + 03 Upper floors (total 18 Guest rooms & 30 bed), basement for storage, Stilt -parking, Ground floor-office, first to 3rd floor (06 guest rooms & 10 bed at each floor). The premise was inspected by the officer concerned of this department on 01/03/2021 in the presence of Sh. Keshav Ghambir and found that the said guest house building has complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 basement for storage, Stilt -parking, Ground floor-office, first to 3rd floor (06 guest rooms & 10 bed at each floor) total 18 guest rooms & 30 bed only with effect from 1-2/2/ ----- for period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 10/3[2]—at New Delhi by.

DIRECTOR

Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre: for information and verification of point no. 4 as printed below. New Delhi:
- 2. The Joint Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID No. 2021022310683 dated 24.02.2021
- 3. M/S The Grace House, 2359-60, 2361, Rajguru Road, Chuna Mandi, Paharganj ,New Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. Any flammable material for interior decoration is strictly prohibited.

NIZ

INSPECTION REPORT

1. Name & address of the building: M/S The Grace House, 2359-60, 2361

Rajguru Road, Chuna Mandi, Paharganj ,New

Delhi

2. Type of occupancy : - Residential, Sub Division-A

B+ Stilt +Gr. + 03 Upper floors (total 18 Guest rooms 30 bed), basement for storage, Stilt -parking, Ground floor-office, first to 3rd floor (06 guest rooms & 10 bed at each

floor)

3. Type of case:-

New Case

4. Details of previous FSC:-

Nil N/A

5. Fire safety directives No.-

01/03/202

6. Date of inspection:-7. Name of the inspecting officer:-

01/03/2021 Sh. Ravinder Singh, ADO & Sh. Rajinder

Atwal, DO (CD)

8. Name & designation of officer From the building side:-

Sh. Keshav Gambir

9. Year of construction:-

2014

10. Applicant's letter No:-

ID No. 2021022310683 dated 24.02.2021.

New case Remarks **UBBL-1983** Provided at site Minimum Standards on fire MR/NMR /NBC part-4 Prevention and fire safety 2016 U/R 33 Access to Building 1. MR 12 mtr 06mtr 1) Road width N/A N/A N/A 2) Gate width N/A N/A N/A 3) Width of internal road Number, Width Type & Arrangement of Exits 2. A. Number of staircases MR 02 Nos. 02 Nos. 1. Upper floors N/A 02 Nos. 02 Nos. 2. Basements B. Width of staircase MR 1.5 m each 1.25mtr. 1. Upper floors MR 1.5 m each 1.25mtr. 2. Basements C. Protection of exits MR Provided Required 1. Fire check door(in basement) N/A N/A N/A 2. Pressurization MR 02 02 D. No. of continuous staircase to terrace MR 1.50 mtr 1.25 mtr E. Width of corridor MR 1.0 mtr 1.0 mtr F. Door size (Room) Compartmentation 3. N/A N/A N/A 1) Fire check door N/A N/A 2) Sealing of electrical shafts N/A N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers Smoke Management System 4. MR 12 ACPH Exhaust fan 1) Basements MR Natural / 12 a/c per 2) Upper floors exhaust fan hour Fire Extinguishers 5.



	The state of the s	12 Nos.	14 Nos.	MR
	1) Total numbers	ABC & CO2	ABC & CO2	MR
	2) Types	Required	Provided	MR
	3) ISI marking	Required		
5.	First-Aid Hose Reel	01	Provided	MR
	1) Total number of each	01	110,110	
	floor	30 mtr.	30 mtr.	MR
	2) Length of hose reel hose	05 mm	05 mm	MR
	3) Nozzle diameter			
7.	Automatic Fire Detection &	Alarming Syst	Provided	MR
	1) Type of detectors/CO type	Required	Provided	MR
	2) Location of main panel	Stilt floor	N/A	N/A
	3) Location of repeater panel	N/A	Provided	MR
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	each floor	Carlo de la companya del companya de la companya del companya de la companya de l	N/A
0	MOEFA	N/A	Provided	
8.	Public Address System	Required	Provided	MR
9.	Automatic Sprinkler System			
10.	1) Basement	N/A	Provided	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
		1,112		
•	ceiling			
11.	Internal Hydrants	N/A	N/A	N/A
3	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	IN/FX		
	floor	N/A	N/A	N/A
	3) Hose box	IN/A	11122	
12.	Yard Hydrants	N/A	N/A	N/A
	1) Total number of hydrants		N/A	N/A
	2) Hose box	N/A	14/21	
13.	Pumping Arrangement		N/A	N/A
	1) Ground level	N/A	N/A N/A	N/A
	a) Discharge of main	N/A	IN/A	
	pump	27/4	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pun		N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump outpo	ut N/A	N/A N/A	N/A
	g) Stand by pump head	N/A	N/A N/A	N/A
	h) Auto starting/Manua	al N/A	IN/ M	
	stopping			
	2) Terrace level	AEO I DNA	450 LPM	MR
	a) Discharge of pump	450 LPM	30 mtr.	MR
	b) Head of pump	30 mtr.		MR
	c) Power supply	Required	1	MR
	d) Auto starting of pur	np Required	Flovided	1744
	Captive Water Storage fo			
14.	Captive water Storage to	N/A	N/A	N/A
	1) Under ground tank	14/15		÷ i
	capacity	on N/A	N/A	N/A
	a) Draw-off connectionb) Fire service inlet	N/A	N/A	N/A
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 / 1		NI/A
	1		N/A	N/A
	c) Access to tank d) Over head tank cap	N/A	N/A 10,000 ltr.	MR

		Required	Provided	MR
15.	Exit Signage.			
16.	Provision of Lifts.(serving from stilt to upper floors only)			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift- lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
•	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any: fire extinguisher	MR		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, we may issue the FSC to said guest house. Accordingly, DFA is prepared and put up for kind perusal/approval and sig. please.

Signature of the inspecting officer

3/3/2021 Name: - Rajinder Atwal

Designation: - DO (CD)

Signature of the Inspecting Officer

Name: Ravinder Singh Designation: ADO (CC)

PI. Apeak about ph. no. 2h3.

1. Sporteen on 20.3. 2021.

2. Year of construction is 2014 as per application

2. Year of construction is 2014 as per application

3. I Applicant has subsurfied one time convenion

3. I Applicant has subsurfied one time convenion

change seceipt of MCD dated 13.4. 2015

change seceipt of MCD dated 13.4. 2015

at close c/12.