GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/EH/2021/NDZ/ / 4

Dated: 11 | 03 | 2021

FIRE SAFETY CERTIFICATE

Certified that the M/s Barshala (A Unit of Insospirit Bars Pvt. Ltd.) running on ground & first floor of the building is comprised of ground and one upper floor located at D-Block, Plot No 9D, CBD Shahdara, Adity Mall, Delhi-110032 owned/occupied by Insospirit Bars Pvt. Ltd. The premises was inspected by the officer concerned of this department in the presence of Sh. Sumit Wadhera and found that the restaurant have complied with the fire prevention and fire safety requirements in accordance with rules 33 of the Delhi Fire Service Rules, 2010 and observed that Eating House is fit for occupancy Group D "Assembly Building" for ground and first floor with effect from Additional for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on 11 03 2021 at New Delhi by

(Atul Garg)
Director
Delhi Fire Service

To,

Sh. Sumit Wadhera H. No. 207, Jor Bagh, Lodhi Raod, Delhi-110003

Copy To:-

The Addl. Commissioner of Police (Lic.) First floor, Police station Defence Colony New Delhi

MHA ID No. 202010307653

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form `J` [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

1. Name & address of the building : M/s Barshala

: M/s Barshala (A Unit of Indospirit Bars Pvt. Ltd.). at Ground & First Floor, D-Block, Plot No.9D, CBD

Shahdara, Adity Mall, Delhi-110032.

2. Building is comprised of : Ground plus one upper floor

3. Type of Occupancy : Assembly (Restaurant)

4. Type of Case : New5. Details of Previous NOC letter : Nil

6. Fire Safety directive letter No : NBC Part IV 7. Date of Inspection : 19/02/2021

8. Name of the Inspecting officers : DO F. Brown9. Name and designation of Officer

from the building side :Sumit Wadhera (Owner)

10. Year of Construction : 2017

11. Applicant's letter No : 202010307653 dated 21/01/2021

Sr.	Minimum Standards on Fire	NBC Part IV	Provided at Site Remains				
No.	Prevention and Fire Safety U/R33	Requirement		MR/NMR			
01	Access to Building						
	Road width	09 mtr.	18 mtr.	MR			
	 Gate width 	N/A	N/A	N/A			
	 Width of internal road Number, Width, Type and Arrangen 	N/A	06 mtr.	MR			
02							
	a. Number of Staircases						
	 Upper floor 	02 Nos.	02 Nos.	MR			
	Basement	N/A	N/A	N/A			
	B. Width of Staircases						
	Upper floor	02 mtr &	02 mtr & 1.50 mtr	MR			
		1.50 mtr					
	Basement	N/A	N/A	N/A			
	c. Protection of Exits						
	Fire check door	Required	Provided	MR			
	Pressurization	N/A	N/A	N/A			
	d. No. of Continuous Staircases to Terrace	N/A	N/A	N/A			
	e. Width of Corridor	N/A	N/A	N/A			
	f. Door Size	02 mtr & 1.50 mtr	02 mtr & 1.50 mtr	MR			
	g. No. of Door	02 nos.	02 nos	MR			
03	Compartmentation.	N/A	N/A	N/A			
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
	 Fire rating of shaft door 	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	Fire dampers	N/A	N/A	N/A			
04	Smoke Management System.						
	Basement	N/A	N/A	N/A			
	Upper floor	N/A	N/A	N/A			
05.	Fire Extinguishers						
	Total numbers	04 nos.	04 nos.	MR			
	Types	ABC /CO ₂	ABC /CO ₂	MR			
	 IS marking 	ISI marked	ISI marked	MR			

06	First-Aid-Hose Reels.						
06			0.4	MR			
	Total numbers on each floor	01 nos	01 nos	MR			
	 Length of hose reel hose 	30 mtr	30 mtr	MR			
	Nozzle diameter	05 mm	05 mm	IVIR			
7	Automatic Fire Detection and Alarming System						
	Type of detectors	N/A	Smoke	MR			
	 Location of main panel 	N/A	N/A	N/A			
	 Location of repeater panel 	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter	N/A	N/A	N/A			
380	MOEFA	Required	Provided	MR			
09	Public Address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.						
	N/A						
	Basement	2 1	Provided	MR			
	Ground & upper floor	N/A	N/A	N/A			
4.4	sprinkler above false ceiling	N/A	IN/A	14//1			
11	Internal Hydrants						
	size of riser/down-comer	100 mm	100 mm	MR			
	 Number of hydrants per floor 	01 no.	01 no.	MR			
	Hose box	01 no.	01 no.	MR			
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
	Hose box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	> Ground Level						
	y Ground Level			1			
	Discharge of main pump	N/A	N/A	N/A			
	Head of main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	 Jockey pump out put 	N/A	N/A	N/A			
	 Jockey pump head 	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump head	N/A	N/A	N/A			
	Auto starting /manual	NI/A	N/A	N/A			
	stopping	N/A	N/A	N/A			
	 Pump house access 	N/A	IV/A	IN/A			
	> Terrace Level						
	Discharge of pump	900 lpm	900 lpm	MR			
	Head of the pump	40 mtr	40 mtr	MR			
	Power supply	Required	Provided	MR			
	Auto starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting Common with the Mall						
		N/A	N/A	N/A			
	5 66	N/A	N/A	N/A			
	Draw-off connection Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	Overhead tank capacity	20,000 ltr	20,000 ltr	MR			
15	Exit Signage.	Required	Provided	MR			
1 10				The state of the s			

16	Provision of Lifts.						
	Pressurization of lift shaft	N/A	N/A	N/A			
	 Pressurization of lift lobby 	N/A	N/A	N/A			
	 Communication in lift car 	N/A	N/A	N/A			
	 Firemen's grounding switch 	N/A	N/A	N/A			
	 Lift signage 	N/A	N/A	N/A			
17	Standby Power Supply	Required	Provided	MR			
18	Refuge Area.						
	Total area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector system panel	N/A	N/A	N/A			
	Detector system panel Flow switch panel	N/A	N/A	N/A			
	DAtama manal	N/A	N/A	N/A			
	D. II. In along	N/A	N/A	N/A			
	D. II.I'm flagger	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of Special Risks, if Any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/checked

found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rule, it is recommended to issue Fire Safety Certificate.

Signature of the Inspecting Officer

Name

: F. Brown

Designation : D'O (ED)

Dy. DFO (NDZ)

PI. Speak Janer 23/2/21

DOCES Spoken-and re-submitted ph.