



No.F6/DFS/MS/School/2021/ 2 2 0

Dated: 12 03 2021

FIRE SAFETY CERTIFICATE

Certified that the EDMC Primary School, Mandoli Balika at Mandoli Ext, Delhi-110093, comprised of ground plus one upper floor, owned/occupied by EDMC Primary School was issued FSC vide letter No-F6/DFS/MS/School/2017/NDZ/339 dated-08/03/17. The school building was re-inspected by the officer concerned of this department on 26/02/2021 in the presence of Mr. Anand Prakash Gupta, Principal of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular Letter No-F16/Estate/CC/FireSafety/2011/3298to3398 dated 01/03/11 issued by Director of Education and found that the school building is fit for occupancy class "B" 'Educational Building' for ground floor with effect from 1.3 0.3 2021 for a period of three years subject to conditions, printed overleaf.

(Dr.S.K.Tomar) DY.Chief Fire Officer

To,

The Principal, EDMC Primary School, Mandoli Balika, Mandoli Ext., Delhi-110093,

Copy:-

The Director of Education, EDMC, Udyog Sadan, Plot No.419, FIE, Patparganj Industrial Area, Delhi-110092

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

Name & address of the building

: EDMC Primary School, Mandoli Balika,

Mandoli Ext., Delhi-110093

Building is comprised of

3. Type of Occupancy

4. Type of Case

5. Details of Previous FSC letter

6. Fire Safety direction letter No

7. Date of Inspection

8. Name of the Inspecting officers

9. Name and designation of Officer from the building side

10. Year of Construction

11. Applicant's letter No

: Ground plus first floor : Educational

Renewal

: F6/DFS/MS/School/2017/NDZ/339 Dt.08/03/17

: F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11

: 26/02/2021

: ADO Mehmood

: Mr Anand Prakash Gupta. (Principal)

: 2005

: Letter No.-Nil, Dated-05/02/2021(email)

Sr.	Minimum Standards on Fire	Circular	Provided at Site	Remarks			
No.	Prevention and Fire Safety U/R33	Requirement		MR/NMR			
01	Access to Building						
	Road width	06 mtr.	06 mtr.	MR			
	 Gate width 	N/A	N/A	N/A			
	 Width of internal road 	N/A	N/A	N/A			
02	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases						
	 Upper floor 	01 nos.	02 nos.	MR			
	 Basement 	N/A	N/A	N/A			
and the second	b. Width of Staircases						
	 Upper floor 	1.50 mtr.	2.15 & 1.5 mtr.	MR			
	 Basement 	N/A	N/A	N/A			
The second second	c. Protection of Exits						
	 Fire check door 	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
tial and manpers on specific	d. No. of Continuous Staircases to Terrace	N/A	N/A	N/A			
	e. Width of Corridor	1.50 mtr.	1.50 mtr	MR			
	f. Door Size	01 mtr.	01 mtr.	MR			
03	Compartmentation.						
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
w were tables	 Fire rating of shaft door 	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
and Majoria was	 Fire dampers 	N/A	N/A	N/A			
04	Smoke Management System.						
-	Basement	N/A	N/A	N/A			
According to	 Upper floor 	N/A	N/A	N/A			
05.	Fire Extinguishers						
	Total numbers	06 nos.	06 nos.	MR			
The second second	• types	ABC /CO ₂	ABC /CO ₂	MR			
	 IS marking 	ISI marked	ISI marked	MR			

06	First-Aid-Hose Reels.						
	Total numbers on each floor	N/A	N/A	N/A			
	 Length of hose reel hose 	N/A	N/A	N/A			
	 Nozzle diameter 	N/A	N/A	N/A			
07	Automatic Fire Detection and Alarming System.						
	Type of detectors	N/A	N/A	N/A			
	 Location of main panel 	N/A	N/A	N/A			
	 Location of repeater panel 	N/A	N/A	N/A			
	 Alternate source of power 	N/A	N/A	N/A			
	 Hooter's location 	N/A	N/A	N/A			
80	MOEFA	N/A	N/A	N/A			
09	Public Address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.						
- Andrew	Basement	N/A	N/A	N/A			
	 upper floor 	N/A	N/A	N/A			
	 sprinkler above false ceiling 	N/A	N/A	N/A			
11	Internal Hydrants						
	size of riser/down-comer	N/A	N/A	N/A			
	 Number of hydrants per floor 	N/A	N/A	N/A			
	Hose box	N/A	N/A	N/A			
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
	Hose box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	➤ Ground Level						
	Discharge of main pump	N/A	N/A	N/A			
	 Head of main pump 	N/A	N/A	N/A			
	 Number of main pumps 	N/A	N/A	N/A			
	 Jockey pump out put 	N/A	N/A-	N/A			
	 Jockey pump head 	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	 Standby pump head 	N/A	N/A	N/A			
	 Auto starting /manual stopping 	N/A	N/A	N/A			
	Pump house accessTerrace Level	N/A	N/A	N/A			
		A 170		8			
	 Discharge of pump Head of the pump 	N/A	N/A	N/A			
	Head of the pumpPower supply	N/A N/A	N/A	N/A			
	Auto Starting of pump	N/A	N/A N/A	N/A N/A			
14	Captive Water Storage for Fire Fighting.						
	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	 Fire service inlet 	N/A	N/A	N/A			
	 Access to tank 	N/A	N/A	N/A			
	 Overhead tank capacity 	N/A	N/A	N/A			
5	Exit Signage.	N/A	Provided	MR			

16	Provision of Lifts.					
	Pressurization of lift Shaft	N/A	N/A	N/A		
	 Pressurization of Lift lobby 	N/A	N/A	N/A		
	 Communication in lift car 	N/A	N/A	N/A		
	 Firemen's grounding switch 	N/A	N/A	N/A		
	 Lift signage 	N/A	N/A	N/A		
17	Standby Power Supply	N/A	N/A	N/A		
18	Refuge Area.					
	Total area	N/A	N/A	N/A		
	 Location 	N/A	N/A	N/A		
19	Fire Control Room					
And the second control of the second control	Detector system panel	N/A	N/A	N/A		
	 Flow switch panel 	N/A	N/A	N/A		
	 PA system panel 	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building floor plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of Special Risks, if Any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/checked at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire Noprevention fire safety required under the circular and F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11 issued by Director of Education, it is recommended to grant Fire Safety Certificate.

Signature of the Inspecting Officer

29/2/2011

Name- Mehmood

Designation- A.D.O(T.P.)

1. DFA Nighed.
2. Pl. correct numbering on noting Unsighed Muets
have been attached.

Doctor F. & lellin do Prepran futar

DY. CROLATELY

DETONOMY

JOHNSON