## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2021/ND2/139

Dated: 16/03/2021

## **FIRE SAFETY CERTIFICATE**

Issued 16/03/2021 at New Delhi by.

(**Dr. S. K.Tomar**)
Dy. Chief Fire Officer
Delhi Fire Service

0270m

Copy to:-

- 1. The Joint Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi online id 2021022810830 dated 28.02.2021.
- 2. The Manager, Hari Piorko Inn Guest House located at 4778-A&B, 4779, 4781 (Part), Main Bazar, Pahar Ganj, New Delhi

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other condition mentioned in the gazette notification dated 27.05.2019 & clarification issued dated on 25.09.2019 & 17.12.2020 latest by 31.03.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 10. The owner shall not use any floor above third floor for any purpose and same shall remain closed/locked.

## INSPECTION REPORT

Hari Piorko Inn Guest House located at 1. Name & address of the building 4778-A&B, 4779, 4781 (Part), Main Bazar,

Pahar Ganj, New Delhi

2. Type of occupancy:-

Residential, Sub Division-A-1
Ground +4<sup>th</sup> upper floor (30 guest rooms)
ground to 2<sup>nd</sup> floor (07 room at each floor), 3<sup>rd</sup>
floor 09 guest room. 4<sup>th</sup> floor not to use as per

affidavit dated 01.02 20.

Renewal 3. Type of case:-

No. F6/DFS/MS/GH/2017/1511 4. Details of previous FSC:-

dated 10/10/17

5. Fire safety directives No.-

N/A

6. Date of inspection:-

10/03/21

7. Name of the inspecting officer:-

Sh. Ravinder Singh(ADO/CC) Sh. Rajinder Atwal ( DO/CC )

8. Name & designation of officer from the building side:-

Mr. Rajeev Makker

9. Year of construction:-

1991

10. Applicant's letter No:-

online id 2021022810830 dated 28.02.2021.

Old Case

10.	Applicant s letter 110			Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building		•	
	1) Road width	N/A	09 mtr.	N/A
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arra	angement of Exi	its	
<u> </u>	A. Number of staircases	0		
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	150 mtr.	160 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03/21 of compliance extended vide order dt 17.12.2020
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	1.0 mtr.	1.0 mtr.	MR
3.	Compartmentation			
J.	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
1 4	Dilluke management System	30 ACPH	N/A	N/A

	2) Upper floors	12 ACPH	Natural	MR
5.	Fire Extinguishers			-1000
0.	1) Total numbers	08 Nos.	10.31	
	2) Types	ABC & CO2	10 Nos.	MR
	3) ISI marking			MR
6.	First-Aid Hose Reel	Required	Provided	MR
	1) Total number of eachfloor	01	0.1	
	2) Length of hose reel hose	30 mtr.	01 Provided	MR
	3) Nozzle diameter	05 mm		MR
7.	Automatic Fire Detection &		Provided	MR
	1) Type of detectors CO type	Required as		
		per G.N dated 27.05.19	Not provided	Last dt. 31.03/21 of compliance extended vide order dt. 17.12.2020
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	<b>Public Address System</b>	Required	Provided	MR
10.	Automatic Sprinkler System	l		
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			8.5
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per floor	N/A	N/A	N/A
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants		1011	10/74
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			1771
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump		1 1/1 1	IV/A
•	b) Head of main pump	N/A	N/A	N/A
	c) Number of main	N/A	N/A	N/A
	pump		•	
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump	N/A	N/A	N/A
	output			
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A
	2) Terrace level			
	a) Discharge of pump	450 LPM	450 LPM	MR

	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for	or Fire Fighting		
	Under ground tank capaci	ty N/A	N/A	N/A
	a) Draw-off connection	on N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	5,000 ltr.	5,000 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		Q1	
	a) Pressurization of lift shaft	ft N/A	N/A	N/A
	b) Pressurization of lift lobby	ft N/A	N/A	N/A
	c) Communication in car	lift N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system par	nel N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Sy Risk, if any: ABC & Co2	ystem for Protect	ion of special	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. No. F6/DFS/MS/GH/2017/1511 dated 10/10/17 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name :- Rajinder Atwal

Name :- Ravinder Singh Designation: - ADO (CC)

Designation:- DO (CD)