GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/Mixed/2021/SZ//63

Dated: .//. /0. 3.../2021

FIRE SAFETY CERTIFICATE

Centre, Jasola New Delhi - 110044 comprised of three tiers basement, ground floor + 06 upper floors was issued No Objection Certificate by this department vide letter No. F.6/DFS/MS/Mixed/SZ/2018/879 Dated 01/05/18. The premises was re-inspected by officer concerned of this department on 05/05/2018 in the presence of Sh. Tilak Singh (Facility Manager) and found that the premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that building is fit for occupancy Class Mixed Occupancy (Mercantile & Business) with effect from 11/03/2021 for period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued 11 /03 /2021 at New Delhi by

Copy to: -

- 1. (Uppal's Plaza M-6) The Indian Coloniser Pvt. Ltd., Plaza M-6, located at Plot No 06, Jasola, Distt. Centre, Jasola New Delhi 110044
- 2. The Ex. Engineer (Bldg), South MCD, Jal Vihar, Lajpat Nagar, New Delhi 110024

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

	- 1				ON REPORT				
	1		N	ame & Address of the Building	Indian Colonis	Indian Coloniser Pvt. Ltd, Plaza, M-6, Plot No-6,			
					Jasola Centre,	Jasola Centre, Jasola, New Delhi 110044			
	2		Ty	pe of Occupancy	Mixed Occupancy "Group-E & F"				
	3	+	D	This Court is to Co	(Mercantile &				
	4	Building Comprised of Three tier Basements, Ground + 06 upper floor Type of Case Renewal							
-	5			tails of Previous NOC	Renewal				
+					F.6/DFS/MS/Mixed/SZ/2018/879 Dated 01/05/18				
-	7	The Surety Directives Letter Ivo			F.6/DFS/MS/BP/2007/886 Dated 28/03/2007 20/02/2021				
+	8	***************************************	-	me of the Inspecting Officers	Dy. CFO (South) & ADO (BCP)				
-	9			me & Designation of Officers	The same of the sa	Sh. Tilak Singh			
				m the building side	Sii. Thak Shigh				
	10			ar of construction	2006-07				
	11	1	Ap	plicant letter No.	Gmail dated 1	1/02/2021			
-	S. No.	1		nimum standards on Fire Prevention	NBC/BBL				
		8	m	Fire Safety U/R 33	Requirements	Provided at Site	Remarks MR/NMR		
-	1	1	Ac	cess to Building.			IVIIVIIVIIVI		
				Road width	9 mtr	Provided	MD		
1				• Gate width	NA (No boundary or	About on road	MR		
				 Width of internal road 	road side) 6 mtr	6 mtr	MR		
	2	I	\u	mber, width, type & arrangement of e		Omu	MR		
-		a	1)	Number of Staircase					
		-		> Upper floors.	03 No	D 111			
				Basement floor.	05 Nos	Provided Provided	MR MR		
		b)	Width of Staircase		1 Tovided	IVIK		
				> Upper floors	1.50m (each)	2 x 1.5 m & 1.8 m	MR		
		-	,	> Basement floor Protection of exits	1.50m (each)	2 x 1.5 m & 3 x 1.8	m MR		
		C	4						
			1	Fire check door	Required	Provided	MR		
- Anna Anna Anna Anna Anna Anna Anna Ann		d	1	> Pressurization No. of continuous staircase to terrace	Required	Provided	MR		
					03 Nos	03 Nos	MR		
		(e)	_	Width of corridor	1.50 mtr	1.50 mtr	MR		
		f)		Door size	1 mtr	1.5 mtr (final exit)	MR		
	3	C	on	npartmentation.					
				• Fire check door.	Required	Provided	MR		
			1	• Sealing of electrical shafts.	Required	Provided	MR		
			-1	Fire rating of shaft door.	NA	NA	NA		
				Water curtain Fire dampers	NA	NA	NA		
	4	SI	_	ke Management system.	Required	Provided	MR		
			+						
				Basement Upper floors	30 ACPH	Provided	MR		
	5	Fi		Extinguishers.	12 ACPH	Provided	MR		
			9		100 nos.	Described.			
			0		ABC/W.co2/M.	Provided	MR		
				ISI Marking	Foam & CO ₂	40/40/20	MR		
	6	T:	PO C 4	Aid Hose Reels.	ISI marked	Provided	MR		
		1.1	DI						
			•	Total numbers on each floor.	GF to Terrace -2 No Basement- 4 Nos.	Provided	MR		
	41/			Length of hose-reel hose.	30m	Provided	MR		
				Nozzle Diameter	5	Provided	MR		
	7	A	ato	omatic fire detection & alarming system		27011000	IVIK		
-					Heat & Smoke	Heat & Smoke	MR		
	1			Location of Main Panel	O 10	TIOU OF SHIOKE	IVIK		

	Hooter's location	Entire building	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System			
10	Basement	Required	Provided	MR
	Upper floors (except EE area)	Required	Provided	MR
	• Sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants.			
	Size of Riser/Down-comer	100mm	100mm	MR
		GF to Terrace -2 No. Basement- 4 Nos.	s Provided	MR
	Number of Hydrant per floor	GF to Terrace -2 No Basement- 4 Nos.	s Provided	MR
	Hose box.	Basement- 4 Nos.		
12	Vard Hydrants.		2 111	MD
	Total number of hydrants.	06 nos.	Provided	MR
	Hose box.	06 nos.	Provided	MR
13	Pumping Arrangements.			
	Ground Level			
	Discharge of main pump.	2280 LPM	4500 LPM	MR
	> Head of main pump.	60m	60m	MR
	Number of main pumps.	01 no	01 no	MR
	> Jockey Pump output.	180 LPM	180 LPM	MR
	> Jockey Pump head.	60m	60m	MR
	> Standby Pump output.	2280 LPM	4500 LPM	MR
	> Standby Pump head.	60m	60m	MR
	➤ Auto Starting/Manual Stopping.	Required	Provided	MR
	> Pump house access.	Required	Provided	MR
	Terrace Level			
	> Discharge of pump.	900 LPM	Provided	MR
	Head of pump.	40 mtr	Provided	MR
	> Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.			
	Underground tank capacity.	1,00,000 Ltrs	1,00,000 Ltrs	MR
	> Draw-off connection.	Required	Provided	MR
	Fire Service Inlet	Required	Provided	MR
	Access to tank.	Required	Provided	MR
	Overhead tank capacity.	20,000 Lts	20,000 Lts	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			P
	Pressurization of lift shaft	Required	Provided	MR
	Pressurization of lift lobby.	Required	Compensated with excess lift shaft pressure in conformity with provision of NBC-2016	MR
	Communication in lift car.	Required	Provided	MR
	Fireman's switch.	Required	Provided	MR
	Lift signage.	Required	Provided	MR
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	Total area	Required	Provided	MR
	• Location	5 th , Floor	Provided	MR
19	Fire Control Room.			
	Detector system panel.	Required	Provided in basement	MR (old case)

	Flow switch panel.	Required	Provided in basement	MR (old case)
	PA system panel. Battery backup.	Required	Provided in basement	MR (old case)
		Required	Provided	MR
	Building floor plan.	Required	Provided	MR
20	Special Fire Protection System for the Protection of special Risk, if any.	Required	Manual Co2 Flooding + 02 nos of DCP Extinguisher for HT/LT Panels provided.	MR

The Fire protection systems provided in the building/ premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/Mixed/SZ/2018/879 Dated 01/05/18 renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the inspection Officer

Name: Sh. Sunil Chawdhary Designation: Dy. CFO (South) Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar, Designation: ADO (BCP)

Dolso was on mlk on 20/2/221

1 S 2-1 Dies Nymaning

9 3001

FIPS

DIW/52 B

As signed not

plane f

Di recto form