GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/Hospital/2021/SZ/ / 2 3

Dated:/ 9 / 03 .../2021

FIRE SAFETY CERTIFICATE

Certified that M/s Nursing Hostel (Adhyayan Block) Part of Phase-II, Institute of Liver & Biliary Science, Sector D-1, Vasant Kunj, New Delhi 110070 comprised of ground plus Seven upper floors was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/Hospital/2016/SZ/1199 Dated 27-07-2016. The Hostel was re-inspected by officers concerned of this department on 13/03/2021 in the presence of Mr. Amit Gautam (AM/Fire & Security) and observed that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class Residential as above with effect from 19/03/2021 for period of Five years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued 19/03/2021 at New Delhi by

Director

Delhi Fire Service

Copy to: -

1. Mr. Amit Gautam (AM/Fire & Security) Institute of Liver & Biliary Sciences Hospital, Plot No D-I, Vasant Kunj, New Delhi-110070

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation, etc. may be got verified from the concerned authorities.
- 5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

	INSPECTION REPORT					
1	Name & Address of the Building	M/s Nursing H	ostel, (Adhyayan Blo	ck) Part of		
		Phase- II, Institu	ute of Liver & Bilian	ry Sciences,		
-		Sector D-I, Vasant Kunj, N. Delhi 110070				
2	Type of Occupancy	Residential building, "Group-A" (Hostel)				
3	Building Comprised of	Ground + 07 upper floors.				
4	Type of Case	Renewal				
5	Details of Previous NOC	1	tal/2016/SZ/1199 Dated 2"			
6	Fire Safety Directives Letter No	1	oital/2011/723 dated 21-	-04-2011		
7	Date of Inspection	13/03/2021				
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)				
9	Name & Designation of Officers	Sh. Amit Gautam (AM/Fire)				
	from the building side					
10	Year of construction	2013				
11	Applicant letter No.	Gmail dated 19-02-2021				
S. No.	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks		
	and Fire Safety U/R 33	Requirements		MR/NMR		
1	Access to Building.					
	Road width	12 mtr	Provided	MR		
	Gate width	6 mtr	Provided	MR		
	Width of internal road	6 mtr	Provided	MR		
2	Number, width, type & arrangement of ex					
AN	a) Number of Staircase					
	> Upper floors.	02 Nos	Provided	MR		
	Basement floor.	=NA=	=NA=	=NA=		
	Of the Control of the	-IN/A-	-iVA-	-INA-		
	b) Width of Staircase	1.5 / 1	1.60	1.40		
	> Upper floors	1.5 mtr each	1.50 mtr each	MR		
	> Basement floor	-NA-	-NA-	-NA-		
	c) Protection of exits			-		
	> Fire check door	Required	Provided	MR		
	> Pressurization	-NA-	-NA-	-NA-		
	d) No. of continuous staircase to terrace	Required	02 Nos	MR		
	e) Width of corridor	1.5m	1.45 mtr	MR		
				(old case)		
	f) Door size	1m	Provided	MR		
3	Compartmentation.					
	 Fire check door. 	Required	Provided	MR		
	 Sealing of electrical shafts. 	Required	Provided	MR		
	 Fire rating of shaft door. 	-NA-	-NA-	-NA-		
	Water curtain	-NA-	-NA-	-NA-		
	Fire dampers.	-NA-	-NA-	-NA-		
4.	Smoke Management system.					
	Basement	30 ACPH	-NA-	-NA-		
	Upper floors	- 12 ACPH	Natural ventilation	MR		
5.	Fire Extinguishers.					
	Total numbers	Required	40 Nos	MR		
		ABC/CO2/W.CO2	ABC, CO2 & W.CO2	MR		
	• Types		 			
	ISI Marking	ISI marked	Provided	MR		
6	First Aid Hose Reels.		·			
	Total numbers on each floor.	02 Nos	Provided	MR		
	 Length of hose-reel hose. 	30m	Provided	MR		
	Nozzle Diameter	5mm	Provided	MR		

7 /	Automotic five detection & alamin			
1 1	 Automatic fire detection & alarming sys Type of detectors 	-NA-	-NA-	1 372
	 Location of Main Panel 	-NA-		-NA-
		-NA-	-NA-	-NA-
	or all of telepouter i unter		-NA-	-NA-
	Alternate source of power	-NA-	-NA-	-NA-
0 8	Hooter's location	-NA-	-NA-	-NA-
	MOEFA	Required	Provided	MR
	Public Address System	Required	Provided	MR
10 A	Automatic Sprinkler System	N. S. L.		
	• Basement	-NA-	-NA-	-NA-
	Upper floors.	-NA-	-NA-	-NA-
	 Sprinkler above false ceiling 	-NA-	-NA-	-NA-
11 In	nternal Hydrants.			
	Size of Riser/Down-comer	-NA-	100 mm	-NA-
	 Number of Hydrant per floor 	-NA-	02 Nos	-NA-
	Hose box.			
12		-NA-	02 Nos	-NA-
12 Y	ard Hydrants.	7.7.4	T	
	 Total number of hydrants. 	=NA=	05 Nos	-NA-
	Hose box.	-NA-	05 Nos	-NA-
13 P	umping arrangements.			
	Ground Level			
	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level		A TA A	1421
	Discharge of pump.	900 LPM	950 LPM	MR
	> Head of pump.	40m	Provided	MR
*	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14 C	aptive water storage for fire fighting.	Trogonica	Trovided	IVIIX
	Underground tank capacity.	-NA-	-NA-	-NA-
	Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	-NA-	-NA-	-NA-
	 Overhead tank capacity. 	25,000 Ltr	35,000 Ltr	MR
15 E	xit Signage.	Required	Provided	MR
	rovision of Lifts.			1711
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	Required	Provided	MR
	• Fireman's switch.	Required	Provided	MR
	Lift signage.	Required	Provided	MR
17 St	andby Power Supply	Required	Provided (DG Set)	
	efuge Area	Required	Trovided (DG Set)	MR
111	Total area	-NA-	NIA	NT A
			-NA-	-NA-
	• Location	-NA-	-NA-	-NA-

19.	Fire Control Room.				
	Detector system panel.	-NA-	-NA-	-NA-	
	Flow switch panel.	-NA-	-NA-	-NA-	
	PA system panel.	-NA-	-NA-	-NA-	
	Battery backup.	-NA-	-NA-	-NA-	
	Building floor plan.	-NA-	-NA-	-NA-	
20.	Special Fire Protection System for the Protection of special Risk, if any.	Required	CO2 type fire extinguishers provided near electrical panel	MR	

The Fire protection systems provided in the building were checked/ tested at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/Hospital/2016/SZ/1199 Dated 27-07-2016, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. S. K Dua Design: DO (South) Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

Dy. CFO (SZ)

Larg

8 09 m

f1 PG

Any BLP

As approved, F.T. letters is pur up for kind perusal, approved Sign for.