GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/NDZ/2021/ 150

Dated: 23/03/2021

FIRE SAFETY CERTIFICATE

Certified that the Punjab Hotel, located at 669, Church Mission Road, Delhi, comprised of Basement + Ground + 03 upper floor: Basement - use for storage purpose, Ground floor - 22 guest rooms + 02 office, 1st floor - 19 guest rooms, 2nd floor - 17 guest rooms + store, 3rd floor - 15 guest rooms total 73 guest rooms was granted FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2018/1042 dated 14.05.2018. The building/premises was re-inspected by Assistant Divisional Officer (SPM) from this department on 16.03.2021 in presence of manager Sri Sudhakar Sharma, and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of "Group A-1 (Residential)" for total 73 guest rooms (Ground floor - 22 guest rooms, 1st floor – 19 guest rooms, 2nd floor - 17 guest rooms, 3rd floor - 15 guest rooms) upto 3rd floor only, with effect from .23\.03\.\?\. for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on 33 03 202 at New Delhi by

(Dr. S.K. Tomar) Dy. Chief Fire Officer

Ox grun

Tel: 011-23412025

ofc De

Copy to:-

1. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi.

2. The Licensee, Punjab Hotel, located at 669, Church Mission Road, Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 and any violation of clarification issued on 25.09.2019 & 17.12.2020 latest by 31.03.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. Basement shall be used as per BBL.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry". Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained there to before occupancy of the same.

ML

1	Name & address of the building	Punjab Hotel, located a	at 669, Church Mi	ssion Road,	
1	Traine & address of the samanig	Delhi			
2	Building is comprised of	Basement + Ground + 03			
		Basement – vacant at the time of inspection			
		(approx. area of basement = 18 sq.m)			
		Ground floor - 22 guest	rooms + 02 office		
		1 st floor – 19 guest rooms			
		2 nd floor - 17 guest rooms + store			
		3 rd floor - 15 guest rooms			
3	Type of Occupancy	Residential Group A-1			
4	Type of Case	Renewal			
5	Details of Previous FSC	F6/DFS/MS/GH/NDZ/20	18/1042 dated 14.05.	2018	
6	Fire Safety direction letter No	Nil			
7	Date of Inspection	16.03.2021			
8	Name of the Inspecting Officers	Rajesh Kumar Shukla AD	OO (SPM)		
9	Name of the designation of Officer	Manager			
	from the building side				
10	Year of Construction	1948	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
11	Applicant's letter No	Email dated 11.03.2021 8	Online application	I.D. no.	
11	Applicant's letter 140	2021012809960 dated 08			
S.N	Minimum Standards on fire	Requirement/ Existing	Provided at Site	Remarks	
0.1	Prevention and fire safety	fire safety		MR/NMI	
	requirements U/R 33	arrangements			
1	Access to building	arrangements		1	
1		06 m	09 m	MR	
	Road width		NA	NA	
	Gate width Width of internal road	NA NA	NA NA	NA	
2	Number, Width, Type and Arran	No. 1914 1914	1471	1112	
2	A. Number of Staircases	igement of Exits			
		02 no.	02 no.	MR	
	Upper Floor	02 no.	01 no.	MR	
	Basement B. Wildth of Stairness	OT HO.	01110.	IVAL	
	B. Width of Staircases	90 cms (as per previous	90 to 160 cms &	MR	
	Upper Floor	inspection)	90 cms		
	Basement	90 cms	90 cms	MR	
	C. Protection of exits				
	Fire check door	(required as per GN dated 27.05.2019)	Not Provided	Last date of compliance extended till 31.03.2021 vide order dated 17.12.2020	
	Pressurization	NA	NA	NA	
		NA	NA	NA	
	D. No. of continuous staircases to	1471			
	terrace	NA	NA	NA	
		·	NA 1 m	NA MR	
3	terrace E. Width of Corridor G. Door size	NA			
3	E. Width of Corridor G. Door size Compartmentation	NA			
3	terrace E. Width of Corridor G. Door size Compartmentation Fire check door	NA 1 m	1 m	MR	
3	E. Width of Corridor G. Door size Compartmentation Fire check door Sealing of electrical shafts	NA 1 m	1 m	MR NA	
3	E. Width of Corridor G. Door size Compartmentation Fire check door Sealing of electrical shafts Fire rating of shaft door	NA 1 m NA NA NA	1 m NA NA	NA NA	
3	E. Width of Corridor G. Door size Compartmentation Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain	NA 1 m NA NA NA NA NA	1 m NA NA NA	NA NA NA	
	terrace E. Width of Corridor G. Door size Compartmentation Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain Fire Dampers	NA 1 m NA NA NA	NA NA NA NA	NA NA NA NA	
3	E. Width of Corridor G. Door size Compartmentation Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain	NA 1 m NA NA NA NA NA	NA NA NA NA	NA NA NA NA	

5.	Fire Extinguisher			MR			
	Total numbers	16 no.	16 no.				
	types	CO ₂ & ABC	CO ₂ & ABC	MR			
	IS marking	Required	Provided	MR			
	First-aid-Hose Reels.						
6	Total numbers of each floor	Olno.	01 no.	MR			
	Length of hose reel hose	30 m	30 m	MR			
	Nozzle diameter	5 mm	5 mm	MR			
	Automatic fire detection and alarming sy	ystem.					
7	Type of detectors	CO detectors (required as per GN dated 27.05.2019)	Not Provided	Last date of compliance extended till 31.03.2021 vide order dated 17.12.2020			
	Location of main panel	NA	NA	NA			
	Location of repeater panel	NA	NA	NA			
	Alternate source of power	NA	NA	NA NA			
	Hooters	NA	NA Provided (Fire	MR			
3	MOEFA	Required	Bell)				
)	Public address System.	Required	Provided	MR			
10	Automatic Sprinkler System.			7.60			
	Basement	NA	Provided	MR			
	Upper Floor	NA	NA	NA			
	Sprinkler above false ceiling	NA	NA	NA			
11	Internal Hydrants						
11	size of riser/down-comer	NA	Provided	NA			
	Number of hydrants per floor	NA	01 no. at ground floor only	NA			
	Hose Box	NA	01 no.	NA			
12	Yard Hydrants.						
12	Total number of hydrants	NA	NA	NA			
		NA	NA	NA			
	Hose Box	1111					
13	Pumping Arrangements.						
	Ground Level Dinternal Pump	NA	NA	NA			
	> Discharge of main Pump	NA NA	NA	NA			
	➤ Head of Main Pump		NA	NA			
	> Number of main pumps	NA	NA NA	NA			
	> Jockey pump out put	NA	NA NA	NA			
	> Jockey pump head	NA NA	NA NA	NA			
	> Standby pump out put	NA NA	NA	NA			
	> Standby pump Head	NA NA	NA	NA			
	Auto Starting /Manual stoppingPump House Access	NA	NA	NA			
	Terrace Level						
	➤ Discharge of pump	450 LPM	450 LPM	MR			
	Head of the Pump	40 m	40 m	MR			
	> Power supply	Required	Provided	MR			
	1 Owel Supply	4	Provided	MR			



14	Captive Water Storage for Fire Fighting.					
	Underground tank capacity	NA	NA	NA		
	Draw-off connection	NA	NA	NA		
	Fire service inlet	NA	NA	NA		
	Access to tank	Required	Provided	MR		
	Overhead Tank capacity	5000 ltrs	5,000 ltrs	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	NA	NA	NA		
	Pressurization of Lift lobby	NA	NA	NA		
	Communication in lift car	NA	NA	NA		
	Firemen's grounding switch	NA	NA	NA		
	Lift Signage	NA	NA	NA		
17	Standby power supply	Required	DG Provided	MR		
18	Refuge Area.					
\	Total area	N.A	N.A	N.A		
	Location	N.A	N.A	N.A		
19	Fire Control Room					
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Detector system panel	NA	NA	NA		
	Flow switch panel	NA	NA	NA		
	PA system panel	NA	NA	NA		
	Batter backup	NA	NA	NA		
	Building Floor Plans	NA	NA	NA		
20	Special Fire Protection systems for prot	ection of special	NA	NA		
	Risks, if any:	2				

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

The shortcomings issued by this department vide letter no. F6/DFS/MS/ GH/NDZ/2021/208 dated 01.03.2021 has been rectified by the management.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/GH/NDZ/2018/1042 dated 14.05.2018 only is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name

Rajesh Kumar Shukla

Designation ADO (SPM)

DO (CD)

Dycho (MDZ)

0210ml

ADORSPM) IT is put up for signatures pla