C-65

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2021/157

Dated: 25/03/2021

## FIRE SAFETY CERTIFICATE

Certified that the **Diplomat Inn Guest House** located at **8227**, **Gali No. 6 Arakashan Road**, **Pahar Ganj**, **New Delhi** comprised of Ground + 04 Upper floors, Ground floor (01 guest rooms + reception), 1<sup>st</sup> floor to 4<sup>th</sup> floor (03 guest rooms at each floor) and terrace floor (sealed by MCD), total 13 guest rooms was granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/357 dated 06/03/2018. The premises was re-inspected by the officer concerned of this department on **19/03/21** in the presence of Sh. Kirpal Singh and found that the said guest house building having **fourth floor not in use as per affidavit submitted by owner dated 08.09.2020**, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class **Residential**, **Sub Division-A-1 Ground floor (01 guest rooms + reception)**, 1<sup>st</sup> floor to 3rd floor (03 guest rooms at each floor) Total 10 guest rooms only, with effect from (15 at 2022) for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 25/03/2021 at New Delhi by.

(**Dr. S.K.Tomar**) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online Id no. 2021022110628 dated 23.02.2021
- 2. The Manager,
  Diplomat Inn Guest House at 8227, Gali No. 6 Arakashan Road, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other condition mentioned in the gazette notification dated 27.05.2019 & clarification issued dated on 25.09.2019 & 17.12.2020 latest by 31.03.2021

2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.

3. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

4. The trained firefighting staff should be available round the clock.

5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.

9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

10. The owner shall not use any floor above third floor and same shall be locked/closed.

ľ	N	C	D	E	C	TI	0	IN	D	D	D	0	RT	7
1	11	0	1	L		IJ		IN	1/	L		U	$\Gamma \Gamma$	

1. Name & address of the building Diplomat Inn Guest House at 8227, Gali No. 6

Arakashan Road, Pahar Ganj, New Delhi

2. Type of occupancy:- Residential, Sub Division-A-1

Gr. + 04 Upper floors (total 10 Guest rooms)
Ground floor (01 guest rooms + reception), 1<sup>st</sup> floor to 4<sup>th</sup> floor (03 guest rooms at each floor) and terrace floor (sealed by MCD).4th floor
not in use as per affidavit, dated 08 09 20

not in use as per affidavit dated 08.09.20

3. Type of case:- Renewal

4. Details of previous FSC:- No. F6/DFS/MS/GH/2018/357 dated 06/03/2018

5. Fire safety directives No.- N/A6. Date of inspection:- 19/03/21

7. Name of the inspecting officer:- Sh. Ravinder Singh(ADO/CC)

8. Name & designation of officer

From the building side:- Kirpal singh

9. Year of construction:- 2001

10. Applicant's letter No:- Online Id no. 2021022110628 dated 23.02.2021

•	>			Old Case			
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR			
1.	Access to Building						
	1) Road width	Required	06 mtr.	MR			
	2) Gate width	N/A	N/A	N/A			
	3)Width of internal road	N/A	N/A	N/A			
2.	Number, Width Type & Arı	rangement of E	Exits				
	A. Number of staircases						
	1. Upper floors	01 Nos.	01 Nos.	MR			
	2. Basements	N/A	N/A	N/A			
	B. Width of staircase						
	1. Upper floors	0.80 mtr.	1.12 to 1.29 mtr.	MR			
	2. Basements	N/A	N/A	N/A			
	C. Protection of exits						
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous	01	01	MR			
	staircase to terrace		e s				
	E. Width of corridor	01 mtr.	01 mtr.	MR			
	F. Door size	01 mtr.	01 mtr.	MR			
<b>.</b>	Compartmentation						
	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
	Smoke Management System						
	1) Basements	30 ACPH	N/A	N/A			
	2) Upper floors	12 a/c per	Natural	MR			
		hour					
5.	Fire Extinguishers						
	1) Total numbers	10 Nos.	12 Nos.	MR			



	2) Types	ABC & CO2	ABC & CO2	MR	
	3) ISI marking	Required	Provided	MR	
6.	First-Aid Hose Reel				
0.	1) Total number of eachfloor	N/A	01	N/A	
	2) Length of hose reel hose	N/A	30 mtr.	N/A	
	3) Nozzle diameter	N/A	05 mm	N/A	
7.	Automatic Fire Detection & A	<b>Alarming Syst</b>	em	- 1. C	
	1) Type of detectors	Required as per G.N dated 27.05.19	Not provided	Last dt. of compliance extended vide order dt. 17.12.2020	
	2) Location of main panel	N/A	N/A	N/A	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	N/A	N/A	N/A	
	5) Hooter's Location	N/A	N/A	N/A	
8.	MOEFA	N/A	Provided	N/A	
9.	Public Address System	N/A	Provided	N/A	
10.	Automatic Sprinkler System				
10.	1) Basement	N/A	N/A	N/A	
	2) Upper floors	N/A	N/A	N/A	
	3) Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants		27/4	N/A	
	1) Size of riser/down-comer	N/A	N/A	N/A N/A	
	2) Number of hydrants per	N/A	N/A	N/A	
	floor		37/4	N/A	
	3) Hose box	N/A	N/A	IV/A	
12.	Yard Hydrants		137/4	I NI/A	
	1) Total number of hydrants	N/A	N/A	N/A N/A	
	2) Hose box	N/A	N/A	IV/A	
13.	Pumping Arrangement		27/4	NI/A	
	1) Ground level	N/A	N/A	N/A N/A	
	a) Discharge of main pump	N/A	N/A		
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pum		N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output	t N/A	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual	N/A	N/A	N/A	
	stopping				
	2) Terrace level	DI/A	180 LPM	N/A	
	a) Discharge of pump	N/A	40 mtr.	N/A	
	b) Head of pump	N/A		N/A	
	c) Power supply	N/A	Provided	N/A	
	d) Auto starting of pump		Provided	IVA	
14.	Captive Water Storage for	Fire Fighting	15111	D.T./A	
	1) Under ground tank	N/A	N/A	N/A	

	capacity			
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	N/A	2500 ltr.	N/A
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syst Risk, if any:	em for Protec	tion of special	N/A

The fire protection systems provided in the building were randomly tested, checked a found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/357 dated 06/03/2018 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended upto third floor only.

Signature of the Inspecting Officer

Name: Rayinder Singh

Designation: ADO (CC)

and Sypon morph.