

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2021/SZ/67

Dated:\2 /03/2021

FIRE SAFETY CERTIFICATE

No R-7B, Ground Floor, Green Park, Extn., Opposite Uphar Cinema, New Delhi 110016, Situated in a building comprised of Basement, Ground Plus Three Upper Floor have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 08/03/2021 in the presence of Mr. Sammer S Bhatia and that the premise is fit for occupancy class Group—D Assembly (Restaurant at ground floor) with effect from \(\frac{1}{2} \) \(\frac{1}{2} \) \(\frac{1}{2} \) 2021 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 12/03/2021 at New Delhi by

(Atul Garg) Director

Copy to: -

- 1. The Joint Comm. of Police (Lic.), First floor, P.S. Defence Colony, New Delhi-110049 (Ref. Online Id 2020110408273 dated 12.11.2020)
- 2. The DHO, (South Zone), SDMC, Public Health Department, Aurobindo Marg, Green Park, New Delhi–110016.
- 3. M/s Garage Inc. American Diner (A Unit of Rover Hospitality) in Property No R-7B, Ground Floor, Green Park, Extn., Opposite Uphar Cinema, New Delhi 110016 Conditions for the validity of Fire Safety Certificate: -
- 1. This NOC is valid only for Ground floor.
- 2. All the means of escape/entry/exit shall be kept free from any obstruction.
- 3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of fire-fighting system.
- 5. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

		ON REPORT			
1	Name & Address of the Building	M/s Garage Inc. American Diner (A Unit of Rover Hospitality) in Property No R-7B, Groun Floor, Green Park, Extn., Opposite Uphar			
2	Type of Occupancy	Cinema, New Delhi 110016 Assembly 'Group-D'			
		Basement + Ground + Three upper Floor			
3	Building comprised of	(Restaurant at C)1	
4	Type of Case	New			
5.	Details of Previous NOC	Nil			
6	Fire Safety Directives Letter No	UBBL/NBC- 2016			
7	Date of Inspection	08.03.2021			
8	Name of the Inspecting Officers	Dy. CFO (SZ) &	ADO (BCP)		
9	Name & Designation of Officers from the building side	Sh. Sammer S Bhatia			
10	Year of construction/ date of conversion	2020			
11	Applicant letter No.	Online Id 2020110408273 dated 12.11.2020			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	NBC / UBBL- 2016	Provided at Site	Remark	
1	Access to Building.				
	Road width	06m	Provided	MR	
	Gate width	NA	NA	-NA-	
	Width of internal road	NA	NA	-NA-	
2	Number, width, type & arrangement of e	xits			
	a. Number of Staircase				
	Upper floors	NA	NA	-NA-	
	Basement floor	NA	NA	-NA-	
	b. Width of Staircase			1	
	Upper floors	NA	NA	-NA-	
	Basement floor	NA	NA	-NA-	
	c. Protection of exits			1	
	Fire check door	NA	NA	NA	
	Pressurization	-NA-	NA	-NA-	
	d. No. of continuous staircase to terrace	- 01	01	MR	
	e. Width of corridor	N/A	N/A	N/A	
	f. Door size	2m/1.5m	Provided	MR	
3	Compartmentation.				
	Fire check door.	N/A	N/A	N/A	
	Sealing of electrical shafts.	N/A	N/A	N/A	
	Fire rating of shaft door.	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	Fire dampers.	N/A	N/A	N/A	
4	Smoke Management system.		J.		
	Basement	30 ACPH	N/A	N/A	
	Upper floors	12 ACPH	N/A	N/A	
5	Fire Extinguishers.			4	
~	Total numbers	04 Nos	06Provided	MR	
7	- Total Hallious		1	7	
	Types	ABC / CO2	ABC & Co2	MR	

·	Underground tank capacity.	-NA-	-NA-	-NA-
14	Captive water storage for Fire Fighting.			
	Auto starting of pump.	Required	Provided	MR
	Power supply.	Required	Provided	MR
	Head of pump.	40m	Provided	MR
	Discharge of pump.	450 LPM	Provided	MR
	Terrace Level			
	Pump House Access	-NA-	-NA-	-NA
	Auto Starting / Manual Stopping.	-NA-	-NA-	-NA
	> Standby Pump head.	-NA-	-NA-	-NA
	Standby Pump output.	-NA-	-NA-	-NA
	Jockey Pump head.	-NA-	-NA-	-NA
	Jockey Pump output.	-NA-	-NA-	-NA
	Head of main pump.Number of main pumps.	-NA-	-NA-	-NA
	Discharge of main pump.	-NA-	-NA-	-NA
		DIA	NTA.	
	Ground Level		2	
13	Pumping arrangements.			2771
	Hose box.	-NA-	-NA-	-NA
	Total number of hydrants.	-NA-	-NA-	-NA
12	Yard Hydrants.			
	Hose box.	Required	Provided	MR
	 Number of Hydrant per floor 	Required	Provided	MR
	Size of Riser/Down-comer	Required	Provided	MR
11	Internal Hydrants.	17/12	1 4/ Z X	14/73
	 Sprinkler above false ceiling 	N/A	N/A	N/A
	Upper floors	N/A	N/A	N/A
	Basement	N/A	N/A	N/A
10	Automatic Sprinkler System		-	
9	Public Address System	-NA-	NA	-NA
	MOEFA	Required	Provided	MR
8	MOFFA	-NA-	NA	-NA
	Hoofer's location	-NA-	NA	-NA
	Alternate source of power	-NA-	NA	-NA
	Location of Repeater Panel	-NA-	NA	-NA
	Location of Main Panel	-NA-	NA.	-NA
	Type of detectors			
7	Automatic fire detection & alarming system.	, Jillii	riovided	IVIK
				MR
	 Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter 	One 30m 5mm	Provided Provided Provided	M M M

16	Provision of Lifts.			44
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	Fireman's switch	-NA-	-NA-	-NA-
20	Lift signage.	-NA-	-NA-	-NA-
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	Total area	-NA-	-NA-	-NA-
	• Location	-NA-	-NA-	-NA-
19	Fire Control Room.			
	Detector System Panel.	-NA-	-NA-	-NA-
-/	Flow Switch Panel.	-NA-	-NA-	-NA-
7	PA system Panel.	-NA-	-NA-	-NA-
1	Battery backup	-NA-	-NA-	-NA-
	Building floor plan	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any:	-NA-	-NA-	-NA-

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate to the said restaurant under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of Inspection Officer Name: Sh. Sunil Chawdhary

Designation: - Dy. CFO (SZ)

Signature of the Inspecting Officer

Name: - Rajesh Kumar Designation: - ADO/BCP

+ solso Not avoilable

193

f I Pls