C-93

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2021/ 133

Dated: 11 | 3 | 2 |

FIRE SAFETY CERTIFICATE

Certified that M/s. Hotel C Park located at 6/13, WEA, Karol Bagh, New Delhi- 110005 comprised of basement, ground plus three upper floors, using basement as hall/storage, ground floor as reception & office, first, second and third floor each having 08 guest rooms respectively (total 24 guest rooms) and a kitchen with two staff rooms on terrace was granted FSC by this department vide letter No. F.6/DFS/MS/GH/SZ/2018/517 dated 27.03.2018. The premises was re-inspected by the officer concerned of this department on 04.03.2021 in presence of Sh. Rakesh Chadha, (Owner), and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for basement (storage), ground floor (reception & office), first, second & third floor each having 08 guest rooms (total 24 guest rooms only) with effect from 11 3 2 2 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued on 11 3 21 at New Delhi by.

(Sunil Chaudhary)

Dy. Chief Fire Officer (SZ)

Of Delhi Fire Service

Copy to:-

- 1. Sh. Rakesh Chadha (Owner), M/s. Hotel C Park, 6/13, WEA, Karol Bagh, New Delhi-110005.
- 2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi

Following Fire Safety Directives must be adhered to: -

- 1. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 10. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

INSPECTION REPORT

1. Name & address of the building

: M/s. Hotel C Park, 6/13, WEA, Karol Bagh, New

Delhi- 110005.

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: F.6/DFS/MS/GH/SZ/2018/517 dated 27.03.2018

5. Fire Safety directives letter No

: Nil

6. Date of inspection

: 04.03.2021

7. Name of the Inspecting Officers

: P.V. Rathee, Asstt. Div. Officer (SRD)

8. Name and designation of officers

from the building side

: Sh. Rakesh Chadha, Owner

9. Year of Construction

: 2005

10. Applicant's letter No.

: Online Application Id 2021021910602 dated 23.02.2021

The said guest house is comprised of basement, ground plus four upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Fire safety arrangements as per FSC dt. 27.03.2018 Provided site		d at Remarks MR/NMR			
1	Access to building						
	 Road width 	06 mts	- Directly accessible		MR		
	Gate width				ible MR		
	 Width of internal road 	N/A			N/A		
2	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases	-	01			-	
	 Upper Floors 	01			MR		
	Basements	01		01	MR	being old case	
	b. Width of staircases			1.30 mts		- 1	
	 Upper Floors 	Old Case	1.3			MR	
	• Basements	Old Case	1.2	5 mts		MR	
	c. Protection of exits			-		1/4_	
	• Fire check door	Required	NOI Provided		date of compliance has bee extended up to 31.03.202		
	Pressurization	N/A			N/A		
	e. No. of continuous staircases to terrace	01			MR		
	g. Width of Corridor	1.0 mt.			MR		
	h. Door Size	Old case			MR being old case		
3	Compartmentation.				4		
	Fire check doorSealing of electrical shafts	Required	Not P	rovided	date of compliance has been extended up to 31.03.2021		
	• Fire Rating of shaft door	N/A	Sealed N/A N/A		N/A N/A		
	Water Curtain	N/A					
	• Fire Dampers	N/A					
		N/A	N	J/A		N/A	
1	Smoke Management System.						
	Basements	30 a/c per hour	Exhaust fan prov		vided	MR	
	Upper floors	12 a/c per hour	Nat	Natural Ventilation		MR	
5	Fire Extinguishers						
	Total numbers	16	Provided Provided Provided			MR	
	• Types	CO ₂ , ABC, WCO ₂				MR	
	IS marking	ISI marked			MR		

6	First-Aid Hose Reels.							
	Total numbers on each floor	01	Provided		MR 🦠			
	 Length of hose reel hose 	30 m	Provided		MR			
	Nozzle diameter	5 mm	Provided		MR			
7	Automatic fire detection and alarming	Automatic fire detection and alarming system.						
	Type of detectors	Carbon Monoxide	Not Provided		mpliance has been up to 31.03.2021			
	Location of Main Panel Location of Repeater Panel	Required	NOI Provided		ed up to 31.03.2021			
	Location of Repeater PanelAlternate source of power	N/A	N/A		N/A			
-	Hooters' Location	N/A	N/A		N/A			
		N/A	N/A		N/A			
8	MOEFA	Required	Provided		MR			
9	Public Address System.	Required	Provided		MR			
10	Automatic Sprinkler System.	Automatic Sprinkler System.						
	Basement	Required	Provided	d	MR			
	Upper Floor	N/A	N/A		N/A			
	Sprinkler above false ceiling	N/A	N/A		N/A			
11	Internal Hydrants							
	Size of riser/down-comer	N/A	N/A		N/A			
	 Number of hydrants per floor 	N/A	N/A		N/A			
	Hose Box	N/A	N/A		N/A			
12	Yard Hydrants.							
	Total number of hydrants	N/A			N/A			
	Hose Box	N/A	N/A		N/A			
13	Pumping Arrangements.							
	Ground Level	!						
	Discharge of main Pump	N/A			N/A			
	Head of Main pump	N/A	N/A		N/A			
	Number of main pumpsJockey Pump out put	N/A	N/A		N/A			
	> Jockey pump head	N/A N/A	N/A		N/A			
	> Standby Pump out put	N/A N/A	N/A		N/A			
	Standby Pump Head	N/A	N/A N/A	1	N/A N/A			
	Auto Starting/ Manual stopping		N/A N/A		N/A			
	Pump House Access	N/A			N/A			
	Terrace level				IN/A			
	 Discharge of pump 	450 LPM	450 LPM		MR			
	Head of the pump	30 mts	30 mts each		MR			
	> Power Supply	Required			MR			
	Auto Starting of pump	Required	Provided		MR			
14	Captive Water Storage for fire fighting	o.						
	Underground tank capacity	N/A	N/A		NI/A			
	> Draw-off connection	N/A	N/A N/A		N/A N/A			
	Fire service inlet	N/A	Provided		N/A			
	> Access to tank	N/A	N/A		N/A			
	Overhead Tank capacity	Old case	Provided (6,000 lts	s)	MR			
15	E-4 C							

			NISC			
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
Ī	Communication In lift Car	Required	Provided	MR		
	Fireman's Grounding Switch	Required	Provided	MR		
	Lift Signage	Required	Provided	MR		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for	on Systems for N/A N/A		N/A		
	Protection of special Risks, if any:	<u></u>				

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The management has given an undertaking not to use any occupancy above third floor & basement as storage purpose.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/SZ/2018/517 dated 27.03.2018 , renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer Name P.V. Rathee

Asstt. Div. Officer (SRD)

os los mor

♦ Dy cfo (52)

F. t. please