GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2021/ \5 2

Dated: 23 03 2021

FIRE SAFETY CERTIFICATE

Certified that Hotel Kama Palace located at 9A/34, Channa Market, WEA, Karol Bagh, New Delhi- 110005 comprised of basement (storage), ground floor (reception, office & 04 guest rooms), first floor (06 guest room) and second floor (06 guest rooms) (total 16 guest rooms) and terrace floor (01 staff room & staff pantry) was granted FSC by this department vide letter No. F6/DFS/MS/GH/SZ/2017/998 dated 11.07.2017. The premises was re-inspected by the officer concerned of this department on 17.03.2021 in presence of Mr. Bharti Sharma, Caretaker of the guest house and found that deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for Basement (storage), ground floor (Reception, office & 4 guest rooms) first & second floor each having 06 guest rooms (total 16 guest rooms only) with effect from 23 03 202 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued on 23 03 20 at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)

OC Delhi Fire Service

Copy to:-

- 1. The Owner, Hotel Kama Palace, 9A/34, Channa Market, WEA, Karol Bagh, New Delhi- 05.
- 2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi

Following Fire Safety Directives must be adhered to: -

- The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

Depo (SZ) Solonki

1. Name & address of the building : M/s. Hotel Kama Palace, 9A/34, Channa Market, WEA, Karol Bagh, New Delhi- 110005.

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/GH/SZ/2017/998 dated 11.07.2017

5. Fire Safety directives letter No : Nil

6. Date of inspection : 17.03.2021

7. Name of the Inspecting Officers : P.V. Rathee, Asstt. Div. Officer (SRD)

8. Name and designation of officers

from the building side : Bharti Sharma (Caretaker)

9. Year of Construction : 1996-97

10. Applicant's letter No. : Online Application id 2021030110845 dated 02.03.2021

The said guest house is comprised of basement, ground plus two upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Existing fire safety requirements as po FSC dated 11.07.20	er site	at Remarks MR/NMR					
1									
	Road width	06 mts	Provided	MR					
	Gate width	4.5 mts	Directly accessib	le MR					
	Width of internal road	N/A	N/A	N/A					
2	Number, Width, Type & Arrangement of Exits								
	a. Number of staircases	_	- 1/2 - 1 T	-					
	• Upper Floors	01	01	MR being old case					
	Basements	01	01	MR being old case					
	b. Width of staircases	-	_	- 1					
	Upper Floors	1.25 mts	1.25 mts	MR being old case					
	Basements	1.25 mts	1.30 mts	MR being old case					
	c. Protection of exits	-	- >						
	Fire check door	Required	Not Provided	date of compliance has been extended up to 31.03.2021					
	Pressurization	N/A	N/A	N/A					
	e. No. of continuous staircases to terrace	01	01	MR					
	g. Width of Corridor	Old case	1.6 mts	MR					
	h. Door Size	Old case	0.80 mts	MR being old case					
3	Compartmentation.								
	Fire check door	Required	Not Provided	date of compliance has been extended up to 31.03.2021					
	Sealing of electrical shafts	N/A	N/A	N/A					
	Fire Rating of shaft door	N/A	N/A	N/A					
	Water Curtain	N/A	N/A	N/A					
	Fire Dampers	N/A	N/A	N/A					
4	Smoke Management System.								
	Basements	12 a/c per hour	Exhaust fan provi						
	Upper floors	12 a/c per hour	Natural Ventilat	ion MR					
5	Fire Extinguishers								
	Total numbers	20	Provided	MR					
	• Types	CO ₂ , ABC, WCO ₂	Provided	MR					
		ICI marked	- 111	MD					

10	First-Aid Hose Keels.							
	Total numbers on each floor	01	Provided			MR		
	 Length of hose reel hose 	30 m	Provided			MR 3		
	Nozzle diameter	5 mm	Provided			MR		
7	Automatic fire detection and alarming system.							
	• Type of detectors .	Carbon Monoxide	Not Provided	date of compliance has been extended up to 31.03.2021		31.03.2021		
	Location of Main Panel	Required	Not Provided	date of compliance has be extended up to 31.03.202				
	Location of Repeater Panel	N/A	N/A	N/A		A		
	Alternate source of power	N/A	N/A	N/A		A		
	Hooters' Location	N/A	N/A	N/A		A		
8	MOEFA	Required	Provided	MR		R		
9	Public Address System.	Required	Provided	MR		R		
10	Automatic Sprinkler System.							
	Basement	Required	Provided			MR		
	Upper Floor	N/A	N/A			N/A		
	Sprinkler above false ceiling	N/A	N/A	/A		N/A		
11	Internal Hydrants							
	Size of riser/down-comer	N/A	N/A	N		N/A		
	 Number of hydrants per floor 	N/A	N/A			N/A		
	Hose Box	N/A	N/A			N/A		
12	Yard Hydrants.							
	Total number of hydrants	N/A	N/A			N/A		
	Hose Box	N/A	. N/A			N/A		
13	Pumping Arrangements.							
	Ground Level		*					
	Discharge of main Pump	N/A	N/A			N/A		
	Head of Main pump	N/A	N/A			N/A		
	Number of main pumps	N/A	N/A			N/A		
	> Jockey Pump out put	N/A	N/A	N/A				
	> Jockey pump head	N/A	N/A	N/A				
	Standby Pump out put	N/A	N/A			N/A		
	> Standby Pump Head	N/A	N/A			N/A		
	Auto Starting/ Manual	N/A	N/A	N/A		N/A		
	stopping Pump House Access	N/A	N/A			N/A		
	Terrace level				-			
	Discharge of pump	450 LPM	450 LPM		MR be	MR being old case		
	> Head of the pump	30 mts	30 mts		MR			
	Power Supply	Required	Provided			MR		
	> Auto Starting of pump	Required	Provided		MR			
14	Captive Water Storage for fire fightin							
	Underground tank capacity	N/A	N/A		N/A			
	> Draw-off connection	N/A	N/A			N/A		
	Fire service inlet	N/A	Provided					
	> Access to tank	N/A	N/A		N/A			
	Overhead Tank capacity	5 000 1+0	E 000 1					

			N(3)						
16	Provision of Lifts.								
	•	Pressurization of Lift Shaft	N/A	N/A	N/A				
10	•	Pressurization of Lift lobby	N/A	N/A	N/A				
-		Communication In lift Car	N/A	N/A	N/A				
		Fireman's Grounding Switch	N/A	N/A	N/A				
	•	Lift Signage	N/A	N/A	N/A				
17	Stand	by power supply	Required	Provided	MR				
18	Refug	efuge Area.							
	. >	Total Area	N/A	N/A	N/A				
	>	Location	N/A	N/A	N/A				
19	Fire (Control Room							
		Detector System Panel	N/A	N/A	N/A				
		Flow Switch Panel	N/A	N/A	N/A				
		PA System Panel	N/A	N/A	N/A				
		Battery backup	Required	Provided	MR				
		Building Floor Plans	N/A	N/A	N/A				
20		al Fire Protection Systems for ction of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. panel	MR				

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The management has given an undertaking not to use any occupancy above third floor & basement as storage purpose.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No F6/DFS/MS/GH/SZ/2017/998 dated 11.07.2017, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer
Name P.V. Rathee

Asstt. Div. Officer (SRD)

19/03/2021

Dy c60 (52)

<u>M</u>