GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2021/155

Dated: 25/03/2021

FIRE SAFETY CERTIFICATE

Certified that M/s. Hotel Royal Holiday located at 17A/35, WEA, Karol Bagh, New Delhi- 110005 comprised of basement, ground plus three upper floors, using basement (storage), ground floor (reception, hall & 03 guest rooms), first floor & second floor each having 05 guest rooms respectively (total 13 guest rooms) and three staff rooms with pantry on third floor, was granted FSC by this department vide letter No. F.6/DFS/MS/GH/SZ/2018/629 dated 06.04.2018. The premises was re-inspected by the officer concerned of this department on 19/03/2021 in presence of Sh. Gurdeep Singh (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) Basement (storage), ground floor (reception, hall & 03 guest rooms) first & second floor each having 05 guest rooms, third floor (03 rooms for personal use) (total 13 guest rooms only) with effect from 25/03/202 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued on 25/03/2021 at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to:-

- 1. Sh. Kulwant Singh (Owner) M/s. Hotel Royal Holiday, 17A/35, WEA, Karol Bagh, New Delhi-110005.
- 2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

Following Fire Safety Directives must be adhered to: -

- The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 10. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

1. Name & address of the building : M/s. Hotel Holiday, 17A/35, WEA, Karol Bagh, New Delhi- 110005

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : F.6/DFS/MS/GH/SZ/2018/629 dated 06.04.2018

5. Fire Safety directives letter No : Nil

6. Date of inspection : 19.03.2021

7. Name of the Inspecting Officers : P.V. Rathee, Asstt. Div. Officer (SRD)

8. Name and designation of officers

from the building side : Sh. Gurdeep Singh (Manager)

9. Year of Construction : 2005-2006

10. Applicant's letter No. : Online Application id 2021031911427 dated 19.03.2021

The said guest house is comprised of basement, ground plus three upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Fire safety arrangements as p FSC dt. 06.04.201	SILC	Remarks MR/NMR			
1	Access to building						
	Road width	06 mts	Provided	MR			
	Gate width		Directly accessible	MR			
	• Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases	1=	-	-			
	• Upper Floors	01	01	MR, Old case			
	Basements	01	01	MR being old case			
	b. Width of staircases	-	-				
	 Upper Floors 	1.25 mts	1.28 mts	MR being old case			
	Basements	1.25 mts	1.25 mts	MR being old cas			
	c. Protection of exits	-		-			
	• Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
	e. No. of continuous staircases to	01	01	MR			
	terrace	1.25 mt.	1.60 mts.	MR			
	g. Width of Corridor h. Door Size	Old case	0.87 mts	MR being old case			
3	Compartmentation.			_			
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	• Fire Dampers	N/A	N/A	N/A			
4	Smoke Management System.						
	Basements	12 a/c per hour	Exhaust fan provided	MR			
	• Upper floors	12 a/c per hour	Natural Ventilation	MR			
5	Fire Extinguishers						
	Total numbers	14	Provided	MR			
	Types	CO ₂ , ABC, WCO ₂	Provided	MR			
	• IS marking	ISI marked	Provided	MR			

P		Length of hose reel hose	30 m	Provided		N.O.	
		Nozzle diameter	5 mm	Provided		MR	
	7	Automatic fire detection and alarming	tomatic fire detection and alarming system.				
		Type of detectors	Carbon Monoxide	Not Provided	extend	compliance has been ded up to 31.03.2021	
-		Location of Main Panel	Required	Not Provided		ate of compliance has been extended up to 31.03.2021	
		Location of Repeater Panel	N/A	N/A		N/A	
		Alternate source of power	N/A	N/A		N/A	
		Hooters' Location	N/A	N/A	N/A		
	8	MOEFA	Required	Provided	MR		
	9	Public Address System.	Required	Provided	MR		
	10	Automatic Sprinkler System.					
		Basement	Required	Provided		MR	
		Upper Floor	N/A	N/A		N/A	
		Sprinkler above false ceiling	N/A	N/A		N/A	
	11	Internal Hydrants					
		Size of riser/down-comer	N/A	N/A		N/A	
		Number of hydrants per floor	N/A	N/A		N/A	
		Hose Box	N/A	N/A		N/A	
	12	Yard Hydrants.					
		Total number of hydrants	N/A	N/A		N/A	
-	Hose Box		N/A	N/A		N/A	
-	13	Pumping Arrangements.	- 7				
		Ground Level					
		Discharge of main Pump	N/A	N/A		N/A	
		Head of Main pump Number of main pumps	N/A	N/A		N/A	
		Number of main pumpsJockey Pump out put	N/A	N/A		N/A	
		Jockey pump head	N/A	N/A		N/A	
		Standby Pump out put	N/A	N/A		N/A	
		Standby Pump Head	N/A	N/A		N/A	
		Auto Starting/ Manual stopping	N/A	N/A		N/A	
		Pump House Access	N/A	N/A		N/A	
	-	Terrace level	N/A	N/A		N/A	
		Discharge of pump					
		Head of the pump	450 LPM	450 LPM		MR	
		Power Supply	30 mts	Provided		MR	
		> Auto Starting of pump	Required	Provided		MR	
			Required	Provided		MR	
	14	Captive Water Storage for fire fighting.					
	-	Underground tank capacity	N/A	N/A		N/A	
		> Draw-off connection	N/A	N/A	177	N/A	
		> Fire service inlet	N/A	N/A		N/A	
		Access to tank	N/A	N/A		N/A	
-	15	Overhead Tank capacity Old Case Good II					

	2.
N	22

16	Provisio	rovision of Lifts.					
	• I	Pressurization of Lift Shaft	N/A	N/A	N/A		
	• I	Pressurization of Lift lobby	N/A	N/A	N/A		
	• (Communication In lift Car	N/A	N/A	N/A		
	• I	Fireman's Grounding Switch	N/A	N/A	N/A		
	• I	Lift Signage	N/A	N/A	N/A		
17	Standby	power supply	Required Provided		MR		
18 Refuge Area.					`		
	> 7	Total Area	N/A	N/A	N/A		
	I	Location	N/A	N/A	N/A		
19	Fire Control Room						
	•	Detector System Panel	N/A	N/A	N/A		
	•	Flow Switch Panel	N/A	N/A	N/A		
	•	PA System Panel	N/A	N/A	N/A		
	•	Battery backup	N/A	N/A	N/A		
	•	Building Floor Plans	N/A	N/A	N/A		
20		Fire Protection Systems for on of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The management has given an undertaking not to use any occupancy above third floor & basement as storage purpose.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/SZ/2018/629 dated 06.04.2018, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer
Name P.V. Rathee

Asstt. Div. Officer (SRD)

Rolf 32 13 31

D. 0. (5W)

Dy cho (gr)

J

coll