## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2021/156

## Dated: 25/03/2021

## FIRE SAFETY CERTIFICATE

Certified that M/s. Hotel Sun Star Heritage located at 8A/43, WEA, Karol Bagh, New Delhi- 110005, comprised of basement, ground plus three upper floors, using basement as hall & 02 rooms for storage, ground floor as reception & 03 guest rooms, first, second & third floor each having 05 guest rooms respectively (total 18 guest rooms) and one staff room with pantry at terrace floor, was granted FSC by this department vide letter No. F6/DFS/MS/GH/SZ/2018/702 dated 13.04.2018. The premise was re-inspected by the officer concerned of this department on 17.03.2021 in presence of Sh. Anchit, manager of the guest house. The said gust house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for basement (storage, ground floor (reception & 03 guest rooms) first, second & third floor each having 05 guest rooms receptively (total 18 guest rooms only) with effect from 25/03/202) for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 25/03/2021 at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)

OCCUPATION OF THE Service

Copy to: -

1. The Joint C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

2. The Manager, M/s Hotel Sun Star Heritage, 8A/43, WEA, Karol Bagh, New Delhi-110005.

## Conditions for the Validity of Fire Safety Certificate

- 1. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 2. All the means of escape shall be kept free of all type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 6. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 7. All comments / directions of licensing department shall always be permitted and followed.
- 8. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 9. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 10. Basement shall be used as per BBL.
- 11. No temporary shed is allowed on terrace.
- 12. The Fire Safety Certificate is only for Guest Rooms.
- 13. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

1. Name & address of the building : M/s. Hotel Sun star Heritage, 8A/43, WEA, Karol Bagh, New Delhi- 110005.

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/GH/SZ/2018/702 dated 13.04.2018

5. Fire Safety directives letter No : Nil

6. Date of inspection : 17.03.2021

7. Name of the Inspecting Officers : P.V. Rathee, Asstt. Div. Officer (SRD)

8. Name and designation of officers

from the building side : Sh. Anchit, Manager

9. Year of Construction : Before 2001

10. Applicant's letter No. : Online Application id 2020092107192 dated 03.03.2021

The said guest house is comprised of basement, ground plus three upper floors.

S. No.	p	Minimum Standards on fire revention and fire safety U/R 33	Fire safety arrangements as per FSC dt.	Provided at site	Remarks MR/NMR		
1	Acc	ess to building	13.04.2018				
	Road width		06 mts	Provided	MR		
		Gate width		Directly accessible	MR		
		• Width of internal road	N/A	N/A	N/A		
2	Nui	nber, Width, Type & Arrangemen	t of Exits				
	-	umber of staircases	-	-	_		
		• Upper Floors	01	01	MR being old case		
		Basements	01	01	MR being old case		
	b. V	Vidth of staircases	J	•	-		
		Upper Floors	Old Case	1.22 mts	MR being old case		
		Basements	Old Case	1.15 mts	MR being old case		
	c. P	rotection of exits		-	· · · · · · · · · · · · · · · · · · ·		
		Fire check door	N/A	N/A	N/A		
		<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A		
	e.	No. of continuous staircases to	01	01	MR		
	g. V	Vidth of Corridor	1.0 mt.	1.20 mts.	MR		
	h. D	oor Size	Old case	0.75 mts	MR being old case		
3	Cor	npartmentation.	<u> </u>				
		• Fire check door	N/A	N/A	N/A		
		<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	Sealed			
		Fire Rating of shaft door	N/A	N/A	N/A		
		• Water Curtain	N/A	N/A	N/A		
		• Fire Dampers	N/A	N/A	N/A		
4	Sm	oke Management System.					
		Basements	30 a/c per hour	Exhaust fan provided	MR		
	*	• Upper floors	12 a/c per hour	Natural Ventilation	MR		
5	Fire Extinguishers						
		Total numbers	15	Provided	MR		
		• Types	CO <sub>2</sub> , ABC, WCO <sub>2</sub>	Provided	MR		
		IS marking	ISI marked	Provided	MR		

	<ul> <li>Total numbers on each floor</li> </ul>		01	Provid	Provided		
The same of the same of	<ul> <li>Length of hose reel hose</li> </ul>		30 m	Provid	Provided		
	Nozzle diameter		5 mm	Provided		MR	
7	Automatic fire detection and alarming system.						
	Type of detectors	Carb	oon Monoxide	Not Provided	date of c	ompliance has been	
	Location of Main Panel					d up to 31.03.2021	
	Location of Repeater Panel		N/A	N/A	1	N/A	
	Alternate source of power	T	N/A	N/A		N/A	
	Hooters' Location	1	Required	D.G. set 82 KVA		MR	
8	MOEFA	Т	N/A	N/A		N/A	
			Required	Provided	*	MR	
9	Public Address System.	F	Required	Provided		MR	
10	Automatic Sprinkler System.						
	Basement		N/A	Provided	Area less	than 200 sq. mts.	
	Upper Floor		N/A	N/A		N/A	
	Sprinkler above false ceiling		N/A	N/A		N/A	
11	Internal Hydrants				· · · · · · · · · · · · · · · · · · ·		
	Size of riser/down-comer		N/A	N/A	N/A		
	<ul> <li>Number of hydrants per floor</li> </ul>		N/A	N/A	N/A		
	Hose Box		N/A	N/A	Y	N/A	
12	Yard Hydrants.					Variable Control	
	Total number of hydrants		N/A	N/A		N/A	
	Hose Box		N/A	N/A		N/A	
13	Pumping Arrangements.						
	Ground Level						
	Discharge of main Pump		N/A	N/A		N/A	
	Head of Main pump		N/A	N/A	N/A		
	Number of main pumps		N/A	N/A	N/A		
	Jockey Pump out put		N/A	N/A		N/A	
	Jockey pump head		N/A	N/A		N/A	
	Standby Pump out put		N/A	N/A		N/A	
	<ul><li>Standby Pump Head</li><li>Auto Starting/ Manual stop</li></ul>		N/A	N/A		N/A	
	Pump House Access	ping	11/11		N/A		
			N/A		N/A		
	Terrace level		450 I DN			NAD	
	Discharge of pump		430 LPW	450 LP	VI	MR	
	Head of the pump		30 mts	30 mts	3	MR	
	Power Supply		Required	d Provide	d	MR	
	Auto Starting of pump		Required	d Provide	d	MR	
14	Captive Water Storage for fire fight	ting.					
	<ul> <li>Underground tank capacity</li> </ul>	3	N/A	N/A		N/A	
	Draw-off connection		N/A	N/A	4 - 41	N/A	
	Fire service inlet		N/A	Provided			
	> Access to tank		N/A	N/A		N/A	
	Overhead Tank capacity		Old case	5000 lts	MR	being old case	
15	Exit Signage.		Required	Provided		MR	
16	Provision of Lifts.						

\*

			M122.					
		Pressurization of Lift Shaft	N/A	N/A	N/A			
		Pressurization of Lift lobby	N/A	N/A	N/A			
0	•	Communication In lift Car	Required	Provided	MR			
		Fireman's Grounding Switch	Required	Provided	MR			
	•	Lift Signage	Required	Provided	MR			
17	Star	dby power supply	Required	Provided	MR			
18	Refu	Refuge Area.						
		Total Area	N/A	N/A	N/A			
		Location	N/A	N/A	N/A			
19	Fire	e Control Room						
Control of the Contro		Detector System Panel	N/A	N/A	N/A			
The second		• Flow Switch Panel	N/A	N/A	N/A			
		PA System Panel	N/A	N/A	N/A			
		Battery backup	N/A	N/A	N/A			
		Building Floor Plans	N/A	N/A	N/A			
20	Spec	cial Fire Protection Systems for	N/A	N/A	N/A			
1	Prot	ection of special Risks, if any:			14/21			

The management has given an undertaking not to use any occupancy above third floor & basement as storage purpose.

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/710-725 dated 17.12.2020 in respect of existing building (copy enclosed) shall be implemented by 31.03.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/SZ/2018/702 dated 13.04.2018, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer
Name- P.V. Rathee

Asstt. Div. Officer (SRD)

D. 0 (5 W)

n nn (5 p 2)