GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/SZ/2021/43

Dated 23 / 02/2021

FIRE SAFETY CERTIFICATE

Issued on 23 / 02 /2021 at New Delhi by

(Sunil Chawdhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to: -

1. The Joint C.P (Lic) 1st Floor, PS Defence Colony, New Delhi 110049.

2. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi- 110016.

3. M/s TACO BELL Restaurant Space-8, (T-316A), (A Unit of Barman Hospitality Pvt Ltd.) 3rd floor at Ambience Mall, Vasant Kunj, New Delhi-110070.

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

		INSPECTI	ON REPORT	29/815-16/1-15/82/07		
1	Na	me & Address of the Building	M/s TACO BELL Restaurant Space-8, (T-316A), 3 rd floor at Ambience Mall, Vasant Kunj, New Delhi-110070.			
				nan Hospitality Pvt Ltd.)		
2	Ty	pe of Occupancy		ding "Group-D" Restaura	nt	
3	Bui	Iding Comprised of	the same of the sa	ment, Ground + 03 upper		
4	Ty	e of Case	Renewal			
5	Det	ails of Previous NOC	F.6/DFS/MS/E	H/2018/SZ/291 Dated 23/	02/2018	
6	Fire	Safety Directives Letter No	Nil			
7	Dat	e of Inspection	19/02/2021			
8	Naı	ne of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)			
9	Naı	ne & Designation of Officers	Mr. Rajender S	ingh (Manager)		
	froi	from the building side				
10		r of construction	Restaurant running at 3 rd Floor in Ambiance Mall building.			
11		olicant letter No.		21011209602 dated 08/02	2/2021	
S. No.		nimum standards on Fire Prevention Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR	
1	Acc	ess to Building. FSC No.F.6/DFS/MS/M		ted 21/01/2020 of Ambienc	e Mall	
		Road width	Restaurant	As above	MR	
		Gate width	within Mall	As above	N/A	
		 Width of internal road 	entre de la constante de la co	As above	N/A	
2	Nui	nber, width, type and arrangements of	f exits.			
		Number of Staircase		Maintained by Ambian	ce Mall	
		Upper floors	02 Nos	As above	MR	
		Basement floor	N/A	As above	N/A	
	b.	Width of Staircase	Provided &	Maintained by Ambian		
		• Upper floors	Required	As above	MR	
		Basement floor	N/A	As above	NI/A	
	c.	Protection of exits	Maintained by Ambiar			
		Fire check door	Required	As above	MR	
		Pressurization	N/A	As above	N/A	
	d.	No. of continuous staircase to terrace	Required	As above	MR	
	-	Width of corridor	N/A	N/A	N/A	
	f.	Door size	Required	Open from all side	MR	
3	Con	npartmentation.		Maintained by Ambian		
		Fire check door.	Required	As above	MR	
		Sealing of electrical shafts.	N/A	As above	N/A	
		Fire rating of shaft door.	N/A	N/A	N/A	
		Water curtain	N/A	N/A	N/A	
		Fire dampers.	N/A	N/A	N/A	
4.	Smo	ke Management system.	Provided &	Maintained by Ambien		
		Basement	N/A	As above	N/A	
		Upper floors	Required	Exhaust fans provided	MR	
5.	Fire	Extinguishers.		1		
		Total numbers	05 Nos	06 Nos.	MR	
		Types	and American	ABC-04, W.CO ₂ -02	MR	
		ISI Marking	ISI marked	Provided	MR	
6.	Firs	Aid Hose Reels.	Provided &	Maintained by Ambien		
	Total numbers on each floor.			One in Restaurant	MR	
		Tour numbers on Cacil 11001.	***			
		Length of hose-reel hose	Hose Reel	3()m	MR	
		Length of hose-reel hose.	Hose Reel	30m 5mm	MR	
7	A	Length of hose-reel hose. Nozzle Diameter omatic Fire Detection and Alarming sy		5mm	MR	

	Type of detectors	Required	Smoke & Heat	MR	
	Location of Main Panel	Required	As above	MR	
	 Location of Repeater Panel 	N/A	N/A	N/A	
	Alternate source of power	Required	As above	MR	
	Hooter's location	Required	As above	MR	
8.	MOEFA	Required	As above	MR	
9.	Public Address System	Required	As above	MR	
10.	Automatic Sprinkler System	-	& Maintained by Ambie		
	Basement	Required	As above	MR	
	Upper floors	Required	Provided in Restt.	MR	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants.	Provided & Maintained by Ambience Mall			
- 44	Size of Riser/Down-comer	Required	As above	MR	
	Number of Hydrant per floor	Required	As above	MR	
	Hose box	Required	As above	MR.	
12.	Yard Hydrants.		& Maintained by Ambie		
	Total number of hydrants.	N/A	As above	N/A	
	• 2. Hose box.	N/A	As above	N/A N/A	
13.	Pumping arrangements.	11/21	AS above	IN/A	
	Ground Level	Provided & Maintained by Ambience Maii			
	Discharge of main pump.	4500 LPM	As above		
	Head of main pump.	70 mtr	As above	MR	
	Number of main pumps.	Two	As above	MR	
	Jockey Pump output.	450 LPM	As above As above	MR	
	Jockey Pump head.	70 mtr	As above As above	MR	
	Standby Pump output.	4500 LPM	As above	MR	
	Standby Pump head.	70 mtr	As above	MR	
	Auto Starting / Manual Stopping.	Required	As above	MR	
	> Access to pump house	Required	As above As above	MR	
	Terrace Level	_	1	MR	
	> Discharge of pump.	Provided & Maintained by Ambience Mall N/A N/A N/A			
	Head of pump.	N/A N/A	N/A N/A	N/A	
	> Power supply.	N/A		N/A	
	Auto starting of pump.	N/A	N/A	N/A	
14.	Captive water storage for Fire Fighting.	N/A N/A Provided & Maintained by Ambience M		NA	
17.		5,00,000 Ltr		7	
	 Underground tank capacity. Draw-off connection. 		As above	MR	
	Fire Service Inlet.	Required	As above	MR	
	Access to tank.	Required	As above	MR	
	Overhead tank capacity.	Required 20,000 Ltr	As above	MR	
15.	Exit Signage.		As above	MR	
16.	Provision of Lifts.	Required &	Provided Maintained by A. I.	MR	
200	Pressurization of lift shaft.	The bottom of the second secon	Maintained by Ambier		
		N/A	N/A	N/A	
	Pressurization of lift lobby. Communication in lift communic	N/A	N/A	N/A	
	Communication in lift car. Firemen's switch	N/A ************************************	N/A	N/A	
	• Fireman's switch.	N/A	N/A	N/A	
17	Lift signage. Startly Programmer	N/A	N/A	N/A	
	Standby Power Supply	Required	Provided (DG Set)	MR	
18.	Refuge Area				
7.37	Total area	N/A	N/A	N/A	
-21	• Location	N/A	N/A	N/A	
	E. C. I.S.				
19	Fire Control Room	Provided &	Maintained by Ambien	co Mall	
19,	Detector System Panel.	Provided & N/A	Maintained by Ambien As above	ce Mall N/A	

	Flow Switch Panel	N/A	As above	N/A
	PA system Panel.	N/A	As above	N/A
	Battery backup	N/A	As above	N/A
	Building floor plan	N/A	As above	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any:	N/A	As above	N/A

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/EH/2018/SZ/291 Dated 23/02/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Rajesh Kumar Designation: ADO / BCP